



## INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

*We Protect Hoosiers and Our Environment.*

100 N. Senate Avenue • Indianapolis, IN 46204

(800) 451-6027 • (317) 232-8603 • [www.idem.IN.gov](http://www.idem.IN.gov)

Eric J. Holcomb  
Governor

Brian C. Rockensuess  
Commissioner

March 28, 2022

Aman LLC  
Attn: Pritpal Kaur, Registered Agent  
13150 Ditch Rd  
Carmel, IN 46032

S & K Food Mart Inc  
Attn: Pritpal Kaur, Registered Agent  
7642 Ballyshannon St  
Indianapolis, IN 46217

Re: Violation Letter  
Arlington Food Mart  
6014 E Washington St  
Indianapolis, Marion County  
UST Facility ID # **2242**

Dear Ms. Kaur:

An inspector from the Indiana Department of Environmental Management (IDEM), Underground Storage Tank (UST) Section, conducted an inspection of the site referenced above on March 9, 2022.

The inspection was conducted pursuant to Indiana Code (IC) 13-14-2-2 to determine compliance with the provisions of IC 13-23 and 329 IAC 9. In accordance with IC 13-14-5, a summary of the inspection is provided below:

Type of Inspection: Initial

Results of Inspection: Violations were discovered and require a submittal.

Within thirty (30) days of receipt of this letter, documentation demonstrating compliance with each of the requirements listed in the attached Inspection Report and Description of Violations (DOV) must be submitted to IDEM. Failure to submit this documentation may lead to this facility being referred for enforcement.

An enforcement action may include civil penalties of up to \$10,000 per UST. Enforcement actions may also affect the owner's and/or operator's eligibility for reimbursement from the Excess Liability Trust Fund (ELTF). Additionally, IDEM may deem the UST's at this facility ineligible for delivery, deposit or acceptance of regulated substances pursuant to IC 13-23-1-4. Finally, federal and criminal penalties may apply for failure to provide required notification; or submitting false information pursuant to IC 13-23-14-2 and liable under IC 13-30-10.


Thank you for your attention to this matter. Please submit the required documents to the UST Section via email at [USTCompliance@idem.in.gov](mailto:USTCompliance@idem.in.gov). Include in the subject line of the response the UST Facility ID # **2242**.

Inspector: Matt Rozycki  
Phone: (317) 296-1853

Direct any questions regarding the inspection to:

Compliance Manager: Carrie Maniet  
Phone: (317) 233-3533

Sincerely,



---

Thomas F. Newcomb, Chief  
UST Compliance Section  
Office of Land Quality

cc: Carrie Maniet  
Matt Rozycki  
UST Facility ID File # 2242  
Aman LLC  
Attn: Pritpal Kaur  
Via email: jugad1337@att.net

### DESCRIPTION OF VIOLATIONS

This inspection or records review revealed that the owner and/or operator of this facility is in violation of Indiana UST Rule 329 IAC 9. 329 Indiana Administrative Code ("IAC") 9 incorporates certain federal underground storage tank requirements found in 40 Code of Federal Regulations ("CFR") Part 280, including those identified below. The Description of Violations (DOV) and corrective measures are as follows:

FACILITY NAME: <b>Arlington Food Mart</b>	UST FACILITY ID: <b>2242</b>
ADDRESS: <b>Arlington Food Mart, Indianapolis, Marion County</b>	INSPECTION DATE: <b>3/9/2022</b>

### VIOLATIONS NOTED IN THIS INSPECTION

#### IC 13-23-12-1 Failure to Pay UST Fees

##### Citation:

Pursuant to IC 13-23-12-1, each year, if an underground storage tank has not been closed before January 1 of the year under rules adopted under IC 13-23-1-2; or a requirement imposed by the commissioner before the adoption of rules under IC 13-23-1-2; the owner of the underground storage tank shall pay to the department an annual registration fee.

The annual registration fee required by this section is ninety dollars (\$90) for each underground petroleum storage tank or two hundred forty-five dollars (\$245) for each underground storage tank containing regulated substances other than petroleum.

If an underground storage tank consists of a single tank in which there are separate compartments, a separate fee shall be paid under subsection (b) for each compartment within the single tank. If an underground storage tank consists of a combination of tanks, a separate fee shall be paid under subsection (b) for each compartment within each tank in the combination of tanks.

For tanks that contain separate compartments and that were in use before July 1, 2014, the payment of a single annual fee of ninety dollars (\$90) for a tank containing separate compartments shall be deemed to satisfy the requirements of subsection.

##### Violation Details:

*The owner and/or operator of the UST system(s) at this site are in violation of this rule because fees are owed for 2020.*

##### Corrective Action:

The owner and/or operator of the UST systems at this site shall pay the required fees to the Indiana Department of Environmental Management within fifteen (15) days of receipt of this notice.

<b>§ 280.34 – Reporting and recordkeeping (general provisions)</b>
<b>Citation:</b>
Pursuant to 40 CFR 280.34, owners and operators of UST systems must cooperate fully with inspections, monitoring and testing conducted by the implementing agency, as well as requests for document submission, testing, and monitoring by the owner or operator pursuant to section 9005 of Subtitle I of the Solid Waste Disposal Act, as amended.
<b>Violation Details:</b>
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because no records were provided at the time of the records request.</i>
<b>Corrective Action:</b>
The owner and/or operator of the UST systems at this site shall immediately perform the monitoring or testing required by the rules and/or submit the requested documentation within seven (7) days of receipt of this notice.

<b>329 IAC 9-8-11(b) – Failure to demonstrate the ability to pay the deductible amount</b>
<b>Citation:</b>
Pursuant to 329 IAC 9-8-11(b), an owner or operator of: (1) twelve (12) or fewer USTs shall demonstrate the ability to pay the applicable deductible amount under IC 13-23-9-1.3; or (2) more than twelve (12) USTs shall demonstrate the ability to pay two (2) times the applicable deductible amount under IC 13-23-9-1.3.
<b>Violation Details:</b>
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because no current financial responsibility mechanism was provided.</i>
<b>Corrective Action:</b>
The owner and/or operator of the UST systems at this site shall submit a copy of the instrument proving they have the coverage required by this rule within thirty (30) days of receipt of this notice.

**§ 280.20(c)(1)(ii) – Failure to have overfill prevention equipment installed or installed properly**

**Citation:**

Pursuant to 40 CFR 280.20(c)(1)(ii), to prevent spilling and overfilling associated with product transfer to the UST system, owners and operators must use the following spill and overfill prevention equipment:

(ii) Overfill prevention equipment that will:

(A) Automatically shut off flow into the tank when the tank is no more than 95 percent full; or

(B) Alert the transfer operator when the tank is no more than 90 percent full by restricting the flow into the tank or triggering a high-level alarm; or

(C) Restrict flow 30 minutes prior to overfilling, alert the transfer operator with a high level alarm one minute before overfilling, or automatically shut off flow into the tank so that none of the fittings located on top of the tank are exposed to product due to overfilling.

**Violation Details:**

*The owner and/or operator of the UST system(s) at this site are in violation of this rule because the site has a history of ball floats, at the time of inspection auto shut off devices were observed in the GSL USTs. Having both forms of overfill can hinder the other from working properly.*

**Corrective Action:**

The owner and/or operator of the UST systems at this site shall, within thirty (30) days of receipt of this notice, contract with a certified contractor to install or replace absent or substandard overfill prevention equipment that will operate as required. The UST owner and/or operator must submit proof that the overfill prevention equipment has been installed properly to the 90% or 95% fill level as required by the type of equipment within forty five (45) days of receipt of this notice. In the case where an owner has changed the overfill prevention equipment from a flow restrictor (ball float) to an auto-shutoff device, the owner must document the entire flow restrictor has been removed or that the automatic shut off device is installed at 90% or lower.

**§ 280.20(b) – Failure to install, design, construct or protect piping from corrosion**

**Citation:**

Pursuant to 40 CFR 280.20(b), the piping that routinely contains regulated substances and is in contact with the ground must be properly designed, constructed, and protected from corrosion in accordance with a code of practice developed by a nationally recognized association or independent testing laboratory.

**Violation Details:**

*The owner and/or operator of the UST system(s) at this site are in violation of this rule because metal components of the piping under the dispensers appear to be in contact with backfill.*

**Corrective Action:**

The owner and/or operator of the UST systems at this site shall, within fifteen (15) days of receipt of this notice, contract with a certified contractor to determine if the piping or metal components in contact with the ground are substandard and what steps will be taken to provide corrosion protection. The UST owner and/or operator must inform IDEM of the proposed work within thirty (30) days of receipt of this notice and receive approval before completing the work. The work must be completed within forty five (45) days of receipt of this notice. If the piping or metal components are determined to be substandard, the UST owner and/or operator shall immediately notify IDEM of their intent to remove or replace the affected components.

**§ 280.35(a)(1) – Failure to perform periodic testing of spill prevention equipment and containment sumps used for IM**

**Citation:**

Pursuant to 40 CFR 280.35(a)(1), owners and operators of UST systems with spill and overflow prevention equipment and containment sumps used for interstitial monitoring of piping must meet these requirements to ensure the equipment is operating properly and will prevent releases to the environment:

(1) Spill prevention equipment (such as a catchment basin, spill bucket, or other spill containment device) and containment sumps used for interstitial monitoring of piping must prevent releases to the environment.

**Violation Details:**

*The owner and/or operator of the UST system(s) at this site are in violation of this rule because periodic testing of the spill prevention equipment was not provided.*

**Corrective Action:**

The owner and/or operator of the UST systems at this site shall, within thirty (30) days of receipt of this notice, contract with a certified contractor to inspect, repair and test all spill prevention equipment and containment sumps. Documentation, to include photographs, inspection, repair and testing results, showing the spill prevention equipment and containment sumps are liquid tight must be submitted within forty five (45) days of the receipt of this notice.

<b>§ 280.35(a)(2) – Failure to perform periodic testing of overfill prevention equipment</b>
<b>Citation:</b> Pursuant to 40 CFR 280.35(a)(2), overfill prevention equipment must be inspected at least once every three years. At a minimum, the inspection must ensure that overfill prevention equipment is set to activate at the correct level specified in § 280.20(c) and will activate when regulated substance reaches that level. Inspections must be conducted in accordance with one of the criteria in paragraph (a)(1)(ii)(A) through (C) of this section.
<b>Violation Details:</b> <i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because periodic testing of the overfill prevention equipment was not provided.</i>
<b>Corrective Action:</b> The owner and/or operator of the UST systems at this site shall, within thirty (30) days of receipt of this notice, contract with a certified contractor to inspect, repair and test all overfill prevention equipment. Documentation, to include photographs, inspection, repair, measurements and testing results, showing the overfill prevention equipment is fully functional and set at the correct level must be submitted within forty five (45) days of the receipt of this notice.
<b>§ 280.36(a)(1)(i) – Failure to perform 30 day walkthrough inspections</b>
<b>Citation:</b> Pursuant to 40 CFR 280.36(a)(1)(i), to properly operate and maintain UST systems, not later than June 28, 2021, owners and operators must conduct a walkthrough inspection every 30 days that, at a minimum, checks spill prevention equipment and release detection equipment (Exception: spill prevention equipment at UST systems receiving deliveries at intervals greater than every 30 days may be checked prior to each delivery).
<b>Violation Details:</b> <i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because monthly walkthroughs have not been provided for July 2021 through February 2022.</i>
<b>Corrective Action:</b> The owner and/or operator of the UST systems at this site shall, within seven (7) days of receipt of this notice, perform the 30 day walkthrough inspection for all UST systems at the site in accordance with a standard of practice referenced in the rule. Documentation, to include photographs, inspection forms, repair documents, and waste disposal records, showing the walkthrough inspection has been completed must be submitted within forty five (45) days of the receipt of this notice.

<b>§ 280.40(a)(3)(i) – Failure to perform annual tests of ATG</b>
<b>Citation:</b>
Pursuant to 40 CFR 280.40(a)(3)(i), owners and operators of UST systems must provide a method, or combination of methods, of release detection that beginning on October 13, 2018, is operated and maintained, and electronic and mechanical components are tested for proper operation, in accordance with one of the following: manufacturer’s instructions; a code of practice developed by a nationally recognized association or independent testing laboratory; or requirements determined by the implementing agency to be no less protective of human health and the environment than the two options listed in paragraphs (a)(1) and (2) of this section. A test of the proper operation must be performed at least annually and, at a minimum, as applicable to the facility, cover the following components and criteria: (i) Automatic tank gauge and other controllers: test alarm; verify system configuration; test battery backup.
<b>Violation Details:</b>
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because an ATG functionality test was not provided.</i>
<b>Corrective Action:</b>
The owner and/or operator of the UST systems at this site shall have all components of the automatic tank gauge or other controllers tested for proper operation within thirty (30) days of receipt of this notice and submit the results within forty five (45) days of receipt of this notice.

<b>§ 280.40(a)(3)(ii) – Failure to perform annual tests of probes &amp; sensors</b>
<b>Citation:</b>
Pursuant to 40 CFR 280.40(a)(3)(ii), owners and operators of UST systems must provide a method, or combination of methods, of release detection that beginning on October 13, 2018, is operated and maintained, and electronic and mechanical components are tested for proper operation, in accordance with one of the following: manufacturer's instructions; a code of practice developed by a nationally recognized association or independent testing laboratory; or requirements determined by the implementing agency to be no less protective of human health and the environment than the two options listed in paragraphs (a)(1) and (2) of this section. A test of the proper operation must be performed at least annually and, at a minimum, as applicable to the facility, cover the following components and criteria: (ii) Probes and sensors: inspect for residual buildup; ensure floats move freely; ensure shaft is not damaged; ensure cables are free of kinks and breaks; test alarm operability and communication with controller.
<b>Violation Details:</b>
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because a functionality test of the ATG probes was not provided.</i>
<b>Corrective Action:</b>
The owner and/or operator of the UST systems at this site shall have all components of the automatic tank gauging probes and sensors tested for proper operation within thirty (30) days of receipt of this notice and submit the results within forty five (45) days of receipt of this notice.

<b>§ 280.40(a)(3)(iii) – Failure to perform annual tests of ALLD</b>
<b>Citation:</b>
Pursuant to 40 CFR 280.40(a)(3)(iii), owners and operators of UST systems must provide a method, or combination of methods, of release detection that beginning on October 13, 2018, is operated and maintained, and electronic and mechanical components are tested for proper operation, in accordance with one of the following: manufacturer's instructions; a code of practice developed by a nationally recognized association or independent testing laboratory; or requirements determined by the implementing agency to be no less protective of human health and the environment than the two options listed in paragraphs (a)(1) and (2) of this section. A test of the proper operation must be performed at least annually and, at a minimum, as applicable to the facility, cover the following components and criteria: (iii) Automatic line leak detector: test operation to meet criteria in § 280.44(a) by simulating a leak.
<b>Violation Details:</b>
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because an annual leak detector test was not provided.</i>
<b>Corrective Action:</b>
The owner and/or operator of the UST systems at this site shall have the automatic line leak detectors tested for proper operation by simulating a leak within thirty (30) days of receipt of this notice and submit the results within forty five (45) days of receipt of this notice.

<b>§ 280.41(a)(1) – Failure to monitor tanks every 30 days if installed before 9/2/2009</b>
<b>Citation:</b>
Pursuant to 40 CFR 280.41(a)(1), considering previous Indiana rule at 329 IAC 9-3-1.3 (repealed 2018), tanks installed on or before September 2, 2009 must be monitored for releases at least every 30 days using one of the methods listed in § 280.43(d) through (i).
<b>Violation Details:</b>
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because 12 months of records were not provided for the tanks.</i>
<b>Corrective Action:</b>
The owner and/or operator of the UST systems at this site shall have any UST or line that contains a regulated amount of product and found to not have been monitored every thirty (30) days tightness tested within thirty (30) days of receipt of this notice and submit the results within forty five (45) days of receipt of this notice. The owner and/or operator shall continue to perform proper monthly release detection and submit the results monthly for a period of six (6) months after the receipt of this notice.

<b>§ 280.41(b)(1)(i)(B) – Failure to perform annual piping LTT or monthly monitoring</b>
Citation:
Pursuant to 40 CFR 280.41(b)(1)(i)(B), pressurized underground piping installed on or before April 11, 2016 (previously cited as September 2, 2009 under 329 IAC 9-2-1(2)(D)) that routinely contains regulated substances must have an annual line tightness test conducted in accordance with § 280.44(b) or have monthly monitoring conducted in accordance with § 280.44(c).
Violation Details:
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because an annual line tightness test is needed.</i>
Corrective Action:
The owner and/or operator of the UST systems at this site shall have any piping that contains a regulated amount of product and found to not have had appropriate monthly monitoring or an annual line tightness test within the 12 months prior to inspection tightness tested within thirty (30) days of receipt of this notice and submit the results within forty five (45) days of receipt of this notice.

<b>§ 280.245 – Failure to maintain list of designated operators and/or training records</b>
Citation:
Pursuant to 40 CFR 280.245, owners and operators of underground storage tank systems must maintain a list of designated Class A, Class B, and Class C operators and maintain records verifying that training and retraining, as applicable, have been completed, in accordance with § 280.34.
Violation Details:
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because updated operator A, B, and C certificates are needed.</i>
Corrective Action:
The owner or operator of the UST systems at this site shall submit a list of those employees designated to be Class A, Class B and Class C operators. Those so designated must be trained and certification of that training submitted within thirty (30) days of receipt of this notice.



**UNDERGROUND STORAGE  
TANK INSPECTION REPORT**

INDIANA DEPARTMENT OF  
ENVIRONMENTAL MANAGEMENT

UST FAC ID: **2242**

Inspector's Name:	Matt Rozycki
Date:	March 9, 2022
Time In:	09:45
Time Out:	10:05
Inspection Type:	Initial

**FACILITY NAME / LOCATION**

FACILITY NAME Arlington Food Mart		FACILITY ADDRESS (number and street) 6014 E Washington St			
ADDRESS (line 2)	CITY Indianapolis	STATE IN	ZIP CODE 46219	COUNTY Marion	

**UST OWNER**

UST Owner Name (if in Individual Capacity) Aman LLC				BUSINESS ID (From the Secretary of State) 2013090600016	
PREFIX	FIRST NAME Pritpal	MI	LAST NAME Kaur	SUFFIX	
TELEPHONE NUMBER (812) 391-3062		EMAIL ADDRESS jugad1337@att.net			

**UST OPERATOR**

UST Operator Name (if in Individual Capacity) S & K Food Mart Inc				BUSINESS ID (From the Secretary of State) 2013102800035	
PREFIX	FIRST NAME Pritpal	MI	LAST NAME Kaur	SUFFIX	
TELEPHONE NUMBER (812) 391-3062		EMAIL ADDRESS jugad1337@att.net			

**PROPERTY OWNER**

UST Property Owner Name (if in Individual Capacity) Aman LLC				BUSINESS ID (From the Secretary of State) 2013090600016	
PREFIX	FIRST NAME Pritpal	MI	LAST NAME Kaur	SUFFIX	
TELEPHONE NUMBER (812) 391-3062		EMAIL ADDRESS jugad1337@att.net			

**COMPLIANCE ELEMENTS**

All USTs properly registered and up-to-date notification form on file	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	UNK	<input type="checkbox"/>
Aman LLC owes fees for 2020						
O/O is in compliance with reporting & record keeping requirements	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	UNK	<input type="checkbox"/>
No records were provided at the time of the records request						
O/O is in compliance with release reporting or investigation	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	N/A	UNK
O/O is in compliance with all UST closure requirements						
O/O is in compliance with all UST closure requirements	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	N/A	UNK
O/O has met all financial responsibility requirements						
O/O has met all financial responsibility requirements	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	N/A	UNK
No current financial responsibility mechanism was provided						
40 CFR 280, Subpart A installation requirements (partially excluded) met	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	N/A	UNK
40 CFR 280, Subpart B installation and upgrade requirements met						
40 CFR 280, Subpart B installation and upgrade requirements met	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	UNK	<input type="checkbox"/>
No overfill on the 2k UST, 2k spill bucket is corroded, metal components continuous with backfill						
40 CFR 280, Subpart C spill/overfill control requirements met	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	N/A	UNK
40 CFR 280, Subpart C compatibility requirements met						
40 CFR 280, Subpart C compatibility requirements met	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	N/A	UNK
40 CFR 280, Subpart C O&M and testing requirements met						
40 CFR 280, Subpart C O&M and testing requirements met	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	UNK	<input type="checkbox"/>
Spill bucket testing, overfill functionality, monthly walkthroughs						
40 CFR 280, Subpart D release detection requirements met	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	UNK	<input type="checkbox"/>
ATG/probes test, LLD, monthly records for the tanks and piping, probe calibration						
40 CFR 280, Subpart J operator training requirements met	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	UNK	<input type="checkbox"/>
A B & C certificates were not provided						

The information contained on this page is based upon a review of files related to this site and/or observations from an underground storage tank inspector. This page may contain information not specifically related to possible violations found during the review or inspection and is meant to give the owners and/or operator specific information to assist them.

Site Maintains three (3) USTs - FG - Installed 11/1/1989

One (1) 10K GSL

One (1) 8K GSL

One (1) 2K DSL

Section Chief Note: The normal operational lifespan of a UST before failing is 25 to 30 years old. The USTs at this site are now 33 years old and the owner should start planning on removing or replacing them soon.

Piping - FG - Pressurized (KER European)

RD UST - ATG

RD Piping - ATG - LTT - LD

Spill protection/Overfill - Spill bucket - Flapper

ATG Certification = N

Overfill Protection Test = N

Spill bucket Test = N

Containment Sumps Test Required N

Site is an active gas station

Any Site history or concerns - Site has history of ball floats

Two (2) USTs closed 11/30/1989 (Closure report on file)

Documentation received -

Notification form - 6/29/2017 (Initial approval)

No additional documents received at time of review

Documentation needed -

RD UST monthly results -

RD Piping

LD

Annual ATG test

Overfill test required every 3 years

Spill bucket test required every 3 years

Monthly walk through July-Current month

Operator certificate - A-B-C

FR

The information contained on this page is based upon a review of files related to this site and/or observations from an underground storage tank inspector. This page may contain information not specifically related to possible violations found during the review or inspection and is meant to give the owners and/or operator specific information to assist them.

The following are AREAS OF CONCERN found during the inspection that will need to be addressed by the owner and/or operator:

1. The REG & PREM spill buckets have some warping, they should be monitored and replaced if a crack develops
2. The spill buckets contained some fluid, they should be monitored and cleaned out as needed
3. The STP sumps had some fluid and debris they should be monitored and cleaned out as needed
4. DSL dispenser has been condemned by Weights and Measure. ATG reads DSL UST has less than 1 inch of product. Before UST is brought back into use spill bucket needs to be replaced, overfill needs to be repaired as ball floats and coaxial drop tubes conflict and does not provide overfill protection.

The following are VIOLATIONS discovered during the inspection that will need to be corrected within 30 days of receipt of this inspection report to avoid further action and achieve compliance with the state underground storage tank program:

1. Fees are owed for 2020 by Aman LLC
2. No records were provided at the time of the records request
3. A current financial responsibility mechanism was not provided
4. The site has a history of ball floats, auto shut off devices were observed on site
5. The metal components of the piping under the dispensers appear to be in contact with the backfill
6. Spill bucket testing was not provided
7. Overfill functionality testing was not provided
8. Monthly walkthrough inspections were not provided
9. The probe for the DSL UST does not appear to be calibrated correctly. The temperature was far higher than the other 2 tanks
10. ATG functionality testing was not provided
11. Functionality testing of the ATG probes was not provided
12. An annual leak detector test was not provided
13. Monthly release detection records were not provided for the tanks
14. Monthly release detection records were not provided for the piping
15. Operator A B & C certificates were not provided

The following are RECORDS to be submitted to [USTCompliance@idem.IN.gov](mailto:USTCompliance@idem.IN.gov) with FID in subject line within 30 days of receipt of this inspection report to avoid further action and achieve compliance with the state underground storage tank program (update accordingly):

RD UST monthly results -

RD Piping

LD

Annual ATG/probes test

Overfill test required every 3 years

Spill bucket test required every 3 years

Monthly walk through July-Current month

Operator certificate - A-B-C

FR

Corrosion protection for the metal components of piping

Fees