## LEVEL 2 ASSESSMENT - TRANSIENT PUBLIC WATER SYSTEM

State Form 55983 (R5 / 12-20) Indiana Department of Environmental Management Office of Water Quality – Drinking Water Branch

Public Water System Identification (PWSID) number

## Mail, e-mail, or fax this form and supporting documents to: INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT DRINKING WATER BRANCH

100 North Senate Avenue, Room N1201 Indianapolis, IN 46204 E-mail: CapCert@idem.in.gov

INSTRUCTIONS: A Certified Level 2 Assessors or agent of the State must complete this form. The goal of this assessment is to resolve this system's total coliform contamination. The assessor will provide a determination of the cause of this total coliform contamination by checking "Yes" on the appropriate checkboxes below. With each issue checked "Yes", the assessor will follow with a narrative in the "Issue Description" AND "Corrective Action" columns. If any question or section does not apply, simply strike through or mark as N/A. The system representative listed below is responsible for implementing the corrective actions identified within thirty (30) days of this assessment and will provide documentation (photos or receipts) of the corrective actions to IDEM at <a href="mailto:CapCert@idem.in.gov">CapCert@idem.in.gov</a>.

Name of system

2760942		Best Western Fremont			
Name of system representative Tigna Patel	Patel How representative is affiliated with the system owner				
1. SAMPLING SITES	Issue(s) Found?	Description of Issue	Corrective Action(s)		
Unclean, leaking, damaged or unsuitable tap	✓Yes □ No	Dwner used unapproved	C. Jing some) of must		
Changed sampling location	¥Yes □ No		Routine samples must		
Unapproved or unsuitable sampling location	☑Yes ☐ No	Sampling site. Sampling	be taken only from		
Low / inadequate disinfection residual	☐ Yes ☑ No	site was visibly	approved locations on		
Plumbing changes or additions	☐ Yes ☑ No	dirty.	•		
Plumbing breaks or failure	☐ Yes 🗹 No	3	official Site Sampling		
Cross connection adjacent sampling site (such as, but not limited to, reverse osmosis unit)	☐ Yes 🗹 No		Plan.		
Untested backflow device(s) adjacent sample site	☐ Yes ☑ No				
Other:	☐ Yes <b>☑</b> No				
2. SAMPLING PROTOCOL	Issue(s) Found?	Description of Issue	Corrective Action(s)		
Tap wasn't flushed (prior to sampling)	☐ Yes 🗹 No	Owner used alcohol wipes, did	Must spray with bleach/		
Tap wasn't disinfected (prior to sampling)	☑Yes ☐ No	not disinfect with 50%	water solution and wait 5		
Aerator or screen damaged or corroded	☐ Yes ☑ No	breach/water solution.	minutes, then flush for 5		
		Dans 1 of 6	minutes, before taking sample.		

Public Water System Identification (PWSID) number 2760942		Name of system  Best Western Fremont				
2. SAMPLING PROTOCOL (continued)	Issue(s) Found?	Description of Issue	Corrective Action(s)			
Old sample bottle	☐ Yes ☑ No	Owner did not remove	Must remove aerator			
Bottle seal broken	☐ Yes ☑ No	aerator from faucet	before taking sample.			
New person collected water sample	☐ Yes 🗹 No	before taking sample.	before alking sample.			
Sampling error	✓Yes □ No	perore such sumpo				
Improper hold time	☐ Yes ☑ No					
Improper storage temperature	☐ Yes ☑ No					
Other:	☐ Yes ☑ No					
3. OPERATIONAL CHANGES	Issue(s) Found?	Description of Issue	Corrective Action(s)			
New sample tap installed	☐ Yes ☑ No	System has removed	System must immediately			
New treatment device added	☐ Yes ☑ No	Source Sample Tap.	install a smooth bore Sample			
Source added	☐ Yes ☑ No	500000	Tap on the line coming			
Source abandoned	☐ Yes ☑ No	Source Sample (TG) that	the building before			
New storage tank added	☐ Yes ☑ No	tested Positive for Total	into the building, before			
Visible indicators of unsanitary conditions	☐ Yes ☑ No	Coliforn was taken from	any split/tee.			
Recent repairs to water lines	☐ Yes ☑ No	a hotel room sink.	System must take a sample			
Water system was NOT disinfected / flushed following plumbing construction or repairs	☐ Yes ☑ No	a note toom some.	from this smooth bore tap (i.e.			
Loss of power	☐ Yes ☑ No		directly from well) that is			
Other:	☑Yes ☐ No		Absent for Total Coliform to			
			clear the well.			

Public Water System Identification (PWSID) number	Name of system
2760942	Best Western Fremont

4. DISTRIBUTION SYSTEM	Issue(s) Found?	Description of Issue	Corrective Action(s)		
Low flow / dead end main	☐ Yes ☑ No	Softener drain line	System needs to cut pipe so		
Low disinfection residuals (if applicable) review systems records, sample (if needed)	☐ Yes ☑ No	and to cross	that there is a 1" air gap		
Water line breaks	☐ Yes ☑ No	goes to cross  connection on floor drain.			
Loss of pressure or low pressure (less than 20 psi)	☐ Yes ☑ No	CONNECTION ON 1000 South.			
Water leaks	☐ Yes ☑ No		May want to investigate		
Construction or installation of plumbing	☐ Yes ☑ No	Sustem has fire suppression			
Cross connection issue(s) including but not limited to softener waste lines, irrigation, boiler make-up, baptismal, fire suppression, mop sinks, manufacturing process systems	✓ Yes □ No	is being served by potable	fire suppression system		
Untested backflow device(s)	☐ Yes ☑ No		after other issues are		
Inadequate flushing of water lines due to inactivity or closure of the facility	☐ Yes ☑ No	well / needs backflow prevention.	corrected.		
Evidence of vandalism	☐ Yes ☑ No				
Other:	☑Yes ☐ No				
5. TREATMENT	Januara Faunda	Description of leave	Compatible A. E. or (a)		
5. TREATMENT N/A	Issue(s) Found?	Description of Issue	Corrective Action(s)		
Treatment device malfunctioning	☐ Yes ☑ No	Water level is above salt	Must clean brine tank		
Treatment added or changed	☐ Yes ☑ No	level in softener brine tank.  Lid was kept off brine tank.  Brine tank lid does not	according to manufacturer's		
Cross connection issue(s)	☐ Yes ☑ No				
Inadequate disinfection	☐ Yes ☑ No		recommendations, and refill		
Interruption in treatment / power loss	☐ Yes ☑ No	close securely; plus there is	with salt.		
Chemical feed rate problems	☐ Yes 🗹 No	a hole at the edge of the lid.	Always keep salt level		
Filter contamination	☐ Yes ☑ No	Water in brine tank visibly	above water level.		

Contaminated.

Public Water System Identification (PWSID) number		Name of system	
2760942		Best Western Fremont	
5. TREATMENT (continued)	/A Issue(s) Found?	Description of Issue	Corrective Action(s)
Maintenance schedules not followed	☐ Yes ☑ No		(Brine tank needs to be
Chemical day tanks empty / inadequately seale (e.g. softener out of salt)	d ✓Yes □ No		(Brine tank needs to be drained and cleaned). I.e.
Evidence of short circuiting in treatment process	S ☐ Yes ☑ No		rinsed w/ bleach water.
Evidence of contamination	✓Yes □ No		Lid must be tightly sealed, no open gaps (sea) with 24#mesh so
Other:	☐ Yes ☑ No		no open gaps (sea) with 24#mesh so
6. STORAGE TANK	I/A Issue(s) Found?	Description of Issue	Corrective Action(s)
Tank(s) is damaged, rusty, or has holes	☐ Yes ☑ No	Sustem randural strange	AA
Tank bladder(s) is waterlogged	☐ Yes ☑ No	System replaced storage tanks last year.	May want to investigate
Hydropneumatic tank malfunctioning	Yes YNo	tanks last year.	storage tanks after other
Vent / overflow screen damaged / missing	☐ Yes ☑ No	However, system did collect	May want to investigate storage tanks after other issues are corrected.
Signs of vandalism / unauthorized access	☐ Yes ☑ No	However, system did collect clean Routine samples	
Recent work or repair of tank	☐ Yes ☑ No	Since then.	
Evidence of contamination	☐ Yes ☑ No		
Standing water around tank	☐ Yes ☑ No		
Debris around tank	☐ Yes ☑ No	] .	
Water age / inadequate turnover	☐ Yes ☑ No		
Lack of maintenance or inspection	☐ Yes ☑ No		
Other:	Yes To a		

Public Water System Identification (PWSID) number		Name of ourters			
2760942	Name of system				
Best Western Fremont					
7. SOURCE - WELLS	Issue(s) Found?	Description of Issue	Corrective Action(s)		
Cracked, broken, or missing well cap	✓Yes □ No	(Ma)) care is escaled )			
Cracked or damaged well casing	☐ Yes ☑ No	Well cap is cracked, loose	, System must call		
If well casing is cracked, is the protective barrier missing?	☐ Yes ☑ No	and visibly open	well driller to		
Well screen missing or damaged	☐ Yes ☑ No	(slight gap where			
Missing or damaged grout seal (voids around well allowing contaminates into well)	☐ Yes ☑ No	contaminants can enter	repair + tighten well		
Recent work on pump	☐ Yes ☑ No	-	cap. Since there is		
Well pump cycling improperly	☐ Yes ☑ No	the system).	1		
Pump assembly leaking / damaged (jet pump or vertical turbine only)	☐ Yes ☑ No		a visible opening, also		
Evidence of contamination	☐ Yes ☑ No	Well cap has loose bolt.	may want to disinfect		
Flooding or standing water near well	☐ Yes ☑ No		the well.		
Standing water / flooding in well pit	☐ Yes ☑ No		yme was:		
Ground slopes toward well casing	☐ Yes ☑ No				
Air relief valve missing screen and / or air gap	☐ Yes ☑ No				
Other:	☐ Yes 🗹 No				
		CERTIFICATION			
I certify under penalty of law that I am a Cortified I a	wol 2 Appagan and th	CERTIFICATION			
I certify, under penalty of law, that I am a Certified Le my knowledge and belief, true, accurate and comple	te. I am also aware tha	at there are significant penalties for submitting false inf	ection, and the information submitted is to the best of ormation.		
Signature A 1 a 1					
Printed name Judson Baker		a Irispector	ise number(s) (if applicable)		
Telephone number (574) 413 - 8833	E-mail address	S JTBaker @ idem. in. gov			

Please save a copy of this form and return the original form along with a copy of your training information (including, but not limited to, an Indiana Water Basics Course (INWBC) certificate of completion) to the Indiana Department of Environmental Management. It is important to provide the system representative with a copy of this document. The drinking water system is responsible for completion of all corrective action(s) identified within thirty (30) days of this assessment.

Public Water System Identification (PWSID) number		Name of system					
2760942			Best Western Fremont				
						and the second s	
		FOR IDEM	USE ONLY				
Name if IDEM reviewer					Date of IDEM consultation	i (if needed) (month, day, year)	
Document preparer completed INWBC Yes No	Level 2 Assessment accepted  Yes No	PWS has corrected	the problem Yes No	Corrective A	ction Plan approved Yes No	Approved with changes	s 🗆 No
Comments		<b></b>					

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT  Public Water System Sanitary Survey / Field Inspection Report
Public Water System Sanitary Survey Field Inspection Report
Best Western Fremont  PWSID Number  2760942 6127124
Best Western Fremont  2760942 6/27/24
* Are there any possible system problems not addressed by this survey that deserve attention of system staff?  42. Comments and Recommendations
Level 2 Assessment
· Routine sample was taken from unapproved location, not
disinfected w/ bleach+water solution, aerator on
faccet was not removed
· Repeat sample that tested Positive was taken from
unapproved location
· TC+ Report sample labeled as "source" sample (TG) was
baken from a hotel room sink, not actually taken from source
· Water softener brine tank lid was open : even when
closed, lid does not seal tightly and there is an open hole
water level above salt level, visible debris in water
· System needs to verify that softener discharge is draining
correctly; drain needs to have 1" air gap above floor drain
· system does not have Source Sample Tap, cannot take
clear sample from well
· well cap is loose, visibly cracked, has loose bolt
· need to call well driller, may want to disinfect well
· may want to investigate storage tanks (adequate tumover?)
and fire suppression system (is it being served by the
potable well? Is backflow prevention needed?) after other issues
are corrected
Parties present: Judson Baker (IDEM) Jigna Patel (system owner)
V
Survey Performed By Person Interviewed and Signature Recheck Date
Judsombaker Jignasy. D. Patel
This Sanitary Survey is being conducted under regulations required by Indiana Code 13.18.16.40 and 40.40.40.40

Page 3

Otate Form 4//12 (R3/11-09)