INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

We Protect Hoosiers and Our Environment.

100 N. Senate Avenue • Indianapolis, IN 46204 (800) 451-6027 • (317) 232-8603 • www.idem.IN.gov

Eric J. Holcomb Governor Brian C. Rockensuess Commissioner

April 29, 2022

MDC Coastal 6 LLC c/o Corporation Service Company 135 N Pennsylvania St., Suite 1610 Indianapolis, IN 46204

FedEx Ground Packing System Inc c/o CT Corporation System 334 N Senate Ave Indianapolis, IN 46204

Re: Violation Letter FedEx Ground North Indianapolis 10301 Bennett Pkwy Zionsville, Boone County UST Facility ID **# 25398**

Dear Mr. Eads:

An inspector from the Indiana Department of Environmental Management (IDEM), Underground Storage Tank (UST) Section, conducted an inspection of the site referenced above on April 6, 2022.

The inspection was conducted pursuant to Indiana Code (IC) 13-14-2-2 to determine compliance with the provisions of IC 13-23 and 329 IAC 9. In accordance with IC 13-14-5, a summary of the inspection is provided below:

Type of Inspection: Initial

Results of Inspection: Violations were discovered and require a submittal.

Within thirty (30) days of receipt of this letter, documentation demonstrating compliance with each of the requirements listed in the attached Inspection Report and Description of Violations (DOV) must be submitted to IDEM. Failure to submit this documentation may lead to this facility being referred for enforcement.

An enforcement action may include civil penalties of up to \$10,000 per UST. Enforcement actions may also affect the owner's and/or operator's eligibility for reimbursement from the Excess Liability Trust Fund (ELTF). Additionally, IDEM may deem the UST's at this facility ineligible for delivery, deposit or acceptance of regulated substances pursuant to IC 13-23-1-4. Finally, federal and criminal penalties may apply for failure to provide required notification; or submitting false information pursuant to IC 13-23-14-2 and liable under IC 13-30-10.





FedEx Ground North Indianapolis UST Facility ID # **25398** Page #2

Thank you for your attention to this matter. Please submit the required documents to the UST Section via email at <u>USTCompliance@idem.in.gov</u>. Include in the subject line of the response the UST Facility ID # **25398**.

Inspector: John Metz Phone: (317) 296-0383

Direct any questions regarding the inspection to:

Compliance Manager: Loic Maniet Phone: (317) 232-3592

CC:

Sincerely, Earl

Thomas F /Newcomb, Chief UST Compliance Section Office of Land Quality

Loic Maniet John Metz UST Facility ID File # 25398 FedEx Ground Packing System Inc Attn: Troy Eads Via email: environmental@fedex.com

DESCRIPTION OF VIOLATIONS

This inspection or records review revealed that the owner and/or operator of this facility is in violation of Indiana UST Rule 329 IAC 9. 329 Indiana Administrative Code ("IAC") 9 incorporates certain federal underground storage tank requirements found in 40 Code of Federal Regulations ("CFR") Part 280, including those identified below. The Description of Violations (DOV) and corrective measures are as follows:

FACILITY NAME: FedEx Ground North Indianapolis	UST FACILITY ID: 25398			
ADDRESS: 10301 Bennett Pkwy, Zionsville, Boone County	INSPECTION DATE: 04/06/2022			

VIOLATIONS NOTED IN THIS INSPECTION

IC 13-23-12-1 Failure to Pay UST Fees

Citation:

Pursuant to IC 13-23-12-1, each year, if an underground storage tank has not been closed before January 1 of the year under rules adopted under IC 13-23-1-2; or a requirement imposed by the commissioner before the adoption of rules under IC 13-23-1-2; the owner of the underground storage tank shall pay to the department an annual registration fee.

The annual registration fee required by this section is ninety dollars (\$90) for each underground petroleum storage tank or two hundred forty-five dollars (\$245) for each underground storage tank containing regulated substances other than petroleum.

If an underground storage tank consists of a single tank in which there are separate compartments, a separate fee shall be paid under subsection (b) for each compartment within the single tank. If an underground storage tank consists of a combination of tanks, a separate fee shall be paid under subsection (b) for each compartment within each tank in the combination of tanks.

For tanks that contain separate compartments and that were in use before July 1, 2014, the payment of a single annual fee of ninety dollars (\$90) for a tank containing separate compartments shall be deemed to satisfy the requirements of subsection.

Violation Details:

The owner and/or operator of the UST systems at this site are in violation of this rule because they have not paid any tank fees for 2021.

Corrective Action:

The owner and/or operator of the UST systems at this site shall pay the required fees to the Indiana Department of Environmental Management within fifteen (15) days of receipt of this notice.

329 IAC 9-2-2(c) – Failure to register/notify with complete information

Citation:

Pursuant to 329 IAC 9-2-2(c), an owner required to submit a notification under this section shall provide:

(1) a notification for each UST owned;

(2) complete information required on the form for each UST owned; and

(3) if applicable, a separate notification form for each separate place of operation at which the USTs are located.

Violation Details:

The owner and/or operator of the UST system(s) at this site are in violation of this rule because their Notification Form has incorrect property ownership information.

Corrective Action:

The owner and/or operator of the UST systems at this site shall fill out and submit to IDEM a correct and complete copy of the appropriate state form with required attachments, within fifteen (15) days of receipt of this notice.

§ 280.41(a)(2) – Failure to monitor (IM) tanks every 30 days if installed after 9/2/2009 Citation:

Pursuant to 40 CFR 280.41(a)(2), and previously 329 IAC 9-3-1.3 (repealed 2018), tanks installed after September 2, 2009 must be monitored for releases at least every 30 days using the method listed in § 280.43(g).

Violation Details:

The owner and/or operator of the UST system(s) at this site are in violation of this rule because twelve (12) months of interstitial monitoring records were not available.

Corrective Action:

The owner and/or operator of the UST systems at this site shall have any UST or line that contains a regulated amount of product and found to not have been monitored every thirty (30) days by not having records of interstitial monitoring tightness tested within thirty (30) days of receipt of this notice and submit the results within forty five (45) days of receipt of this notice. The owner and/or operator shall continue to perform proper monthly release detection and submit the results monthly for a period of six (6) months after the receipt of this notice.

§ 280.41(b)(2) – Failure to perform monthly monitoring on piping installed after 9/2/2009, except proper European

Citation:

Pursuant to 40 CFR 280.41(b)(2), piping installed or replaced after April 11, 2016 (previously cited as September 2, 2009 under 329 IAC 9-2-1(2)(D)) must meet one of the following:

(i) Pressurized piping must be monitored for releases at least every 30 days in accordance with § 280.43(g) and be equipped with an automatic line leak detector in accordance with § 280.44(a)

(ii) Suction piping must be monitored for releases at least every 30 days in accordance with § 280.43(g).

Violation Details:

The owner and/or operator of the UST system(s) at this site are in violation of this rule because twelve (12) months of interstitial monitoring records were not provided.

Corrective Action:

The owner and/or operator of the UST systems at this site shall continue to perform proper monthly release detection and submit the results monthly for a period of six (6) months after the receipt of this notice.

STHE STATE OF	UNDERGROUND	STORAGE	RAGE		Inspector's Name: John Metz					
SEAL SEAL	TANK INSPECTIO	ON REPORT			Date: April 6, 2022					
1816	INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT			Time In: 11:55						
			_		Time Out: 13:15					
	UST FAC ID:	25398		Inspec	tion Ty	pe: Initial				
FACILITY NAME		FACILITY	FACILITY ADDRESS (nu							
-	Fround North Indianap	olis	10301 Benn							
ADDRESS (line 2	2)	Zionsville		STATE IN		₌ 6077	7 Boone			
			IST OWNER							
UST Owner Nam	e (If in Individual Capacity) Ground Package Syste	m Inc				BUSINESS ID		retary of State)		
^{prefix} Mr	FIRST NAME Troy	MI	LAST NAME Eads		-			SUFFIX		
TELEPHONE NU (412) 26		EMAIL ADDRESS	ntal@fedex.con	n						
(+12)20	2-1010		T OPERATOR							
	ame (If in Individual Capacity) Ground Packing Syster					BUSINESS ID 198806	(From the Secr 1204	etary of State)		
^{prefix} Mr	FIRST NAME Stephen	MI	LAST NAME Hunt					SUFFIX		
TELEPHONE NU (317) 87		EMAIL ADDRESS	nt@fedex.com							
(317)07	5-1055									
	vner Name (If in Individual Capacity) Astal 6 LLC						(From the Secr 251156			
PREFIX	FIRST NAME	МІ	LAST NAME			201000	201100	SUFFIX		
TELEPHONE NU (630) 36		EMAIL ADDRESS								
(000) 00	0 2040	COMPL		ſS						
All USTs pr	operly registered and up-to-d				YES	XNO		UNK		
	otification Form to reflect proper									
O/O is in co	ompliance with reporting & rec	cord keeping requ	irements	X	YES	NO		UNK		
O/O is in co	mpliance with release reporti	ng or investigatior	۱		YES	NO	X N/A	UNK		
O/O is in co	mpliance with all UST closur	e requirements			YES	NO	X N/A	UNK		
	·	·						<u> </u>		
O/O has me	et all financial responsibility re	equirements			YES	NO	N/A	UNK		
40 CFR 280	0, Subpart A installation requi	rements (partially	excluded) met	X	YES	NO	N/A	UNK		
					11					
40 CFR 280	D, Subpart B installation and u	upgrade requirem	ents met		YES	NO		UNK		
40 CFR 280), Subpart C spill/overfill cont	rol requirements r	net	X	YES	NO	N/A	UNK		
40 CEB 280	0, Subpart C compatibility rec	uirements met			YES	NO	N/A	UNK		
40 01 11 200	, ouspart o compatishity red				120					
40 CFR 280	0, Subpart C O&M and testing	g requirements me	ət	X	YES	NO		UNK		
40 CFR 280), Subpart D release detectio	n requirements m	et	I	YES	X NO		UNK		
	rds INT for both tanks					· · ·				
40 CFR 280	0, Subpart J operator training	requirements me	t	×	YES	NO		UNK		

COMPLIANCE REVIEW AND COMMENTS UST Facility ID 25398
The information contained on this page is based upon a review of files related to this site and/or observations from an underground storage tank inspector. This page may contain information not specifically related to possible violations found during the review or inspection and is meant to give the owners and/or operator specific information to assist them.
Site Maintains:
- One (1) 20K DSL FG DW UST installed in September 2013 - Piping is FG DW and Pressurized
RD UST = INT RD Piping = N/A Overfill/Spill = Spill Buckets + Ball Float (Consistent) + Alarm (consistent) ATG Certification = Y (4/5/2022) Overfill Protection Test = Y (4/9/2021) Spill bucket Test = Y (10/14/2021) Containment Sumps Test (required) = Y (4/9/2021)
Site History:
Site is a Fedex facility with fueling capability. There is no prior UST history at this site.
Contact Information
Troy Eads environmental@fedex.com
Documentation not provided at the time of the file review:
- Updated NF (NF 11/14/2014, Approval 11/26/2014 - property ownership has changed in 2016) - Certificate of Financial Responsibility - Fees 2021
 Operator Certificates Release Detection Records INT (UST and piping)
 Leak Detector test Spill bucket / UDC / STP testing ATG/Sensors test Overfill test Walkthrough
CM Note:
- Owner submitted documentation after inspection:
 - FR, Spill bucket test DSL 10/14/2021, spill bucket test 4/9/2021 (fail), LLD 4/9/2021, ATG Certification 4/9/2021, Overfill Alarm test 4/9/2021, Sump inspection 4/9/2021 (visual only), LLD 4/5/2022, LTT (main + satellite) 4/5/2022, ATG/Probes/sensors 4/5/2022, STP/UDC test 4/9/2021, Monthly walkthroughs - Overfill alarm visible within feet of UST. - Line tightness test completed on 4/6/2022 - will only require owner to submit records for upcoming month

COMPLIANCE REVIEW AND COMMENTS CONTINUED

UST Facility ID 25398

The information contained on this page is based upon a review of files related to this site and/or observations from an underground storage tank inspector. This page may contain information not specifically related to possible violations found during the review or inspection and is meant to give the owners and/or operator specific information to assist them.

The following are AREAS OF CONCERN found during the inspection that will need to be addressed by the owner and/or operator:

- 1. The fill port cap was broken.
- 2. The spill bucket contained some fluid.
- 3. The STP sump contained a small amount of fuel.

The following are RECORDS to be submitted to the inspector within 30 days of receipt of this inspection report to avoid further action and achieve compliance with the state underground storage tank program:

- 4. Updated Notification Form with correct property owner information
- 5. 2021 tank fees
- 6. 12 months of interstitial release detection for USTs

7. Continue to submit INT records for piping. LTT was provided and would address prior missing records but will need upcoming records to ensure piping is properly monitored.