

Indiana Department of Environmental Management

We Protect Hoosiers and Our Environment.

100 N. Senate Avenue • Indianapolis, IN 46204 (800) 451-6027 • (317) 232-8603 • www.idem.IN.gov

Eric J. Holcomb

Brian Rockensuess Commissioner

June 28, 2024

Via Email to: clerk@lafontaine.in.gov Mr. John Krhin , Town Council President Town of Lafontaine 13 W Branson St. LaFontaine. Indiana Wabash

Dear Mr.:

Re: Inspection Summary Letter
LaFontaine STP
NPDES Permit No. IN0020371
LaFontaine, Wabash County

An inspection of the above-referenced facility or location was conducted by a representative of the Indiana Department of Environmental Management, Office of Water Quality, pursuant to IC 13-18-3-9. A summary of the inspection is provided below:

Date(s) of Inspection: June 25, 2024

Type of Inspection: Reconnaissance Inspection

Inspection Results: Potential problems were discovered or observed.

Effective immediately, IDEM is initiating a program strongly encouraging domestic wastewater utilities to perform cybersecurity vulnerability assessments, and to take actions to mitigate identified vulnerabilities and increase the cybersecurity resilience of Indiana's water sector. Utilities can choose any assessment tool appropriate for the water sector, but IDEM is highlighting the following websites for information and helpful vulnerability assessment tools made available from the U.S. EPA and the American Water Works Association: https://www.epa.gov/waterresilience/epa-cybersecurity-water-sector and https://www.awwa.org/Resources-Tools/Resource-Topics/Risk-Resilience/Cybersecurity-Guidance. IDEM will continue to share important updates on the cybersecurity of the water sector.

A copy of the NPDES Wastewater Facility Inspection Report is enclosed for your records. Please direct any response to this letter and any questions to Andy Schmidt at 317-691-1905 or by email to atschmid@idem.IN.gov.

Sincerely,

1 Re

Kim Rohr, Chief Wastewater Inspection Section Office of Water Quality

Enclosure



NPDES Wastewater Facility Inspection Report INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

NPDE	S Permit Number:	Facility Type:						Facility Classification:		TEMPO AI ID		
	IN0020371		Munic	ipality		Min	or		I	55268		
Date	(s) of Inspection: June	e 25, 2024								•		
		nnaissance	Inspec	tion								
	and Location of Facility Inspec	ted:				Receiving Wa	iters:		F	Permit Expiration Date		
	ontaine STP					0 10				7/21/2026		
	5 E 1050 S ontaine	IN 4694		County: /abash		Grant Cree	eK			Design Flow: 0.176MGD		
	· · · · · · · · · · · · · · · · · ·	Title Certified	•		ntair	neutilities@c				one 0-330-9762		
Was a verbal summary of findings presented to the on-site representative? Yes Certified Operator: Number: Class: Effective Date: Expiration Date: Email:												
Certiii	Lance Gray	16801	Class.	7-1-22	E.	6-30-25	Elliali.					
Cybe	er Security Contact:		<u> </u>									
Name	,			Email:								
Respo	Responsible Official: Permittee: Town of Lafontaine											
	lohn Krhin , Town Council	President					clerk@la					
13 V	V Branson St.								9-1	Contacted?		
LaFo	ontaine, Indiana Wabash											
Lai	maino, maiana vvabaon			INSPECTIO	ON F							
	O Conditions evaluated w	vere found to	be sati	sfactory at th	he tin	ne of the insr	ection. (5	5)				
		Phone: 765-981-4591 Contacted? Fax: No INSPECTION FINDINGS Is evaluated were found to be satisfactory at the time of the inspection. (5) Is were discovered but corrected during the inspection. (4) problems were discovered or observed. (3) Is were discovered and require a submittal from you and/or a follow-up inspection by IDEM. (2) INSPECTION FINDING INSPECTION INSPECTION AREAS EVALUATED DURING INSPECTION										
		Fax: No INSPECTION FINDINGS were found to be satisfactory at the time of the inspection. (5) ered but corrected during the inspection. (4) re discovered or observed. (3) ered and require a submittal from you and/or a follow-up inspection by IDEM. (2) ered and may subject you to an appropriate enforcement response. (1)										
		I were found to be satisfactory at the time of the inspection. (5) overed but corrected during the inspection. (4) overed discovered or observed. (3) overed and require a submittal from you and/or a follow-up inspection by IDEM. (2) overed and may subject you to an appropriate enforcement response. (1) AREAS EVALUATED DURING INSPECTION										
	Violations were discove			-				sponse. (1)			
								aluated				
S	Receiving Waters	S	Facility	y/Site	S	Self-Monitor	oring	Ν	Enforcem	ent		
S	Effluent	М	Opera	tion	Ν	Flow Meas	surement	t N	Pretreatm	ent		
N	Permit	S	Mainte	enance	S	Laboratory	/	S	Effluent Li	mits Compliance		
S	Collection System	S	Sludge	e Disposal	S	Records/R	eports	N	Other:			
	,		_		A E	/ALUATION	•					
Rec	eiving Waters:											
Comn		of the diesel	orgo of	Outfall 000	Cro	nt Crook on	noorod n	ormal f	r the coor	on Mator		
was	iewed from the location o clear, with no visible evid							iormai io	or the seaso	on. vvaler		
Efflu										_		
Comments: Effluent was clear at Outfall 002 at the time of the inspection.												
	ection System:											
	nents: etation #3 (main lift station	a) and lift et	ation #1) wara inen	ecter	l and both w	vere foun	nd to be	in good wo	rking		
Lift station #3 (main lift station) and lift station #2 were inspected and both were found to be in good working condition, with "clean" wet wells, all pumps in service, and with SCADA connection. Also, lift stations are inspected daily by the operator.												
	lity/Site:	л.										
Comn		to he well	maintai	ned Acces	SS 14/	as anod to th	he facility	, and to	the outfall (at Grant's		
1116	idonity grounds appeared	I TO DO WEII	mama	nou. Acces	JJ 110	as good to the	io racinty	and to	are outiall o	at Orant 3		

Creek. There is a generator on site for power outages.

Operation:

Comments:

Operation was rated marginal for high mixed liquor concentrations in aeration tanks and for resulting foam on the surface of the secondary clarifier. Looking at MRO data, it was noted that MLSS was 10,184 in March 2024, 10,984 in April, and 7,260 in May 2024. This condition appears to have been caused by part of the recent plant upgrade project, where the RAS line flows into a splitter box then it splits RAS flow into both aeration tanks. The operator had noticed signs of high MLSS in one tank and low MLSS in the other tank and testing verified that the configuration of the splitter box had been causing higher concentrations of RAS to flow into one aeration tank, and lower concentrations into the other tank. By the time that the operator was able to verify that, MLSS concentrations had risen above normal benchmark levels. It was noted during the inspection that MLSS concentrations have been reduced in the past month, and the operator will continue until MLSS reaches ideal levels. In addition, the operator has been using a pump to circulate mixed liquor between the aeration tanks to help achieve even levels, and it was recommended to continue doing separate MLSS and 30 Minute SSV testing for each aeration tank. With the plant upgrade project in it's end stages, that situation is considered to be part of the normally expected trouble-shooting and operational fine-tuning that can be part of a facility upgrade project.

The operator will continue with process control testing, and experiment with operating parameters to develop a new Operational Summary, which will detail most efficient levels for those parameters with the newly upgraded system.

Maintenance:

Comments:

All treatment units and equipment appeared to be in good working condition at the time of the inspection. The facility and grounds appeared well-kept and well-tended.

There was a problem with clarifier skimmers noted during the inspection, but it appeared that is most probably attributable to the operational issues noted above, due to the recent plant upgrade. The operator indicated that he is currently working to determine the most efficient ways to keep the sludge blanket depth at efficient levels using the new RAS system.

In addition, the operator indicated that a new online preventative maintenance (PM) system - Silversmith Active Management is intended to be put into use for the sewage treatment plant.

Self-Monitoring:

Comments:

The Self Monitoring Program was rated as satisfactory. All sampling practices, including raw and intermediate unit process testing, are conducted accurately and at the frequency required by the permit.

During the recent upgrade, new auto samplers were included for both raw and final effluent sampling. The samplers were set to collect a flow proportioned sample, with aliquots every 1000 gallons.

It was recommended to obtain NIST traceable thermometers to be kept inside the sample compartments of the samplers to assure proper temps for sample holding.

Laboratory:

The following laboratory records were reviewed:

Ammonia Bench Sheets CBOD Bench Sheets TSS Bench Sheets

pH Bench Sheets

- S 1. The laboratory practices and protocol reviewed were adequate, including:
 - a. A written laboratory QA/QC manual was available.
 - b. Samples were found to be properly stored.
 - c. Approved analytical methods were found to be used.
 - d. Calibration and maintenance of instruments was found to be adequate.
 - e. QA/QC procedures were found to be adequate.
 - f. Dates of analyses (and times where required) were recorded.
 - g. Name of person performing analyses was recorded.
 - 2. Review of lab records and/or on-site field testing equipment and protocols was found to be adequate.

Ν

Comments:

Review of the Hach DR 3900 Ammonia-Nitrogen and Phosphorus analysis unit indicated that the data log was turned off. The data log was turned on during the inspection, and it was also verified that the Phosphorus analysis was set to the proper Phosphorus setting.

Cursory review of recent bench sheets showed no significant issues.

Records/Reports:

The following records/reports were reviewed:

DMRs for the period of March 2024 to May 2024 were reviewed as part of the inspection.

Comments

The requested records were available and appeared to be complete and accurate. Copies of DMRs and MROs were available at the facility.

Enforcement:

Comments:

N/A

Effluent Limits Compliance:

Yes 1. Were DMRs reviewed as part of the inspection?

DMRs for the period of March 2024 to May 2024 were reviewed as part of the inspection.

No 2. Were violations noted during the review of DMRs?

Comments:

No violations were noted on DMRs reviewed for this inspection.

	IDEM REPRESENTATIVE		
nspector Name: Andy Schmidt	Email:	Phone Number: 317-691-1905	
Other staff participating in the inspection:	atschmid@idem.IN.gov	317-091-1903	
Name(s)	Phone Number(s)		
Jeremy Waite	jwaite@idem.in.gov		
Porfirio Ascencio	pascenci@idem.in.gov		
	IDEM MANAGER REVIEW		
DEM Manager:		Date:	
Kim Rohr		6/27/2024	