

**INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT
OFFICE OF AIR QUALITY
FIELD INSPECTION REPORT**



SOURCE INFORMATION	
<u>SOURCE NAME</u>	Co-Alliance – Scircleville Elevator
<u>SOURCE LOCATION</u>	16 South 1100 East Frankfort, IN 46041 Clinton County
<u>MAILING ADDRESS</u>	NA
<u>PLANT ID</u>	023-00019
<u>PERMIT INFORMATION</u>	Permit Type: Permit By Rule Permit Number: Permit Expiration Date: VFC Document No.(hyperlink):
<u>ATTAINMENT STATUS</u>	<input checked="" type="checkbox"/> Attainment for all criteria pollutants <input type="checkbox"/> Nonattainment for <input type="checkbox"/> SO ₂ <input type="checkbox"/> CO <input type="checkbox"/> O ₃ <input type="checkbox"/> NO ₂ <input type="checkbox"/> Pb <input type="checkbox"/> PM ₁₀ <input type="checkbox"/> PM _{2.5}
<u>SOURCE STATUS</u>	<input type="checkbox"/> PSD Major (326 IAC 2-2) <input type="checkbox"/> Major Source of HAPs <input type="checkbox"/> Emission Offset (326 IAC 2-3) <input type="checkbox"/> Area Source of HAPs <input type="checkbox"/> Acid Rain (326 IAC 21)
<u>SOURCE DESCRIPTION</u>	Grain Elevator

INSPECTION INFORMATION			
<u>INSPECTED BY</u>	Rebecca Hayes		
<u>INSPECTION DATE AND TIME</u>	10/21/2020	TIME IN: 11 am	TIME OUT: 12 noon
<u>REPORTED BY</u>	Rebecca Hayes	REPORT DATE: 10/27/2020	
<u>COMPLIANCE PERIOD REVIEWED</u>	10/21/2020		
<u>INSPECTION NOTIFICATION</u>	<input checked="" type="checkbox"/> Unannounced <input type="checkbox"/> Announced:		
<u>INSPECTION OBJECTIVE(S)</u>	<input type="checkbox"/> Compliance Monitoring Strategy (CMS) <input type="checkbox"/> Commitment <input type="checkbox"/> Mega-Site: <input type="checkbox"/> FCE <input type="checkbox"/> PCE <input checked="" type="checkbox"/> Complaint <input type="checkbox"/> Other: <input checked="" type="checkbox"/> Surveillance		
<u>ACES TRACKING NUMBER(S)</u>	Inspection: 252085	Complaint:	Violation/Warning:
<u>RM TRACKING NUMBER(S)</u>	Complaint: 251906		
<u>INSPECTION BACKGROUND</u>	<p>IDEM received a complaint on 10/20/2020 concerning fugitive dust related to the grain elevator in Scircleville. The complainant claimed that the concrete pad for overflow grain storage when the bins fill up was not being tarped due to a rip in the material. Therefore, causing nearby homes to be inundated with fugitive dust.</p>		

SOURCE PERSONNEL INTERVIEWED			
<i>Name</i>	<i>Title</i>	<i>Phone Number</i>	<i>Email Address</i>
NA			

INSPECTION AND COMPLAINT HISTORY (PREVIOUS 5 YEARS)			
<i>Date</i>	<i>Inspection/Complaint Type</i>	<i>Result</i>	<i>Comments</i>
11/13/2017	COMPLAINT	No Violations Noted	
12/7/2016	COMPLAINT	No Violations Noted	
5/17/2016	COMPLAINT	No Violations Noted	

COMPLIANCE HISTORY (PREVIOUS 5 YEARS)			
Informal Enforcement Actions			
<i>Date Issued</i>	<i>Action Taken</i>	<i>Describe Violation(s)</i>	
	N/A		
Formal Enforcement Actions			
<i>Case Number</i>	<i>Enforcement Type</i>	<i>Civil Penalty</i>	<i>Describe Violation(s)</i>
	N/A	\$	
Other Relevant Actions			
<i>Action Taken</i>	<i>Comments</i>		

INSPECTION FINDINGS					
Observations and Comments:					
<p>During the surveillance, I observed semitrucks entering the property and unloading grain in the covered dump pit (see photo No. 3). Also I observed the overflow grain storage area to ensure that the grain was being tarped appropriately to prevent fugitive dust. The area was tarped and the tarp appeared to be in good condition and covering the storage pile appropriately (see Photo No. 1). No fugitive dust was observed from any of the processes operating during the surveillance.</p>					
Compliance Status:					
<input checked="" type="checkbox"/> No violations were observed or determined at the time of the inspection. <input type="checkbox"/> The following violations were determined at the time of the inspection: <table border="1" style="margin-left: 20px;"> <thead> <tr> <th><i>Condition/Citation</i></th> <th><i>Comments</i></th> </tr> </thead> <tbody> <tr> <td></td> <td></td> </tr> </tbody> </table>		<i>Condition/Citation</i>	<i>Comments</i>		
<i>Condition/Citation</i>	<i>Comments</i>				
RECOMMENDED ACTION	Closing Complaint ACES No. 251906				
EXIT INTERVIEW	NA				

SUPPORTING DOCUMENTATION

Photo No. 1



Source Name:	Co-Alliance – Scircleville Elevator
Photographer:	Rebecca Hayes, IDEM, Office of Air Quality
Date and Time:	10/21/2020 at 11:00 am
Description:	Photo taken from the road frontage at the overflow grain storage area

Photo No. 2



Source Name:	Co-Alliance – Scircleville Elevator
Photographer:	Rebecca Hayes, IDEM, Office of Air Quality
Date and Time:	10/21/2020 at 11:00 am
Description:	Photo taken from the road frontage at the main grain storage silo area

Photo No. 3



Source Name:	Co-Alliance – Scircleville Elevator
Photographer:	Rebecca Hayes, IDEM, Office of Air Quality
Date and Time:	10/21/2020 at 11:00 am
Description:	Photo taken from the road frontage at the grain receiving area