

Masterwear  
INN 000508678

EPA REGION 5  
Monthly Projection Form- Site Assessment/Brownfields- STATES

FAX THIS COMPLETED FORM TO HOWARD PHAM AT US EPA  
by Noon the Tuesday prior to sampling @ (312)-886-0186 or E-MAIL at pham.howard@epa.gov

Site Name/City, State MasterWear, Martinsville, IN

CERCLIS ID INN000508678 Site/Spill ID(if applicable) \_\_\_\_\_

Sampling Plan Submittal Date \_\_\_\_\_ - or- Sampling Plan Approval Date \_\_\_\_\_

Site Assessment Type (IA/SI, ESI, U.S. EPA, SIP, etc.) IA - OR- Brownfield Assessment \_\_\_\_\_

Sampling Date(s) November, 2003

Sampler Name/Organization Bill Giles, IDEM

Email Address for electronic data receipt: bgiles@dem.state.in.us

Sampler Phone# 317/234-0345 Sampler Fax # R 317/234-0428

Please check all applicable requests: 7-day CLP \_\_\_\_\_, 14-day CLP \_\_\_\_\_, 21-day CLP , CRL (30 days) \_\_\_\_\_, CLP-  
CADRE Data Review TA Time: \_\_\_\_\_ Level I, \_\_\_\_\_ Level II,  Level III. (See QAPP for Rqmts.)

Analysis Required (e.g., CLP VOA-MeOH, CLP VOA-EnCore, CLP-SVOC-OLM, CLP-Pest/PCB-OLM, CLP VOA-OLM, CLP VOA-OLC, CLP SVOC-OLC, CLP Pest/PCB-OLC, CLP METALS & CN, CRL Metals/CN (res.well), etc.)	Matrix (soil, groundwater, surface water, sediment, drinking water, etc.)	Number of Samples (per matrix)
<u>CLP VOA-OLM</u>	<u>Ground Water</u>	<u>15 80 53</u>

\* ALL SAS WORK Scheduled through the Region REQUIRES 3-4 weeks lead time, and an approved SAS client request form All work to be scheduled must be included in an approved QAPP and sampling plan.

**NOTIFY THE FOLLOWING PERSONS PRIOR to SHIPMENT, FOR CONFIRMATION**

- CLP- RAS -Kelly Falconi, Dyncorp, (703)264-9348
- SAS - (If Scheduled through Region) - Howard Pham (312) 353-2310
- CRL- Bill Sargent- U.S. EPA - (312) 353-9083

Sampling Coordinator(signature/date) \_\_\_\_\_

