



INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

We Protect Hoosiers and Our Environment.

100 N. Senate Avenue • Indianapolis, IN 46204

(800) 451-6027 • (317) 232-8603 • www.idem.IN.gov

Eric J. Holcomb
Governor

Brian C. Rockensuess
Commissioner

April 9, 2024

Singh Balbir
908 Wellington Ct
Canton, MI 48187

Hudson's Oil Company, Inc.
Attn: Nirjodh Singh Chahal
Via email: jodhsingh58@gmail.com

Re: Violation Letter
Hudson Clark
6669 Melton Rd
Portage, Porter County
UST Facility ID # **11401**

Dear Messrs. Balbir and Chahal:

An inspector from the Indiana Department of Environmental Management (IDEM), Underground Storage Tank (UST) Section, conducted an inspection of the site referenced above on March 25, 2024.

The inspection was conducted pursuant to Indiana Code (IC) 13-14-2-2 to determine compliance with the provisions of IC 13-23 and 329 IAC 9. In accordance with IC 13-14-5, a summary of the inspection is provided below:

Type of Inspection: [REDACTED]

Results of Inspection: Violations were discovered and require a submittal.

Within thirty (30) days of receipt of this letter, documentation demonstrating compliance with each of the requirements listed in the attached Inspection Report and Description of Violations (DOV) must be submitted to IDEM. Failure to submit this documentation may lead to this facility being referred for enforcement.

An enforcement action may include civil penalties of up to \$10,000 per UST. Enforcement actions may also affect the owner's and/or operator's eligibility for reimbursement from the Excess Liability Trust Fund (ELTF). Additionally, IDEM may deem the USTs at this facility ineligible for delivery, deposit or acceptance of regulated substances pursuant to IC 13-23-1-4. Finally, federal and criminal penalties may apply for failure to provide required notification; or submitting false information pursuant to IC 13-23-14-2 and liable under IC 13-30-10.


Thank you for your attention to this matter. Please submit the required documents to the UST Section via email at USTCompliance@idem.in.gov. Include in the subject line of the response the UST Facility ID # **11401**.

Inspector: Todd Settles
Phone: (219) 314-1653

Direct any questions regarding the inspection to:

Compliance Manager: Carrie Maniet
Phone: (317) 233-3533

Sincerely,



Thomas F. Newcomb, Chief
UST Compliance Section
Office of Land Quality

cc: Carrie Maniet
Todd Settles
UST Facility ID File # 11401

DESCRIPTION OF VIOLATIONS

This inspection or records review revealed that the owner and/or operator of this facility is in violation of Indiana UST Rule 329 IAC 9. 329 Indiana Administrative Code ("IAC") 9 incorporates certain federal underground storage tank requirements found in 40 Code of Federal Regulations ("CFR") Part 280, including those identified below. The Description of Violations (DOV) and corrective measures are as follows:

FACILITY NAME: Hudson Clark

UST FACILITY ID: 11401

ADDRESS: 6669 Melton Rd
Portage, IN 46368

INSPECTION DATE: 3/25/2024

VIOLATIONS NOTED IN THIS INSPECTION

Citation:

Pursuant to 329 IAC 9-2-2(c), an owner required to submit a notification under this section shall provide:

- (1) a notification for each UST owned;
- (2) complete information required on the form for each UST owned; and
- (3) if applicable, a separate notification form for each separate place of operation at which the USTs are located.

Violation Details:

The owner and/or operator of the UST system(s) at this site are in violation of this rule because an updated Notification Form is needed to update owner information.

Corrective Action:

The owner and/or operator of the UST systems at this site shall fill out and submit to IDEM a correct and complete copy of the appropriate state form with required attachments, within fifteen (15) days of receipt of this notice.

Description of Violations

UST Fac ID:11401

Page 2

Citation:
Pursuant to 40 CFR 280.41(a)(1), considering previous Indiana rule at 329 IAC 9-3-1.3 (repealed 2018), tanks installed on or before September 2, 2009 must be monitored for releases at least every 30 days using one of the methods listed in § 280.43(d) through (i).
Violation Details:
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because twelve (12) months of UST release detection records were not provided.</i>
Corrective Action:
The owner and/or operator of the UST systems at this site shall have any UST or line that contains a regulated amount of product and found to not have been monitored every thirty (30) days tightness tested within thirty (30) days of receipt of this notice and submit the results within forty five (45) days of receipt of this notice. The owner and/or operator shall continue to perform proper monthly release detection and submit the results monthly for a period of six (6) months after the receipt of this notice.

Citation:
Pursuant to 40 CFR 280.41(b)(1)(i)(B), pressurized underground piping installed on or before April 11, 2016 (previously cited as September 2, 2009 under 329 IAC 9-2-1(2)(D)) that routinely contains regulated substances must have an annual line tightness test conducted in accordance with § 280.44(b) or have monthly monitoring conducted in accordance with § 280.44(c).
Violation Details:
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because line tightness test or twelve (12) months of release detection records.</i>
Corrective Action:
The owner and/or operator of the UST systems at this site shall have any piping that contains a regulated amount of product and found to not have had appropriate monthly monitoring or an annual line tightness test within the 12 months prior to inspection tightness tested within thirty (30) days of receipt of this notice and submit the results within forty five (45) days of receipt of this notice.

Citation:
Pursuant to 40 CFR 280.40(a)(3)(iii), owners and operators of UST systems must provide a method, or combination of methods, of release detection that beginning on October 13, 2018, is operated and maintained, and electronic and mechanical components are tested for proper operation, in accordance with one of the following: manufacturer's instructions; a code of practice developed by a nationally recognized association or independent testing laboratory; or requirements determined by the implementing agency to be no less protective of human health and the environment than the two options listed in paragraphs (a)(1) and (2) of this section. A test of the proper operation must be performed at least annually and, at a minimum, as applicable to the facility, cover the following components and criteria: (iii) Automatic line leak detector: test operation to meet criteria in § 280.44(a) by simulating a leak.
Violation Details:
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because leak detector testing was not provided.</i>
Corrective Action:
The owner and/or operator of the UST systems at this site shall have the automatic line leak detectors tested for proper operation by simulating a leak within thirty (30) days of receipt of this notice and submit the results within forty five (45) days of receipt of this notice.

Citation:
Pursuant to 40 CFR 280.35(a)(2), overfill prevention equipment must be inspected at least once every three years. At a minimum, the inspection must ensure that overfill prevention equipment is set to activate at the correct level specified in § 280.20(c) and will activate when regulated substance reaches that level. Inspections must be conducted in accordance with one of the criteria in paragraph (a)(1)(ii)(A) through (C) of this section.
Violation Details:
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because overfill testing was not provided.</i>
Corrective Action:
The owner and/or operator of the UST systems at this site shall, within thirty (30) days of receipt of this notice, contract with a certified contractor to inspect, repair and test all overfill prevention equipment. Documentation, to include photographs, inspection, repair, measurements and testing results, showing the overfill prevention equipment is fully functional and set at the correct level must be submitted within forty five (45) days of the receipt of this notice.

Citation:
Pursuant to 40 CFR 280.35(a)(1), owners and operators of UST systems with spill and overfill prevention equipment and containment sumps used for interstitial monitoring of piping must meet these requirements to ensure the equipment is operating properly and will prevent releases to the environment: (1) Spill prevention equipment (such as a catchment basin, spill bucket, or other spill containment device) and containment sumps used for interstitial monitoring of piping must prevent releases to the environment.
Violation Details:
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because spill bucket testing was not provided.</i>
Corrective Action:
The owner and/or operator of the UST systems at this site shall, within thirty (30) days of receipt of this notice, contract with a certified contractor to inspect, repair and test all spill prevention equipment and containment sumps. Documentation, to include photographs, inspection, repair and testing results, showing the spill prevention equipment and containment sumps are liquid tight must be submitted within forty five (45) days of the receipt of this notice.

Citation:
Pursuant to 40 CFR 280.36(a)(1)(i), to properly operate and maintain UST systems, not later than June 28, 2021, owners and operators must conduct a walkthrough inspection every 30 days that, at a minimum, checks spill prevention equipment and release detection equipment (Exception: spill prevention equipment at UST systems receiving deliveries at intervals greater than every 30 days may be checked prior to each delivery).
Violation Details:
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because monthly walkthroughs were not provided.</i>
Corrective Action:
The owner and/or operator of the UST systems at this site shall, within seven (7) days of receipt of this notice, perform the 30 day walkthrough inspection for all UST systems at the site in accordance with a standard of practice referenced in the rule. Documentation, to include photographs, inspection forms, repair documents, and waste disposal records, showing the walkthrough inspection has been completed must be submitted within forty five (45) days of the receipt of this notice.

Citation:
Pursuant to 40 CFR 280.36(a)(1)(ii), to properly operate and maintain UST systems, not later than June 28, 2021 owners and operators must conduct a walkthrough inspection annually that, at a minimum, checks containment sumps and hand held release detection equipment.
Violation Details:
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because an annual walkthrough was not provided.</i>
Corrective Action:
The owner and/or operator of the UST systems at this site shall, within seven (7) days of receipt of this notice, perform the annual walkthrough inspection for all UST systems at the site in accordance with a standard of practice referenced in the rule. Documentation, to include photographs, inspection forms, repair documents, and waste disposal records, showing the walkthrough inspection has been completed must be submitted within forty five (45) days of the receipt of this notice.

Citation:
Pursuant to 40 CFR 280.245, owners and operators of underground storage tank systems must maintain a list of designated Class A, Class B, and Class C operators and maintain records verifying that training and retraining, as applicable, have been completed, in accordance with § 280.34.
Violation Details:
<i>The owner and/or operator of the UST system(s) at this site are in violation of this rule because operator training certificates A, B, C were not provided.</i>
Corrective Action:
The owner or operator of the UST systems at this site shall submit a list of those employees designated to be Class A, Class B and Class C operators. Those so designated must be trained and certification of that training submitted within thirty (30) days of receipt of this notice.

**UNDERGROUND STORAGE
TANK INSPECTION REPORT**

INDIANA DEPARTMENT OF
ENVIRONMENTAL MANAGEMENT

UST FAC ID:

Inspector's Name:	<input type="text"/>
Date:	<input type="text"/>
Time In:	<input type="text"/>
Time Out:	<input type="text"/>
Inspection Type:	<input type="text"/>

FACILITY NAME / LOCATION				
FACILITY NAME		FACILITY ADDRESS (number and street)		
ADDRESS (line 2)	CITY	STATE	ZIP CODE	COUNTY

UST OWNER				
				BUSINESS ID (From the Secretary of State)
PREFIX	FIRST NAME	MI	LAST NAME	SUFFIX
TELEPHONE NUMBER	EMAIL ADDRESS			

UST OPERATOR				
				BUSINESS ID (From the Secretary of State)
PREFIX	FIRST NAME	MI	LAST NAME	SUFFIX
TELEPHONE NUMBER	EMAIL ADDRESS			

PROPERTY OWNER				
				BUSINESS ID (From the Secretary of State)
PREFIX	FIRST NAME	MI	LAST NAME	SUFFIX
TELEPHONE NUMBER	EMAIL ADDRESS			

COMPLIANCE ELEMENTS							
All USTs properly registered and up-to-date notification form on file	<input type="checkbox"/>	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	UNK	
O/O is in compliance with reporting & record keeping requirements	<input type="checkbox"/>	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	UNK	
O/O is in compliance with release reporting or investigation	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	N/A	UNK
O/O is in compliance with all UST closure requirements	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	N/A	UNK
O/O has met all financial responsibility requirements	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	N/A	UNK
40 CFR 280, Subpart A installation requirements (partially excluded) met	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	N/A	UNK
40 CFR 280, Subpart B installation and upgrade requirements met	<input checked="" type="checkbox"/>	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>		UNK
40 CFR 280, Subpart C spill/overfill control requirements met	<input checked="" type="checkbox"/>	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	N/A	UNK
40 CFR 280, Subpart C compatibility requirements met	<input checked="" type="checkbox"/>	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	N/A	UNK
40 CFR 280, Subpart C O&M and testing requirements met	<input type="checkbox"/>	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>		UNK
40 CFR 280, Subpart D release detection requirements met	<input type="checkbox"/>	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>		UNK
40 CFR 280, Subpart J operator training requirements met	<input type="checkbox"/>	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>		UNK

The information contained on this page is based upon a review of files related to this site and/or observations from an underground storage tank inspector. This page may contain information not specifically related to possible violations found during the review or inspection and is meant to give the owners and/or operator specific information to assist them.

[Empty rectangular area for compliance review and comments]

The information contained on this page is based upon a review of files related to this site and/or observations from an underground storage tank inspector. This page may contain information not specifically related to possible violations found during the review or inspection and is meant to give the owners and/or operator specific information to assist them.

[Empty box for compliance review and comments]