

FACILITY ID # 3522		FACILITY NAME Speedway #7553			
IDEM UST REGISTRATION NUMBER		7	8	9	
COMPARTMENT IDENTIFICATION NUMBER					
T	UNDERGROUND STORAGE TANK RELEASE DETECTION				
PRIMARY UST RELEASE DETECTION					
MANUFACTURER					
MODEL					
SECONDARY UST RELEASE DETECTION					
MANUFACTURER					
MODEL					
U	UNDERGROUND PIPING RELEASE DETECTION				
PRIMARY PIPING RELEASE DETECTION					
MANUFACTURER					
MODEL					
SECONDARY PIPING RELEASE DETECTION (LEAK DETECTOR REQUIRED FOR PRESSURIZED PIPING)					
MANUFACTURER					
MODEL					
TERTIARY PIPING RELEASE DETECTION					
MANUFACTURER					
MODEL					
V	SPILL AND OVERFILL PREVENTION EQUIPMENT				
CATCHMENT BASIN / SPILL BUCKET					
(mm/dd/yyyy) DATE INSTALLED					
MANUFACTURER					
MODEL					
FILL LATITUDE					
FILL LONGITUDE					
PRIMARY OVERFILL PREVENTION EQUIPMENT		Auto Shutoff / Flapp	Auto Shutoff / Flapp	Auto Shutoff / Flapp	
(mm/dd/yyyy) DATE INSTALLED					
MANUFACTURER					
MODEL					
% ULLAGE SET POINT		95	95	95	
SECONDARY OVERFILL PREVENTION EQUIPMENT					
(mm/dd/yyyy) DATE INSTALLED					
MANUFACTURER					
MODEL					
% ULLAGE SET POINT					
UNDER DISPENSER CONTAINMENT PRESENT					
MANUFACTURER					
(mm/dd/yyyy) DATE INSTALLED					
SUBMERSIBLE TURBINE SUMP PRESENT					
MANUFACTURER					
(mm/dd/yyyy) DATE INSTALLED					

Kreegar, Cynthia

From: Rice, Andrew Nicholas (Andrew) <Andrew.Rice@7-11.com>
Sent: Tuesday, June 18, 2024 11:37 AM
To: IDEM USTCompliance (USTcompliance); IDEM USTregistration
Cc: Ware, Jordan M; Byrne, Michael B (Michael)
Subject: UST FID 3522- Speedway #7553 Interim Response Letter 06-18-2024
Attachments: 7553 Section V Update- Overfill 06-18-2024.pdf

**** This is an EXTERNAL email. Exercise caution. DO NOT open attachments or click links from unknown senders or unexpected email. ****

Hi Jordan,

Please accept the NF with updated Section V for the overfill type at Speedway #7553.

The associated WOs have been dispatched to address the following AOCs:

WO 1107347297
fluid in RUL spill bucket

WO 1107347199
fluid in #1/2 UDC sump

WO 1107347351
piping boots damaged under #1/2, 5/6 and #7/8

Andrew N. Rice

Region Gas & Environmental Compliance Specialist – IN & MI
500 Speedway Drive, Enon, OH 45323
M: 937.521.9797 | Andrew.Rice@7-11.com



From: IDEM USTCompliance (USTcompliance) <USTCompliance@idem.IN.gov>
Sent: Monday, June 10, 2024 12:58 PM
To: Byrne, Michael B (Michael) <Michael.Byrne@7-11.com>; Rice, Andrew Nicholas (Andrew) <Andrew.Rice@7-11.com>
Cc: Ware, Jordan M <JMWare@idem.IN.gov>
Subject: Violation Letter, FID 3522

See attached UST correspondence.



UST Compliance Section
Petroleum Branch | Office of Land Quality
Indiana Department of Environmental Management
