



Indiana Department of Environmental Management Emergency Response Incident Report

Description

Incident # 112111

Incident Description: Oil sheen on private storm water retention pond.

Incident Type: Emergency Response-Reportable Spill

Occurred Date/Time: 04/23/2024 12:00 am

Regulatory Program: Emergency Response

Incident Priority: 3-Low

Incident Status: Closed

Closure Method: Referred Outside IDEM

Lead Investigator: Smith, Brian

Resolution Desc: MCHD Emme Lohr conducted an on-site investigation 4-23-24. She updated OSC Smith that she deployed an absorbent boom at the pond outfall and that she would recover it after a couple rain events. She described the sheen as a slight sheen and expected it to evaporate. Source unknown, but suspected it was a minor, acute release.

Other Substance: rainbow colored sheen

Media Impacted: Surface Water

Location

Location Description: pond located on west side of 642 Danver Lane
Beech Grove/Marion Co

County: Marion

Latitude DD: 39.710791

Longitude DD: -86.09779

Method: Interpolation-Map

System: Lat.\Long - Decimal Degrees

Datum: NAD83

Collected By: IDEM Staff

Source Entity

Source Type: Non-Agency Interest

Source Entity Name: unknown



Indiana Department of Environmental Management Emergency Response Incident Report

Reporter

Received By: Smith, Brian

Received Date/Time: 04/23/2024 5:19:32 pm

Receipt Method: Emergency Response Hotline

Reporter Type: Private Citizen

Name: Robert McNevin

Title: citizen

Organization: citizen

Address 1: 642 Danver Lane

Municipality: Beech Grove

State: IN

Comments: Caller reported what appears to be a petroleum sheen on a pond that has an outfall to Lick Creek.

Telecom: Cellular phone number 1 317-438-2512

Actions

Task	Staff Assigned	Start Date	Due Date	Completed Date	Hours Spent
Complete Emergency Response	Smith, Brian			04/23/2024	
Lead ER Staff	Smith, Brian			04/23/2024	