

LEVEL 2 ASSESSMENT - TRANSIENT PUBLIC WATER SYSTEM

State Form 55983 (R5 / 12-20) Indiana Department of Environmental Management Office of Water Quality – Drinking Water Branch

Mail, e-mail, or fax this form and supporting documents to: INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT DRINKING WATER BRANCH

100 North Senate Avenue, Room N1201 Indianapolis, IN 46204 E-mail: CapCert 2 idem in gov

INSTRUCTIONS A Certified Level 2 Assessors or agent of the State must complete this form. The goal of this assessment is to resolve this system's total coliform contamination. The assessor will provide a determination of the cause of this total coliform contamination by checking "Yes" on the appropriate checkboxes below. With each issue checked "Yes", the assessor will follow with a narrative in the "Issue Description" AND "Corrective Action" columns. If any question or section does not apply, simply strike through or mark as N/A. The system representative listed below is responsible for implementing the corrective actions identified within thirty (30) days of this assessment and will provide documentation (photos or receipts) of the corrective actions to IDEM at CapCert@jdem.in.gov.

Public Water System Identification (PWSID) number 2110833 Name of system representative Chet Coo	prider	New Hope Raphst Church How representative is a filiated with the system Samples		
1. SAMPLING SITES	Issue(s) Found?	Description of Issue	Corrective Action(s)	
Unclean, leaking, damaged or unsuitable tap	☐ Yes ÞØNo			
Changed sampling location	☐ Yes 🎾 No			
Unapproved or unsuitable sampling location	☐ Yes 🎾 No			
Low / inadequate disinfection residual	☐ Yes ☐ No			
Plumbing changes or additions	☐ Yes і XONo			
Plumbing breaks or failure	☐ Yes (XDNo			
Cross connection adjacent sampling site (such as, but not limited to, reverse osmosis unit)	☐ Yes 🎞 No			
Untested backflow device(s) adjacent sample site	☐ Yes (\$PNo			
Other	☐ Yes ☐ No			
2. SAMPLING PROTOCOL	Issue(s) Found?	Description of Issue	Corrective Action(s)	
Tap wasn't flushed (prior to sampling)	☐ Yes 🎾 No	Too was disinferted	Lorger Cartact time	
Tap wasn't disinfected (prior to sampling)	Yes No	Tap was disinfected but pillow for longer	for disinfectant.	
Aerator or screen damaged or corroded	☐ Yes 💆 No	Contact time	Attempt to get disintectant	
	-		further into the fauce	

D. M. W. L. C			
Public Water System Identification (PWSID) number 240833		Name of system Hope F	aptist Church
2. SAMPLING PROTOCOL (continued)	Issue(s) Found?	Description of Issue	Corrective Action(s)
Old sample bottle	☐ Yes 🆄 No		
Bottle seal broken	☐ Yes 🕅 No		
New person collected water sample	☐ Yes 🎾 No		
Sampling error	☐ Yes 🎾 No		
Improper hold time	☐ Yes 🏚 No		
Improper storage temperature	☐ Yes ☑ No		
Other	☐ Yes ☐ No		
3. OPERATIONAL CHANGES	Issue(s) Found?	Description of Issue	Corrective Action(s)
New sample tap installed	☐ Yes 🖾 No		
New treatment device added	☐ Yes 🔯 No		
Source added	☐ Yes 🛱 No		
Source abandoned	☐ Yes 🎾 No		
New storage tank added	☐ Yes ØNo		
Visible indicators of unsanitary conditions	☐ Yes 🌠 No		
Recent repairs to water lines	☐ Yes 【\$PNo		
Water system was NOT disinfected / flushed following plumbing construction or repairs	☐ Yes ØNo	hell power turned of between Sundays	- keep well power
Loss of power	Ø∕es □ No	between Sundays	on at all times
Other	☐ Yes ☐ No	O O	

Building did not have power at time of inspection, age 2 of ue to recent severe weather

0.46-00-0			
Public Water System Identification (PWSID) number 2 11 0833		Name of system New Hope	Baptist Church
4. DISTRIBUTION SYSTEM	Issue(s) Found?	Description of Issue	Corrective Action(s)
Low flow / dead end main	□ Yes (\$\time{Q}\time		
Low disinfection residuals (if applicable) review systems records, sample (if needed)	☐ Yes ☐¶010		
Water line breaks	□ Yes (\$\text{\$\text{Q}}\text{No}		
Loss of pressure or low pressure (less than 20 psi)	Øres □ No	- Well turned off	
Water leaks	☐ Yes ☑No		
Construction or installation of plumbing	☐ Yes X No		
Cross connection issue(s) including but not limited to softener waste lines, irrigation, boiler make-up, baptismal, fire suppression, mop sinks, manufacturing process systems	☐ Yes 🌠 No		
Untested backflow device(s)	☐ Yes (XONo		
Inadequate flushing of water lines due to inactivity or closure of the facility	☐ Yes 🎾 No		
Evidence of vandalism	☐ Yes ØNo		
Other:	☐ Yes ☐ No		
5. TREATMENT ONA	Issue(s) Found?	Description of Issue	Corrective Action(s)
Treatment device malfunctioning	☐ Yes ☐ No		
Treatment added or changed	☐ Yes ☐ No		
Cross connection issue(s)	☐ Yes ☐ No		
Inadequate disinfection	☐ Yes ☐ No		
Interruption in treatment / power loss	☐ Yes ☐ No		
Chemical feed rate problems	☐ Yes ☐ No		
Filter contamination	☐ Yes ☐ No		

Public Water System Identification (PWSID)	number		Name of system New Hope	Baptist Church
5. TREATMENT (continued)	WIA	Issue(s) Found?	Description of Issue	Corrective Action(s)
Maintenance schedules not followed	•	☐ Yes ☐ No		
Chemical day tanks empty / inadequate (e.g. softener out of salt)	ly sealed	☐ Yes ☐ No		
Evidence of short circuiting in treatment	process	☐ Yes ☐ No		
Evidence of contamination		☐ Yes ☐ No		
Other.		☐ Yes ☐ No		
6. STORAGE TANK	□ N/A	Issue(s) Found?	Description of Issue	Corrective Action(s)
Tank(s) is damaged, rusty, or has holes	3	Yes No		
Tank bladder(s) is waterlogged		☐ Yes 🗗 No		
Hydropneumatic tank malfunctioning		☐ Yes 🞾 No		
Vent / overflow screen damaged / miss	ing	☐ Yes 🏧 No		
Signs of vandalism / unauthorized acce	ss	☐ Yes ♥ No		
Recent work or repair of tank		☐ Yes ♥ No		
Evidence of contamination		☐ Yes ☐No		
Standing water around tank		☐ Yes 🕅 Yo		
Debris around tank		☐ Yes \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Water age / inadequate turnover		☐ Yes 🎾 No		
Lack of maintenance or inspection		☐ Yes ¥No		
Other		Yes No		

Public Water System Identification (PWSID) number 210833 Name of system Name				
7. SOURCE - WELLS	Issue(s) Found?	Description of Issue	Corrective Action(s)	
Cracked, broken, or missing well cap	☐ Yes ☑No			
Cracked or damaged well casing	☐ Yes X No			
If well casing is cracked, is the protective barrier missing?	☐ Yes ☐ Yo			
Well screen missing or damaged	☐ Yes ☐No			
Missing or damaged grout seal (voids around well allowing contaminates into well)	☐ Yes 🕍 No			
Recent work on pump	☐ Yes 🍎 No			
Well pump cycling improperly	☐ Yes □XONo			
Pump assembly leaking / damaged (jet pump or vertical turbine only)	☐ Yes 😰 No			
Evidence of contamination	☐ Yes 🕅 No			
Flooding or standing water near well	☐ Yes 🎾 No			
Standing water / flooding in well pit	☐ Yes 🏹 No			
Ground slopes toward well casing	☐ Yes X No			
Air relief valve missing screen and / or air gap	☐ Yes 🖟 No			
Other	☐ Yes ☐ No			
CERTIFICATION				
I certify, under penalty of law, that I am a Certified Level 2 Assessor, and that this document was prepared by me or under my direction, and the information submitted is to the best of my knowledge and belief, true, accurate and complete. I am also aware that there are significant penalties for submitting false information.				
Signature Date (month, day, year) (0/27/24				
Programme Renkert Title Field Inspector (IDEM License number(s) (if applicable)				
Teterphone number 7-0070 E-markeddress Cert Diagnain, gov				

Please save a copy of this form and return the original form along with a copy of your training information (including, but not limited to, an Indiana Water Basics Course (INWBC) certificate of completion) to the Indiana Department of Environmental Management. It is important to provide the system representative with a copy of this document. The drinking water system is responsible for completion of all corrective action(s) identified within thirty (30) days of this assessment.

Public Water System Identification (PW	SID) number	Name of system	Hope Baptist	Church
		FOR IDEM USE ONLY	1	
Name if IDEM reviewer			Date of IDEM consultation	i (if needed) (month, day, year)
Document preparer completed INWBC Yes No	Level 2 Assessment accepted Yes No	PWS has corrected the problem Yes No	Corrective Action Plan approved Yes No	Approved with changes Yes No
Comments	•			
K				