



INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

We Protect Hoosiers and Our Environment.

100 N. Senate Avenue • Indianapolis, IN 46204
(800) 451-6027 • (317) 232-8603 • www.idem.IN.gov

Eric J. Holcomb
Governor

Bruno L. Pigott
Commissioner

November 25, 2019

Heritage-Crystal Clean LLC
Brian Recatto, President
2175 Point Blvd, Suite 375
Elgin, Illinois 60123-9211

Business Commercial Registered Agent
Registered Agent for Heritage-Crystal Clean LLC
150 West Market Street, Suite 800
Indianapolis, Indiana 46204

Dear Mr. Recatto:

Re: Close Out Report

Former Warrior Oil Facility
809 Overstreet Street
Franklin, Johnson County
Site Number #0000797

The Indiana Department of Environmental Management (IDEM) is investigating releases of hazardous substances contributing to groundwater contamination located within an area of Franklin, Indiana near the former Amphenol Facility. A facility currently owned by Heritage-Crystal Clean, LLC (Heritage), is located at 809 Overstreet Street, Franklin, Indiana (Property) within the aforementioned area of interest in Franklin, Indiana.

The Property was listed for consideration as a potential source of hazardous substances due to its previous use. The Property was developed circa 1976-1990 as Shell Oil Corp. In 1990 Warrior Oil Services, also known as Warrior Petroleum Processing occupied the Property. In 2010 Heritage completed a Phase I investigation and Phase II investigation on the Former Warrior Oil before completing the purchase of the Property.

An Information Request Letter was sent out on August 2, 2018 to Heritage-Crystal Clean LLC Attention: Brian Recatto, President. This letter was received, and a response was submitted to IDEM on October 1, 2018.

Based on the information available to IDEM, the Property does not appear to be contributing to the chlorinated solvent contamination detected in the groundwater in the surrounding area. Five soil samples were collected, one from 14-16 feet below the ground surface (bgs) (from soil boring (SB)-1), two from 10-12 feet bgs (from SB-2 and SB-3), and two from 2-4 feet bgs (from SB-4 and SB-5). Three grab groundwater samples were collected from the three deepest soil borings/intervals. No volatile organic compounds (VOCs), polyaromatic hydrocarbons (PAHs), or total petroleum hydrocarbons (TPH) were detected in soil samples collected from the deeper intervals. TPH and 1,2,4-trimethylbenzene were detected in SB-4. The groundwater sample

collected from SB-1 detected 1,1-dichloroethane (1,1-DCA), the report suspected the 1,1-DCA to be from an off-site source. The information provided to IDEM shows that the Property is not a source of contamination, nor is there significant contamination moving across the Property from other sources.

If new information becomes available, additional action at the Property may be required.

Sincerely,

A handwritten signature in black ink that reads "Haley Faulds". The signature is written in a cursive style with a long horizontal line extending to the right.

Haley Faulds
State Cleanup Section
Office of Land Quality

HF:sb

cc: IDEM Site #0000797

Lisa McCoy, IDEM OLC Attorney

Philip Comella, Freeborn & Peters LLP

Decina, Anita, Heritage Crystal-Clean Vice President