



**UNDERGROUND STORAGE
TANK INSPECTION REPORT**

INDIANA DEPARTMENT OF
ENVIRONMENTAL MANAGEMENT

UST FAC ID: **7001**

Inspector's Name:	Tristan Voge
Date:	June 26, 2024
Time In:	09:30
Time Out:	10:10
Inspection Type:	Initial


FACILITY NAME / LOCATION				
FACILITY NAME GoLo		FACILITY ADDRESS (number and street) 2040 E Wahsington St		
ADDRESS (line 2)	CITY Indianapolis	STATE IN	ZIP CODE 46201	COUNTY Marion

UST OWNER				
UST Owner Name (If in Individual Capacity) SC Petroleum Inc.			BUSINESS ID (From the Secretary of State) 201801221235371	
PREFIX	FIRST NAME Raj	MI	LAST NAME Kaur Kalkat	SUFFIX
TELEPHONE NUMBER	EMAIL ADDRESS shannasha@yahoo.com			


UST OPERATOR				
UST Operator Name (If in Individual Capacity)			BUSINESS ID (From the Secretary of State)	
PREFIX	FIRST NAME Manjtt	MI	LAST NAME Singh	SUFFIX
TELEPHONE NUMBER	EMAIL ADDRESS shannasha@yahoo.com			

PROPERTY OWNER				
UST Property Owner Name (If in Individual Capacity) SC Petroleum Inc.			BUSINESS ID (From the Secretary of State) 201801221235371	
PREFIX	FIRST NAME Raj	MI	LAST NAME Kaur Kalkat	SUFFIX
TELEPHONE NUMBER	EMAIL ADDRESS shannasha@yahoo.com			

COMPLIANCE ELEMENTS					
All USTs properly registered and up-to-date notification form on file	<input type="checkbox"/>	<input checked="" type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/>	<input type="checkbox"/> UNK
Fees 2015, 2017, 2019 to 2024. An updated notification form is needed with the correct ownership, release detection and system information indicated.					
O/O is in compliance with reporting & record keeping requirements	<input type="checkbox"/>	<input checked="" type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/>	<input type="checkbox"/> UNK
The owner and/or operator did not respond to IDEM's records request dated 05/17/2024.					
O/O is in compliance with release reporting or investigation	<input checked="" type="checkbox"/>	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A	<input type="checkbox"/> UNK
O/O is in compliance with all UST closure requirements	<input checked="" type="checkbox"/>	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A	<input type="checkbox"/> UNK
O/O has met all financial responsibility requirements	<input checked="" type="checkbox"/>	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A	<input type="checkbox"/> UNK
40 CFR 280, Subpart A installation requirements (partially excluded) met	<input type="checkbox"/>	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> N/A	<input type="checkbox"/> UNK
40 CFR 280, Subpart B installation and upgrade requirements met	<input type="checkbox"/>	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/>	<input type="checkbox"/> UNK
The PREM spill bucket was over half filled with fluid and would not function in a spill/overflow.					
40 CFR 280, Subpart C spill/overflow control requirements met	<input checked="" type="checkbox"/>	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A	<input type="checkbox"/> UNK
40 CFR 280, Subpart C compatibility requirements met	<input checked="" type="checkbox"/>	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A	<input type="checkbox"/> UNK
40 CFR 280, Subpart C O&M and testing requirements met	<input type="checkbox"/>	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/>	<input type="checkbox"/> UNK
Spill/overflow test reports and 07/2023-06/2024 monthly/annual walkthroughs were not provided.					
40 CFR 280, Subpart D release detection requirements met	<input type="checkbox"/>	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/>	<input type="checkbox"/> UNK
Annual ATG/probes and line leak detector test reprints were not provided.					
40 CFR 280, Subpart J operator training requirements met	<input type="checkbox"/>	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/>	<input type="checkbox"/> UNK
A, B and C operator certificates were not provided.					



Imagery ©2024 Airbus, Maxar Technologies, Map data ©2024 Google 50 ft



Map data ©2024 , Map data ©2024 Google 20 ft



GoLo



GoLo
3458

GoLo

GoLo

7th Street
E. Broadway St





Person in yellow safety vest and green pants.

Large dark brown manhole cover.

Manhole with blue corrugated liner.

Manhole cover with 'MANNING' text.

Large green manhole cover with a blue tool resting on it.

Small manhole with a copper-colored cap.

Manhole cover with 'VAPOR RECOVERY' text.

Red manhole cover with a circular hole.

Manhole with a red and black frame.

Green traffic cone.

Green traffic cone.


Large green traffic cone.























GoLo

WARNING
STOP
ENGINE
NO
SMOKING

IT IS UNLAWFUL AND DANGEROUS FOR ANYONE TO DISPENSE GASOLINE INTO AN UNAPPROVED CONTAINER.
IT IS UNLAWFUL AND DANGEROUS TO DISPENSE GASOLINE WITHOUT AN ATTENDANT ON DUTY.

16.00
4625 **2**

87 89 93

Regular
Unleaded
Plus
Premium
Unleaded

GoLo
Quality Fuel Lo Price

Hamilton Ave

STOP





GoLo

3

4


GoLo

1000
Gallons 299.1

Unleaded Plus Premium

87 89 93





6

GoLo

WARNING
STOP
ENGINE
NO
SMOKING

IT IS DANGEROUS AND HARMFUL FOR ANYONE TO DISPOSE GASOLINE INTO AN UNAPPROVED CONTAINER.

IT IS UNLAWFUL AND HARMFUL TO DISPENSE GASOLINE WITHOUT AN ATTENDANT ON DUTY.

Gasoline

87 89 93

Regular
Unleaded
Plus
Premium
Unleaded

GoLo
Quality Fuel Lo Price





Card Reader Instructions.
Insert card fully as shown with the magnetic strip facing down and card numbers to the left.

Step 1. Follow instructions on the display to select method of payment.

Step 2. Remove nozzle.

Step 3. Press buttons to select product.

Step 4. Dispense fuel, return nozzle.

Take receipt below

PRICE PER GALLON 2400 3700 4400

87 Push Here

89 Push Here

93 Push Here

Wayne



GoLo
Quality Fuel Lo Price

Store Type: Convenience Store
Location Address: 2040 E Washington St
Indianapolis, IN 46201-4158
County: MARION

Field Office: Indianapolis, IN
Field Office Address: 3101 Park Center Dr
Ste FO -2
Alexandria, VA 22302

are hereby granted approval to accept and redeem SNAP benefits on
struments shall be in accordance with the rules and regulations governing

NOT TRANSFERABLE

eration void this permit. To prevent illegal use, this permit must be
le/transfer of the business or upon request by the FNS. Failure to report
ministrative sanctions. IF THE STORE MOVES, IS SOLD/CLOSED OR
TION ASSISTANCE PROGRAM, PLEASE CONTACT YOUR

Date of Issue: 05/25/2012

REGISTERED RETAIL MERCHANT CERTIFICATE
INDIANA DEPARTMENT OF REVENUE
100 N SENATE AVE
INDIANAPOLIS IN 46204-2253
(317) 232-2240

 INDIANA 1816

INDY GOLO
2040 E WASHINGTON ST
INDIANAPOLIS IN 46201-4158

FEIN 86-1598145
LOC ID 0170899799-001
ISSUED January 22, 2021
EXPIRES February 28, 2023

IS AUTHORIZED TO COLLECT INDIANA RETAIL SALES TAX AT THE
ADDRESS ABOVE IF DIFFERENT FROM BELOW.

THIS LICENSE:
IS NOT TRANSFERABLE TO ANY OTHER PERSON.
IS NOT SUBJECT TO REBATE.
IS VOID IF ALTERED.



INDY SUPER MART INC
2040 E WASHINGTON ST
INDIANAPOLIS IN 46201-4158

Robert J. Jennings
COMMISSIONER

MUST BE DISPLAYED BY MERCHANT IN THE LOCATION SHOWN

INDIANA STATE EGG BOARD
Creighton Hall of Animal Science
Purdue University
WEST LAFAYETTE, INDIANA 47907

RETAIL CERTIFICATE OF REGISTRATION
Non-Transferable No Refund Post in Conspicuous Place

License No. 7827
Expires: June 30, 2021

2020
\$ 30.00

SC Petroleum
2040 E. Washington Street
Indianapolis IN 46201 4158





Indiana Department of Environmental Management
Underground Storage Tank Program
Operator Training Certification

A

Certificate of Completion

Awarded to:
jimmy jessey

For completion of IDEM's Underground Storage Tank "A" Operator Training in accordance with 329 IAC 9.

License #: 4908

Issue Date: March 24, 2013

Expiration Date: March 24, 2016

A handwritten signature in black ink, appearing to read "Tom Easterly".

Thomas W. Easterly, Commissioner

IDEM may require operator retraining if a UST System managed by the operator has documented deficiencies per 329 IAC 9.