ill en Ca





ITT Corporation

Communications Systems 7310 Innovation Blvd. PO Box 731 Tel 260 451 5220 Fax 260 451 5066 mary.hatch@itt.com

July 15, 2008

Indiana Department of Environmental Management Office of Air Quality, Compliance Branch 100 North Senate Avenue Indianapolis, IN 46206-6015

Attention:

Commissioner, Office of Air Quality

Subject:

2nd / 2008 Quarterly Air Report

Reference: CP 003-4713, Pit ID No. 003-00010

Dear Commissioner:

Enclosed is the second quarter 2008 Quarterly Air Report for the air emissions control source covered by Permit No. CP 003-4713, Pit ID No. 003-00010. This equipment is not currently being operated.

The soil vapor extraction remediation system located at the former ITT Aerospace/Communications Division's facility at 3700 east Pontiac Street, Fort Wayne, IN was turned off April 22, 2005. No equipment remains on site. ITT intends to retain this permit in the event that this activity may resume.

If you have questions, do not hesitate to contact me.

Respectfully,

Mary T. Hatch, C.H.M.M.

Environmental Safety & Health Specialist

mary I Hatch

Mail Stop 534

Enclosure (1)

/mth

DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

Office of Air Management Compliance Data Section

Quarterly Report of Monthly VOC Input Usage

Company Name: ITT Aerospace / Communications Division

Location: 3700 E. Pontiac Street, Fort Wayne, Indiana

Permit No.: CP 003- 4713, Pit Id No. 003 - 00010

Facility I. D.: Positive displacement compressors of the soil vapor extraction system

Pollutant: Volatile Organic Compounds (VOC)

Limit: 2.0 tons per month of VOC

Quarter/Year: 2nd / 2008

Month	VOC in tons/month	
April	0.00	
May	0.00	
June	0.00	

Submitted by:	Mary T.	Hatch

Title / Position: <u>Environmental Health & Safety Specialist</u>

Signature: Mary J. Hatch

Date: July 15, 2008