



Indiana Department of Environmental Management

RM Record

Description

Incident # 113538

Received By: Frosch, Scott

Received Date: 07/24/2024 10:02 am

Receipt Method: Emergency Response Hotline

Incident Description: **Exercise, Exercise Exercise**

Tank overfill to secondary containment

Incident Type: Emergency Response-Other

Occurred Date/Time: 07/24/2024 8:00 am

Regulatory Program: Emergency Response

Incident Priority: 2-Medium

Incident Status: Closed

Closure Method: Not Applicable

Lead Investigator: Frosch, Scott

Resolution Desc: EXERCISE

The bulk terminal called their OSRO - SET is en route, additional resources have been dispatched. Nothing has escaped secondary containment (except for what has evaporated into the air).

	Parameter	CAS #	Quantity	Units
Substances/Impacts:	Ethyl benzene	100414		
	Naphthalene	91203		
	Diesel	68334305	50400	gallons

Media Impacted: Secondary Containment Area

Location

Location Description: 1527 141st St
Hammond
Lake County

County: Lake

Municipality: Hammond



Indiana Department of Environmental Management RM Record

Source Entity

Source Type: Agency Interest

Source Entity Name: ExxonMobil Oil Corporation

Address 1: 1527 141st St

Municipality: Hammond

County: Lake

State: IN

Zip Code: 46327

Telecom: Business phone number 1 703-846-6692

Reporter

Reporter Type: Self Reported/Resp Party

Name: Robert

Organization: Exxon Mobil Oil Corporation

State: IN

Comments: DRILL - 1527 141st Hammond St - Tank overfill -Tank 152 - 1200 bbl diesel into 2 containment - no fire no explosion - no evac - dead end public street - RQ ethyl benzene naphthalene.

Telecom: Business phone number 1 (219) 933-6051

Actions

Task	Staff Assigned	Start Date	Due Date	Completed Date	Hours Spent
Lead ER Staff	Frosch, Scott			07/24/2024	
Complete Emergency Response	Frosch, Scott			07/24/2024	