
IN2660016

Pond View Golf Course





Seaso

State Form 55927 (R2 / 9-16)

This checklist must be completed as you start up your system. It will aid in preventing contamination from entering your water system and will help you identify problems with your system. You must complete the following tasks (if applicable), check completion of each task, and mail, fax, or e-mail a signed copy with a copy of the special purpose sample result to the IDEM Drinking Water Branch. Make and keep a copy for your records.

Review Sampling Requirements	Done?
Review sampling schedule available at myweb.in.gov/IDEM/DWW/ or you can call 1(800) 451-6027 ext. 47430	Yes
Make arrangements for sample collection analysis with a certified lab (including SSLAP)	Yes
Review your site sampling plan and make sure it is up to date	Yes
Well(s)	Done?
Well cap is tight and secure	Yes
Pump house is locked and secure	Yes n/a
Well casing is structurally sound and there is no visible damage	Yes
Vent screen is in place and downturned	Yes n/a
Rodents and insects are kept out of any enclosure around the well (e.g. keep area mowed)	Yes
The source or well sample tap* does not leak and flows freely when opened *This is typically a spigot, hose bib, or sample tap located after the well but before the storage tank or any water treatment device	Yes
Contaminant sources such as chemicals, livestock, and fuel are kept at least 100 feet from the well	☑ Yes
Check for evidence of flooding or standing water near the well	Yes
Treatment Equipment	Done?
All components are operating properly and free of corrosion or damage	Yes n/a
ANSI- or NSF-approved water treatment chemicals are on hand	Yes n/a
Storage Tank(s)	Done?
All valves, gauges, and controls are working properly	Yes n/a

System Name POND VIEW G.C.	IN 26600,	16 Date 5/	(month, day, year) 20/20	
Storage Tank(s) CONTINUED			Diome?	
Pressure is being maintained and the pump is cycli (once the system is pressurized)	ng normally		Yes	
Tanks are sealed, not leaking, and in working orde	r		Yes	.18489-0-
For a non-pressurized tank, the vent screen is in pl	lace and downturned		Yes n,	/a
Distribution System			Done?	
All accessible lines and equipment are free of corre	osion, damage, or lea	aks [[./_
All valves open and close freely				1/a
Outdoor spigots or yard hydrants have vacuum bre			Yesn	ı/a
All testable backflow preventers have been tested the last twelve (12) months.	by a certified backflo	w tester in	Yes n	n/a
Activate and Pressurize			Done?	
Well and pump are operating correctly			Yes	
System is fully pressurized (at least 20 psi) and no	ot leaking	e Nice to part Notice Particle and the	Yes	
Water treatment equipment is operating correctly			Yes 🗾	n/a
Disinfect and Flush System			Done?	
System was disinfected			Yes	No
System was flushed		ara esta de la compansión	∠ Yes	
Collected a satisfactory special purpose total colif in the distribution system. Submit results of samp	orm sample from fart le to IDEM.	hest point	Date Collecte	
Keep a copy of this checklist and submit the origin	nal to IDEM.		Yes	
Date system opens for the season: $6/5/3$	20			
Comments (Attach an additional sheet if more sp.	ace is needed.)	,		
OPEINING LATE BECAUSE OF COVIDIA.	WILL CLOSE 10,	131/20,		
I certify, under penalty of law, that this document we me, and that any deficiencies found during this seat inspection have, to the best of my knowledge and becorrected.	as prepared by sonal start-up belief, been	Mail, fax checklist and s Indiana De Environmenta 100 N. Senate Indianapo	epartment of al Managemen	nt

Name

Signature

Date (month, day, year)

Email: CapCert@idem.in.gov