System N IN2441080

IDEM

Lucys Vedie Twist



PWSID 244/080 Date (month, day, year)

## Start-up Requirements

State Form 55927 (R2 / 9-16)

This checklist must be completed as you start up your system. It will aid in preventing contamination from entering your water system and will help you identify problems with your system. You must complete the following tasks (if applicable), check completion of each task, and mail, fax, or e-mail a signed copy with a copy of the special purpose sample result to the IDEM Drinking Water Branch. Make and keep a copy for your records.

Review Sampling Requirements	ID(e)n(e <sup>2</sup> ?
Review sampling schedule available at <a href="myweb.in.gov/IDEM/DWW/">myweb.in.gov/IDEM/DWW/</a> or you can call 1(800) 451-6027 ext. 47430	Yes
Make arrangements for sample collection analysis with a certified lab (including SSLAP)	Yes
Review your site sampling plan and make sure it is up to date	Yes
\W/ell(s)	Dome?
Well cap is tight and secure	Yes
Pump house is locked and secure	Yes n/a
Well casing is structurally sound and there is no visible damage	Yes
Vent screen is in place and downturned	Yes n/a
Rodents and insects are kept out of any enclosure around the well (e.g. keep area mowed)	Yes
The source or well sample tap* does not leak and flows freely when opened *This is typically a spigot, hose bib, or sample tap located after the well but before the storage tank or any water treatment device	Yes
Contaminant sources such as chemicals, livestock, and fuel are kept at least 100 feet from the well	Yes
Check for evidence of flooding or standing water near the well	Yes
Tiresแกกระเกน์ เริดุเมน์อุมกระหาน์	Desire
All components are operating properly and free of corrosion or damage	Yes n/a
ANSI- or NSF-approved water treatment chemicals are on hand	Yes n/a
Stronage Tank(s)	Digitie 2º
All valves, gauges, and controls are working properly	Yes n/a

System Name	PWSID 244/08	Date (mon	th, day, year)
Silonagge Tanik(s) GONTHNUED			Dioline 2
Pressure is being maintained and the pump is cycli (once the system is pressurized)	ng normally		/es
Tanks are sealed, not leaking, and in working orde	r		es /
For a non-pressurized tank, the vent screen is in pl	ace and downturne	ed Y	'es n/a
Distribution System			Novare 2
All accessible lines and equipment are free of corro	sion, damage, or le	eaks 📝 Y	'es
All valves open and close freely		<b>□</b> y	es n/a
Outdoor spigots or yard hydrants have vacuum brea	akers or backflow p	oreventers /Y	es n/a
All testable backflow preventers have been tested be the last twelve (12) months.	y a certified backflo	ow tester in	es n/a
Availvatte and Pressunise		D	rojhtej?/
Well and pump are operating correctly	· .	· ZY	es
System is fully pressurized (at least 20 psi) and not	leaking	Ye	es
Water treatment equipment is operating correctly		Ye	es n/a
IDistinfie of sincol Floreth Systems			olare)2'
System was disinfected		<b>√</b> ye	s No
System was flushed		√ Ye	es.
Collected a satisfactory special purpose total coliform in the distribution system. Submit results of sample to	m sample from fartl to IDEM.	nest point bonf	y/aggo Collected
Keep a copy of this checklist and submit the original	to IDEM.	Ye	 S
identia etalian etalia etalia eta edua proporto (ovid	5/61/2020		
Comments (Attach an additional sheet if more space	is needed.)		
I certify, under penalty of law, that this document was penalty and that any deficiencies found during this season inspection have, to the best of my knowledge and belied corrected.	al start-up cl f, been	Mail, fax, or e-m necklist and sample Indiana Departmer Environmental Manag 100 N. Senate Ave IGC Indianapolis, IN 46 Fax: 317-234-746	result to at of gement CN 1255 204

Signature Date (month, day, year)

Fax: 317-234-7462 Email: <u>CapCert@idem.in.gov</u>