

Indiana Department of Environmental Management
Municipal Solid Waste Landfill Inspection Report

Facility: LAWRENCE COUNTY LANDFILL (Closed) Permit #: 47-2 County: LAWRENCE

Date: March 29, 2010 Time: 12:00 pm Inspected by: Rick Schroeder

271	IC 013-020-009 (02)	065	329 IAC 010-020-008 (a) (02)	094	329 IAC 010-020-016 (b)
270	IC 013-020-014 (01)	066	329 IAC 010-020-008 (a) (03)	095	329 IAC 010-020-016 (c)
021	329 IAC 010-013-004 (c)	067	329 IAC 010-020-008 (b)	096	329 IAC 010-020-016 (d) (01)
038	329 IAC 010-020-001 (a)	068	329 IAC 010-020-009	101	329 IAC 010-020-016 (d) (02)
039	329 IAC 010-020-001 (b)	069	329 IAC 010-020-010 (a)	097	329 IAC 010-020-016 (e)
040	329 IAC 010-020-001 (c)	070	329 IAC 010-020-010 (b)	098	329 IAC 010-020-016 (f)
041	329 IAC 010-020-002 (a)	071	329 IAC 010-020-010 (c)	099	329 IAC 010-020-016 (g)
042	329 IAC 010-020-002 (b)	072	329 IAC 010-020-011 (a) (01)	100	329 IAC 010-020-016 (h)
043	329 IAC 010-020-002 (c)	073	329 IAC 010-020-011 (a) (02)	272	329 IAC 010-020-016 (i)
045	329 IAC 010-020-002 (e)	074	329 IAC 010-020-011 (b)	102	329 IAC 010-020-018 (a)
046	329 IAC 010-020-003	075	329 IAC 010-020-011 (c)	103	329 IAC 010-020-018 (b)
047	329 IAC 010-020-004 (a)	076	329 IAC 010-020-012 (a)	104	329 IAC 010-020-018 (c)
048	329 IAC 010-020-004 (b)	077	329 IAC 010-020-012 (c)	105	329 IAC 010-020-020 (b)
049	329 IAC 010-020-004 (c)	078	329 IAC 010-020-013 (a)	106	329 IAC 010-020-020 (c)
050	329 IAC 010-020-004 (d)	079	329 IAC 010-020-013 (b)	107	329 IAC 010-020-020 (d)
051	329 IAC 010-020-004 (e)	080	329 IAC 010-020-014 (a)	108	329 IAC 010-020-021 (a)
052	329 IAC 010-020-004 (f)	081	329 IAC 010-020-014 (b)	109	329 IAC 010-020-021 (b) (04)
053	329 IAC 010-020-004 (g) (01)	082	329 IAC 010-020-014 (c)	223	329 IAC 010-020-024 (a)
054	329 IAC 010-020-004 (g) (02)	083	329 IAC 010-020-014 (d)	112	329 IAC 010-020-027 (a)
055	329 IAC 010-020-004 (g) (03)	084	329 IAC 010-020-014 (e)	113	329 IAC 010-020-027 (b)
056	329 IAC 010-020-004 (h)	085	329 IAC 010-020-014 (f)	114	329 IAC 010-020-028 (a)
057	329 IAC 010-020-005	086	329 IAC 010-020-014 (g)	115	329 IAC 010-020-028 (b)
058	329 IAC 010-020-006 (a)	087	329 IAC 010-020-014 (h)	116	329 IAC 010-020-028 (c)
059	329 IAC 010-020-006 (b)	088	329 IAC 010-020-015 (b)	117	329 IAC 010-020-029 (a)
060	329 IAC 010-020-007 (a)	089	329 IAC 010-020-015 (c)	118	329 IAC 010-020-029 (b)
061	329 IAC 010-020-007 (b)	090	329 IAC 010-020-015 (d)	119	329 IAC 010-020-031 (01)
062	329 IAC 010-020-007 (c)	091	329 IAC 010-020-015 (e)	120	329 IAC 010-020-031 (02)
063	329 IAC 010-020-007 (d)	092	329 IAC 010-020-015 (f)		
064	329 IAC 010-020-008 (a) (01)	093	329 IAC 010-020-016 (a)		

CIRCLED ITEMS ARE VIOLATIONS OF 329 IAC 10 or IC 13-20 AND MUST BE CORRECTED.

Comments: Today's inspection of this closed landfill finds premises mowed & well maintained. There is a new gun range being constructed on the south end. No problems observed in association with this construction. Graveled parking area adjacent to range. Monitoring wells locked.

Last Inspection Date: Violations at last inspection: N/A

Received by: Marela Ryan