


RM 113098



- Facility
 - Huntington County
- Photographer
 - OSC Caldwell
- Date/Time
 - 6/25/24
- Others Present
 - N/A
- Dead fish in the channel

RM 113098



- Facility
 - Huntington County
- Photographer
 - OSC Caldwell
- Date/Time
 - 6/25/24
- Others Present
 - N/A
- Location of incident

RM 113098



- Facility
 - Huntington County
- Photographer
 - OSC Caldwell
- Date/Time
 - 6/25/24
- Others Present
 - N/A
- DO reading on east side of WWTP

RM 113098



- Facility
 - Huntington County
- Photographer
 - OSC Caldwell
- Date/Time
 - 6/25/24
- Others Present
 - N/A
- Dead fish near the WWTP

RM 113098



- Facility
 - Huntington County
- Photographer
 - OSC Caldwell
- Date/Time
 - 6/25/24
- Others Present
 - N/A
- DO in the water from the inlet

RM 113098



- Facility
 - Huntington County
- Photographer
 - OSC Caldwell
- Date/Time
 - 6/25/24
- Others Present
 - N/A
- WWTP west side. Dark area is a number of minnows in the high oxygenated water

RM 113098



- Facility
 - Huntington County
- Photographer
 - OSC Caldwell
- Date/Time
 - 6/25/24
- Others Present
 - N/A
- Inlet water from the Wabash River

RM 113098



- Facility
 - Huntington County
- Photographer
 - OSC Caldwell
- Date/Time
 - 6/25/24
- Others Present
 - N/A
- View from levee looking into the channel