Caldwell, Dwayne

From:	Kroeger, Margaret
Sent:	Monday, June 10, 2024 3:14 PM
То:	broadwaymotors4675@att.net; zoomersrvindiana@gmail.com
Cc:	Stackhouse, Lynn; Denney, Michelle; McNeil, Tammie; Wade, Ciara; Carter, Charnell;
	VOSS, LEIGH; Caldwell, Dwayne
Subject:	IN0041637 Cocojo's RV Resort WWTP Recon, Wabash Co.
Attachments:	IN0041637 Recon 6-7-24.pdf

The attached document includes a letter and inspection report resulting from a recent inspection by IDEM staff. Please ensure these documents are reviewed by the appropriate individuals. If the letter requires a response, we encourage you to respond via email by sending your response to <u>wwViolationResponse@idem.IN.gov</u>.

Thank you.

Maggie Kroeger IDEM Wastewater Inspector

On behalf of



Kim Rohr Section Chief Wastewater Inspections Office of Water Quality

Office: 317-234-2558 Cell: 317-605-6489 krohr@idem.in.gov

Indiana Department of Environmental Management 100 N. Senate Avenue, Indianapolis, IN 46204 <u>https://www.in.gov/idem/cleanwater/2337.htm</u>

IDEM values your feedback. Please take two minutes and complete this brief survey.





Indiana Department of Environmental Management

We Protect Hoosiers and Our Environment.

100 N. Senate Avenue • Indianapolis, IN 46204 (800) 451-6027 • (317) 232-8603 • www.idem.IN.gov

Eric J. Holcomb Governor Brian Rockensuess Commissioner

June 10, 2024

<u>Via Email to:</u> zoomersrvindiana@gmail.com Mr. Mike Weaver, Owner Cocojo's A Zoomers RV Resort, LLC 2503 E State Road 524 Wabash, Indiana 46992

Dear Mr. Weaver:

Re: Inspection Summary/ Noncompliance Letter Cocojo's RV Resort WWTP

NPDES Permit No. IN0041637 Lagro, Wabash County

An inspection of the above-referenced facility or location was conducted by a representative of the Indiana Department of Environmental Management, Northern Regional Office, pursuant to IC 13-18-3-9. A summary of the inspection is provided below:

Date(s) of Inspection:	June 07, 2024
Type of Inspection:	Reconnaissance Inspection
Inspection Results:	Violations were observed.

The following concerns were noted:

On Tuesday, June 4, 2024 IDEM received a complaint regarding a sewage leak at CocoJo's RV Park. IDEM Emergency Response completed the initial investigation. Other agencies that received this complaint included IDNR and Indiana State Board of Health. On June 6, 2024, this inspector was notified by ISBH that there was some indications that the WWTP did not discharge to the Salamonie Reservoir as indicated in the current permit, but did discharge to a small creek prior to entry into the reservoir. This inspection was completed with IDEM Emergency Response staff to dye test the effluent pipe from the treatment plant in hopes of definitively locating the discharge location.

As noted above, dye testing was conducted at the end of the WWTP. Four high visibility dye tablets were placed in the discharge pipe. Within 10 minutes, the neon green dye was visible in a small creek located down a horseman's path and just to the east of the treatment plant. On both the cover page and page 1 of your NPDES permit, it specifically authorizes discharge from the treatment plant into Salamonie Reservoir and does not authorize any other discharge locations. The treatment plant discharge into the creek prior to the reservoir is a violation of Part II. B. 6 of your permit which states: any overflow or release of sanitary wastewater from the wastewater treatment facilities or

collection system that results in a discharge to waters of the state and is not specifically authorized by this permit is expressly prohibited. These discharges are subject to the reporting requirements in Part II.C.3 of this permit.

In addition, Pursuant to 327 IAC 5-2-8(11)(E), where the permittee becomes aware that it failed to submit any relevant facts or submitted incorrect information in a permit application or in any report to the Commissioner, the permittee shall promptly submit such facts or corrected information to the Commissioner. You must work with the IDEM Municipal Permits staff to modify the permit to accurately reflect the receiving stream. Please reach out to Leigh Voss at LVOSS@idem.IN.gov or by phone at 317-232-8698.

Part II. A. 1. of your permit requires you to comply with its terms and conditions. Any noncompliance with the terms of your permit may subject you to an enforcement action which can include the imposition of penalties. You are required to immediately take all necessary measures to comply with the terms and conditions of your NPDES Permit, specifically those violations identified above.

Within 30 days of receipt of this letter, a written detailed response documenting correction of the concerns listed above and/or a plan for assuring future compliance must be submitted to this office. Failure to respond adequately to this letter may result in formal enforcement action. Please direct your response to this letter to our letterhead address or via email to wwViolationResponse@idem.IN.gov. Any questions should be directed to Lynn Stackhouse at 317-691-0099 or by email to lstack@idem.IN.gov. Thank you for your attention to this matter.

Sincerely,

Jam E. Weingart

James E. Weingart, Director Northern Regional Office

Enclosure



NPDES Wastewater Facility Inspection Report INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

NPDE	S Permit Number:	Facility Type:				Facility Classification:			TEMPO AI ID	
	IN0041637	Mixed Ownership				Minor				54426
Date(s) of Inspection: June 07, 2024										
Туре	e of Inspection: Recor	nnaissance	Inspec	tion						
	e and Location of Facility Inspec	ted:				Receiving Waters:		[it Expiration Date:
	ojo's RV Resort WWTP	TP 9/30/2025						9/30/2025		
	9 East 400 South			ounty:		Salamonie Reservo	oir	1		gn Flow:
Lagr		IN 4694	-1 V	/abash						0.012MGD
	On Site Representative(s): First Name Last Name Title Email Phone									
Coli		Certified	Operate	or broa	adwa	aymotors4675@att.r	net	26	60-3	88-3007
	Was a verbal summa	arv of find	inas pr	esented to	o the	e on-site represer	ntative?	Yes		
Certifi		Number:	Class:	Effective Date	EX	piration Date: Email:				
	Colin Bullock	13827	IV	7-1-22		6-30-25 broadw	aymotor	s4675@att	i.net	
Cyb	er Security Contact:									
Name				Email:						
	onsible Official: Vike Weaver, Owner					Permittee: Cocojo's	s A Zoon	ners RV Re	esort	i, LLC
	3 E State Road 524					Email: ZOOMERS	rvindian	a@gmail.c	om	
200						Phone:				Contacted?
Wab	ash, Indiana 46992					Fax:				No
			I	NSPECTIO	N FI	NDINGS				
	\bigcirc Conditions evaluated w	ere found to	be satis	factory at th	ne tim	ne of the inspection. (5)			
	\bigcirc Violations were discove	red but corr	ected du	iring the insp	oectic	on. (4)				
	\bigcirc Potential problems were	e discovered	or obse	rved. (3)						
	• Violations were discove	red and req	uire a su	bmittal from	you	and/or a follow-up in:	spection	by IDEM. (2)	
	\bigcirc Violations were discove									
						RING INSPECTION				
	1				l = Un	satisfactory, N = Not Ev	aluated	-		
Ν	Receiving Waters	N	Facility		Ν	Self-Monitoring	N	Enforcement		
Ν	Effluent	N	Opera	tion	Ν	Flow Measuremen	t N	Pretreatm	reatment	
U	Permit	N	Mainte	nance	Ν	Laboratory	Ν	Effluent L	imit	s Compliance
Ν	Collection System	N	Sludge	e Disposal	Ν	Records/Reports	Ν	Other:		
DETAILED AREA EVALUATIONS										
On Tuesday, June 4, 2024 IDEM received a complaint regarding a sewage leak at CocoJo's RV Park. IDEM										
Emergency Response completed the initial investigation. Other agencies that received this complaint included IDNR										
and Indiana State Department of Health. On June 6, 2024, this inspector was notified by IDOH that there was some indications that the WWTP did not discharge to the Salamonie Reservoir as indicated in the current permit, but did										
	discharge to a small creek prior to entry into the reservoir.									
This inspection was completed with IDEM Emergency Response staff to dye test the effluent pipe from the treatment										
plant in hopes of definitively locating the discharge location. Permit:										
Comments:										
As r	noted above, dye testing w									placed
	in the discharge pipe. Within 10 minutes, the neon green dye was visible in a small creek located down a									
hors	horseman's path and just to the east of the treatment plant. On both the cover page and page 1 of your NPDES									

permit, it specifically authorizes discharge from the treatment plant into Salamonie Reservoir and does not authorize any other discharge locations. The treatment plant discharge into the creek prior to the reservoir is a violation of Part II. B. 6 of your permit which states: any overflow or release of sanitary wastewater from the wastewater treatment facilities or collection system that results in a discharge to waters of the state and is not specifically authorized by this permit is expressly prohibited. These discharges are subject to the reporting requirements in Part II.C.3 of this permit.

In addition, Pursuant to 327 IAC 5-2-8(11)(E), where the permittee becomes aware that it failed to submit any relevant facts or submitted incorrect information in a permit application or in any report to the Commissioner, the permittee shall promptly submit such facts or corrected information to the Commissioner. You must work with the IDEM Municipal Permits staff to modify the permit to accurately reflect the receiving stream. Please reach out to Leigh Voss at LVOSS@idem.IN.gov or by phone at 317-232-8698.

Effluent Limits Compliance:

No 1. Were DMRs reviewed as part of the inspection?

IDEM REPRESENTATIVE					
Inspector Name:	Email:	Phone Number:			
Lynn Stackhouse	lstack@idem.IN.gov	317-691-0099			
Other staff participating in the inspection:					
Name(s)	Phone Number(s)				
Dwayne Caldwell - ER					
IDEM MANAGER REVIEW					
IDEM Manager:		Date:			
James E. Weingart		6/10/2024			

Inspection Photographs





Facility: Cocojo's RV Res	ort W/W/TD
Photographer:	
Lynn Stackhouse	
Date: 6/7/2024	Time:
Others Present:	
Dwayne Caldwell	
Discharge pipe loc creek prior to entry Reservoir.	ation into small / into the Salamonie
Facility:	
Cocojo's RV Res	ort WWTP
Photographer:	

Lynn Stackhouse

Date: 6/7/2024

Others Present:

Dwayne Caldwell

Location/Description:

Pooled area just downstream of the discharge pipe location into the small creek located prior to entry into the Salamonie Reservoir.

Time: