

RM 112732



- Facility
 - CoCoJo's RV Campground
- Photographer
 - CO Harmon
- Date/Time
 - 6/1/24
- Others Present
 - N/A
- Possible sewage near bridal trail

RM 112732



- Facility
 - CoCoJo's RV Campground
- Photographer
 - CO Harmon
- Date/Time
 - 6/1/24
- Others Present
 - N/A
- Possible Sewage

RM 112732




- Facility
 - CoCoJo's RV Campground
- Photographer
 - OSC Caldwell
- Date/Time
 - 6/7/24
- Others Present
 - N/A
- WWTP building

RM 112732



- Facility
 - CoCoJo's RV Campground
- Photographer
 - OSC Caldwell
- Date/Time
 - 6/7/24
- Others Present
 - N/A
- Dye discharging after tablets were placed in WWTP effluent.

RM 112732



- Facility
 - CoCoJo's RV Campground
- Photographer
 - OSC Caldwell
- Date/Time
 - 6/7/24
- Others Present
 - N/A
- Dye near the bridal trail