

Municipal Solid Waste Landfill Inspection State Form 34505 (R2/2-97)

Indiana Department of Environmental Management Solid Waste Compliance Section Office of Land Quality 100 North Senate Avenue, Room N-1101 Indianapolis, Indiana 46204-2251

Inspector Name: Cheryl Wiseman Inspector Phone: 219-781-8557

Inspection Date: 6/26/2024

Time In: 9:40 am Time Out: 10:52 am

| Facility Name: Prairie View Recycling | Type of Inspection: Routine | | | |
|---------------------------------------|------------------------------------|----------------------------|--|--|
| County: St. Joseph | Permit #: 71-02 | Permit Expires: 11/22/2028 | | |
| Last inspection date: 3/25/2024 | Violation at last inspection: None | | | |

| CHECKED ITEMS ARE VIOLATIONS OF 329 IAC 10 OR IC 13-20 THAT MUST BE CORRECTED | | | | | | | |
|---|--|--|-----|---|--|-----|--|
| 038 | 329 IAC 10-20-1(a) Established Roadways | | 067 | 329 IAC 10-20-8(b) Furnishing Records to IDEM | | 095 | 329 IAC 10-20-16(c) Vegetation Clearing |
| 039 | 329 IAC 10-20-1(b) Restricted Access | | 068 | 329 IAC 10-20-9 Open Burning | | 096 | 329 IAC 10-20-16(d)(1) Final Cover Vegetation |
| 040 | 329 IAC 10-20-1(c) Barrier Control | | 069 | 329 IAC 10-20-10(a) First Waste Layer | | 097 | 329 IAC 10-20-16(e) Anchored Mulch/Erosion Control Blankets |
| 041 | 329 IAC 10-20-2(a) Passable Roads | | 070 | 329 IAC 10-020-10(b) Slope & Layers | | 098 | 329 IAC 10-20-16(f) Erosion Control Layer |
| 042 | 329 IAC 10-20-2(b) Tracking Mud-On-Site Roads | | 071 | 329 IAC 10-020-10(c) Compaction Working Face/Equipment | | 099 | 329 IAC 10-20-16(g) Vegetation/Mulch Maintenance |
| 043 | 329 IAC 10-20-2(c) Mud/Dust Control-On-Site Roads | | 072 | 329 IAC 10-20-11(a)(1) Run-On Controls | | 100 | 329 IAC 10-20-16(h) Rills/Gullies |
| 045 | 329 IAC 10-20-2(e) Congestion | | 073 | 329 IAC 10-20-11(a)(2) Run-Off Controls | | 101 | 329 IAC 10-20-16(d)(2) Vegetation Mowing |
| 046 | 329 IAC 10-20-3 Signs | | 074 | 329 IAC 10-20-11(b) Waste Deposited in Water | | 102 | 329 IAC 10-20-18(a) Leachate Outside Solid Waste Boundary |
| 047 | 329 IAC 10-20-4(a) Vectors | | 075 | 329 IAC 10-20-11(c) Run-Off/Discharge Handling | | 103 | 329 IAC 10-20-18(b) Surface Leachate Management |
| 048 | 329 IAC 10-20-4(b) Livestock Present | | 076 | 329 IAC 10-20-12(a) Additional Erosion/Sedimentation Control Measures | | 104 | 329 IAC 10-20-18(c) Surface Water Drainage Systems-Leachate |
| 049 | 329 IAC 10-20-4(c) Dust Control | | 077 | 329 IAC 10-20-12(c) Basin Drainage Control Measures | | 105 | 329 IAC 10-20-20(b) Monitoring Leachate Levels |
| 050 | 329 IAC 10-20-4(d) Litter Barriers | | 078 | 329 IAC 10-20-13(a) Cover Soil Type | | 106 | 329 IAC 10-20-20(c) Leachate Collection Contingency Plan |
| 051 | 329 IAC 10-20-4(e) Litter | | 079 | 329 IAC 10-20-13(b) Cover Maintenance/Alt. Cover Approval | | 107 | 329 IAC 10-20-20(d) Leachate Discharge/Disposal |
| 052 | 329 IAC 10-20-4(f) Dead Animal Disposal | | 080 | 329 IAC 10-20-14(a) Working Face Size | | 108 | 329 IAC 10-20-21(a) Leachate Recycling Approval |
| 053 | 329 IAC 10-20-4(g)(01) Outside Containers | | 081 | 329 IAC 10-20-14(b) Daily Cover | | 109 | 329 IAC 10-20-21(b)(4) Leachate Recycling-Odors/ Contamination |
| 054 | 329 IAC 10-20-4(g)(2) Inside Containers | | 082 | 329 IAC 10-20-14(c) Alternative Cover Use | | 112 | 329 IAC 10-20-27(a) Bulk/Un-containerized Liquid Disposal |
| 055 | 329 IAC 10-20-4(g)(3) Recycling Containers | | 083 | 329 IAC 10-20-14(d) Cover-Continuously Open | | 113 | 329 IAC 10-20-27(b) Containerized Liquid Disposal |
| 056 | 329 IAC 10-20-4(h) Human Health/Environmental Threat | | 084 | 329 IAC 10-20-14(e) Daily Cover Supply | | 114 | 329 IAC 10-20-28(a) Bi-monthly Self-Inspection |
| 057 | 329 IAC 10-20-5 | | 085 | 329 IAC 10-20-14(f) | | 115 | 329 IAC 10-20-28 (b) |

| | Scavenging | | Intermediate Cover | | Problem/Hazard Correction |
|-----|---|-----|--|-----|--|
| 058 | 329 IAC 10-20-6(a) Salvage Control | 086 | 329 IAC 10-20-14(g) Intermediate Cover Grading | 116 | 329 IAC 10-20-28(c) Self-Inspection Reports |
| 059 | 329 IAC 10-20-6(b) Salvage Storage | 087 | 329 IAC 10-20-14(h) Additional Erosion/Sedimentation Control Measures-Intermediate Cover | 120 | 329 IAC 10-20-31(2) Baled Waste Management Plan |
| 060 | 329 IAC 10-20-7(a) Safety Devices | 088 | 329 IAC 10-20-15(b) Storage Sites/Borrow Pit Grading | 121 | 329 IAC 10-13-4(c) Permit Compliance |
| 061 | 329 IAC 10-20-7(b) First Aid Kit | 089 | 329 IAC 10-20-15(c) Vegetation Clearing- Storage/Borrow Pits | 223 | 329 IAC 10-20-24(a) Boundary Markers |
| 062 | 329 IAC 10-20-7(c) Telephone | 090 | 329 IAC 10-20-15(d) Tracking Mud-Storage/Borrow Pits | 270 | IC 13-20-14-1 Whole Waste Tire Ban |
| 063 | 329 IAC 10-20-7(d) Personnel Provisions | 091 | 329 IAC 10-20-15(e) Mud/Dust Control- Storage/Borrow Pits | 271 | IC 13-20-09(2) Vegetative Matter Ban |
| 064 | 329 IAC 10-20-8(a)(1) On-Site/Up-to-Date Plans | 092 | 329 IAC 10-20-15(f) Topsoil Management | 272 | 329 IAC 10-20-16(i) Vegetation Mowing |
| 065 | 329 IAC 10-20-8(a)(2) Current Permit | 093 | 329 IAC 10-20-16(a) Cover Continuous Maintenance | | |
| 066 | 329 IAC 10-20-8(a)(3) Quarterly Plot Plan | 094 | 329 IAC 10-20-16(b) Final Cover Grading | | |
| | 329 IAC 10-20-6(c) | 086 | 329 IAC 10-20-14(g) Intermediate Cover Grading | 116 | 329 IAC 10-20-28(c) Self-Inspection Reports |

Comments: A routine inspection was performed at this facility on June 26, 2024. I entered the gate and parked in the parking area outside the main office, where I met with Mr. Donovan Kelley, and Mr. Jerry Klopfenstein. Prior to my arrival, I drove around the outside perimeter of the landfill, where I noted no trash or litter blowing along area roads or on neighboring fields. According to Mr. Kelley, local laborers are routinely employed to collect any windblown trash or litter that may have escaped the efforts of the mobile fencing and heavy equipment operators to contain the trash.

During my meeting in the main office, site conditions and the future plans for the landfill were discussed. Mr. Kelly showed me an updated Quarterly Plot Plan/map from the 1st Quarter of 2024, and a map from the Annual Fly-over from 2023. The active face of the landfill is in the east sides of Cells 6C and 5B, and in the west sides of Cells 3 & 2. Seeding attempts by Fox contractors earlier this year have resulted in grass growth along multiple berms, and any rills or gullies that developed due to recent heavy rains have quickly been addressed.

Mr. Kelley then provided me with a physical tour of the inside of the landfill, and we drove past areas of the landfill containing intermediate cover and areas that are planned for seeding within the next few weeks.

The landfill is well-maintained and is operating in compliance with the current IDEM permit and 329 IAC 10. I noted no solid waste violations with the items and areas inspected.

Confidential Information

In accordance with 329 IAC 6.1 (http://www.in.gov/legislative/iac/T03290/A00061.PDF) a person submitting information to the department for which confidential treatment is requested shall make a written claim of confidentiality at the time of submittal of the information. A person may request confidential treatment of information at the time the information is acquired through the actions of the department, such as inspections. The written claim for confidential treatment may be broad, but must be sufficiently clear to allow for accurate identification of the information claimed to be confidential. In accordance with 329 IAC 6.1-4-1(d), supporting information must be submitted to the commissioner within five (5) working days from the time the information claimed as confidential is acquired by the department. A person submitting a claim of confidentiality shall designate and segregate the information and the supporting information to which the claim applies in a manner that is sufficiently clear to allow the department to identify all confidential claim materials. Confidential information may include (but is not limited to) written or printed material, maps, charts, photographs, or samples (see definition of information at 329 IAC 6.1-2-8). The undersigned Owner/Representative has

| alleged information acquired during this inspection does does not (check one) contain confidential information. A check in the "does" box is not a written claim for confidential treatment of information acquired during | | | | | | |
|---|--|--|--|--|--|--|
| this inspection. | | | | | | |
| Notice of Oral Report | | | | | | |
| In accordance with IC 13-14-5 an oral report of the inspection was provided to the undersigned Owner/Agent at the conclusion of the inspection. The oral report includes any specific matters discovered during the inspection that the IDEM representative believes may be a violation of a law or of a permit issued by the department. The report does not include matters not evident to the IDEM representative or any fact that indicates an intentional, a knowing, or a reckless violation. | | | | | | |
| | | | | | | |
| Received by: Emailed to Mr. Kelley, the St. Joseph County | E-mail Address: <u>dkelley4@wm.com</u> , | | | | | |
| Health Department, and the St. Joseph County Solid Waste | envirohd@sjcindiana.com, | | | | | |
| Management District | randyprzybyszswmd@gmail.com | | | | | |
| Date Emailed by Inspector: 6/27/2024 | ☐ Needs Mailed | | | | | |