



June 16, 2022

McClure Oil Co  
PO Box 1750  
Marion, IN 46952

RE: UST Testing/Inspection Results

Testing Performed:

Elec Line Leak Detector, Product Line Testing

Testing Date: 6/16/2022

Location of Test: McClure Oil  
670 E Main St  
Russiaville, IN 46979

We have completed the testing and/or inspections for the above location as per your request.

A summary of testing results along with copies of the testing/inspections have been enclosed for your records.

If you should have any questions after your review of the results, please let us know.  
Thank you for your continued business.

Sincerely,

Paula Groff-Weidner  
CEO

Enclosures



## UST TESTING/INSPECTION RESULTS SUMMARY

OWNER NAME: McClure Oil Co  
 OWNER ADDRESS: PO Box 1750  
 OWNER CITY/STATE/ZIP: Marion, IN 46952

LOCATION NAME: McClure Oil  
 LOCATION ADDRESS: 670 E Main St  
 LOCATION CITY/STATE: Russiaville, IN 46979

TESTING DATE: **6/16/2022**

### ANNUAL TESTING/INSPECTIONS

AUTOMATIC TANK GAUGE TEST NOT PERFORMED

TANK NO	PRODUCT	BRAND/MODEL	RESULT

PRODUCT LINE TEST COMPLETED

Product line must be within manufacturer's criteria of +/- .050 GPH.

LINE NO	PRODUCT	RESULT	GPH
#1	87	PASS	0
#2	93	PASS	0
#3	E-85	PASS	0
#4	DIESEL	PASS	0
#5	PREM DIESEL	PASS	-0.0296
#6	OFF RD DIESEL	PASS	-0.0296
#1	87	PASS	0

LEAK DETECTOR TEST COMPLETED

PUMP NO	PRODUCT	MAKE	RESULT
	87	FEPETRO	PASS
	93	FEPETRO	PASS
	E-85	FEPETRO	PASS
	DIESEL	FEPETRO	PASS
	PREMIUM DIESEL	FEPETRO	PASS
	OFF R DIESEL	FEPETRO	PASS
	K-1	FEPETRO	PASS

LIQUID SENSOR FUNCTIONALITY TEST NOT PERFORMED

LOCATION	PRODUCT	TYPE	RESULT

### UPON REQUEST TESTING/INSPECTIONS

NON-VOLUMETRIC TANK TEST NOT PERFORMED

LOCATION	VOLUME	PRODUCT	RESULT

SHEAR VALVE OPERATION INSPECTION NOT PERFORMED

DISPENSER	PRODUCT	TYPE	RESULT

### THREE YEAR TESTS/INSPECTIONS

SPILL BUCKET INTERGRITY TESTING NOT PERFORMED

TANK NO	PRODUCT	CONSTRUCTION	RESULT

HYDROSTATIC SUMP TEST NOT PERFORMED

SUMP ID	MATERIAL	DEPTH	RESULT

OVERFILL EQUIPMENT INSPECTION NOT PERFORMED

TANK	PRODUCT	TYPE	RESULT

OVERFILL ALARM TEST NOT PERFORMED

TANK	PRODUCT	BRAND/MODEL	RESULT

VENT CAP TEST NOT PERFORMED

VALVE ID	MANUFACTURER	MODEL #	RESULT

INTERSTITIAL TEST NOT PERFORMED

PRODUCT	LINE #	READING	RESULT

CATHODIC PROTECTION TEST NOT PERFORMED

	PRODUCT	RESULT	

**ELECTRONIC LINE LEAK DETECTOR TEST RESULTS**

*Certified Presion Tank & Line Testing Monthly Monitoring \* Stage - 2 Testing*

DATE OF TEST: 6/16/2022

LOCATION ADDRESS:  
McClure Oil  
670 E Main St  
Russiaville, IN 46979

PRODUCT TESTED	MAKE	PASS/FAIL
<u>87</u>	<u>FEPETRO</u>	<b>PASS</b>
<u>93</u>	<u>FEPETRO</u>	<b>PASS</b>
<u>E-85</u>	<u>FEPETRO</u>	<b>PASS</b>
<u>DIESEL</u>	<u>FEPETRO</u>	<b>PASS</b>
<u>PREMIUM DIESEL</u>	<u>FEPETRO</u>	<b>PASS</b>
<u>OFF R DIESEL</u>	<u>FEPETRO</u>	<b>PASS</b>

NOTES:

OFF ROAD DIESEL FILTERS ON DISPENSER 13 ARE LEAKING.

LARRY GENTRY  
CERTIFIED TECHNICIAN NAME (printed)

*Larry Gentry*  
CERTIFIED TECHNICIAN SIGNATURE

CERT NO: UC108685  
EXPIRATION DATE: 1/21/2024



**OFF ROAD DISPENSER #13**



# ELECTRONIC LINE LEAK DETECTOR TEST RESULTS

*Certified Presion Tank & Line Testing Monthly Monitoring \* Stage - 2 Testing*

DATE OF TEST: 6/16/2022

LOCATION ADDRESS:  
McClure Oil  
670 E Main St  
Russiaville, IN 46979

PRODUCT TESTED	MAKE	PASS/FAIL
<u>K-1</u>	<u>FEPETRO</u>	<u>PASS</u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

NOTES:  
   
   
   
   
 

LARRY GENTRY  
CERTIFIED TECHNICIAN NAME (printed)

Larry Gentry  
CERTIFIED TECHNICIAN SIGNATURE

CERT NO: UC108685  
EXPIRATION DATE: 1/21/2024









