



# INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

*We Protect Hoosiers and Our Environment.*

Northern Regional Office • 300 N. Dr. Martin Luther King Jr. Blvd, Suite 211 • South Bend, IN 46601-1295

(800) 753-5519 • (574) 245-4870 • Fax (574) 245-4877 • www.idem.IN.gov

**Eric J. Holcomb**  
Governor

**Brian C. Rockensuess**  
Commissioner

July 1, 2024

VIA ELECTRONIC MAIL

Chris Zumbaugh  
Star Environmental, Inc.  
2215 Alvord Street  
Indianapolis, Indiana 46205  
czumbaugh@starenv.net

Re: Inspection Summary Letter  
Vacant Outbuilding #5  
Fort Wayne, Allen County

Dear Chris Zumbaugh:

On June 28, 2024, a representative of the Indiana Department of Environmental Management (IDEM), Office of Air Quality (OAQ), conducted an inspection of the Vacant Outbuilding #5, located at 3717 Ardmore Avenue in Fort Wayne, Indiana to determine compliance with Indiana's asbestos rules. This inspection was conducted pursuant to IC 13-14-2-2. For your information, and in accordance with IC 13-14-5, a summary of the inspection is provided below:

Inspection Type: Routine Demolition/Renovation Project  
Inspection Results: No violations were observed

Please direct any questions to me at 574-261-4003 or by email at jealexan@idem.in.gov.

Sincerely,

John Alexander, Compliance Inspector  
Northern Regional Office  
Office of Air Quality

ACES ID: 298250

ENCLOSURE

cc: John Alexander, Compliance and Enforcement Branch, Office of Air Quality  
Nicole Buridana, American Electric Power, 110 East Wayne Street, Fort Wayne, Indiana  
46802, ncburidana@aep.com

**INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT  
OFFICE OF AIR QUALITY  
ASBESTOS FIELD INSPECTION REPORT**



SITE INFORMATION	
SITE NAME/DESCRIPTION	Vacant Outbuilding #5
SITE LOCATION	3717 Ardmore Avenue, Fort Wayne, Indiana Allen County

NOTIFICATION INFORMATION			
NOTIFICATION RECEIVED	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	ORIGINAL DATE RECEIVED: 6/11/2024	
STRIPPING/REMOVAL DATES	6/25/2024 to 8/31/2024	DEMOLITION DATES	6/27/2024 to 8/31/2024
CONTRACTOR INFORMATION	Chris Zumbaugh, Star Environmental, Inc., 2215 Alvord Street, Indianapolis, Indiana 46205, czumbaugh@starenv.net		
OWNER INFORMATION	Nicole Buridana, American Electric Power, 110 East Wayne Street, Fort Wayne, Indiana 46802, ncburidana@aep.com		

INSPECTION INFORMATION			
INSPECTED BY	John Alexander <i>J.A.</i>		
INSPECTION DATE AND TIME	June 28, 2024	TIME IN: 9:20 am	TIME OUT: 9:35 am
REPORTED BY	John Alexander <i>J.A.</i>	REPORT DATE: 6/28/2024	
INSPECTION OBJECTIVE(S)	<input checked="" type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/> Complaint <input type="checkbox"/> Demolition <input type="checkbox"/> Ordered Demolition <input type="checkbox"/> Other:		
ACES TRACKING NUMBER(S)	Notification/General Inspection: 298250		
	Complaint:	Violation/Warning:	
RM TRACKING NUMBER(S)	Complaint:		
PROJECT STATUS	The renovation was completed.		

PERSONNEL INTERVIEWED				
Name	Company	Title	Phone Number	Email Address
Jeff Geller	Star Environmental, Inc.	Asbestos Project Supervisor	260-417-1258	jgeller@starenv.net

<b>OBSERVATIONS</b>				
<b>GENERAL SITE OBSERVATIONS</b>				
Description of area(s) inspected and location of material(s): Upon arrival at the work site, I was met by Jeff Geller of Star Environmental, Inc. Mr. Geller took me back to the site where the structures used to be located. At the time of the inspection, all structures were demolished, and the debris had been loaded into dumpsters. The demolition crew was in the process of removing the concrete foundation of one of the structures. During the inspection, I observed that the project was conducted at a residential farm and the notification should have been marked Courtesy. This was not a regulated project. I checked the area, and I did not observe any suspect asbestos containing material or debris.				
Pre-existing contamination in work area	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Contractor equipment on site	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Asbestos removal in progress	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Accreditation cards available for inspection	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
<b>ABATEMENT</b>				
Asbestos removal clearly observed If yes, from where:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
	<input type="checkbox"/> Through viewing ports	<input type="checkbox"/> By entering enclosures		
	<input type="checkbox"/> Direct observation (No enclosures)			
Estimated amounts of RACM removed/disturbed		linear feet		square feet
		cubic feet		% of total
Abatement method(s) observed:	<input type="checkbox"/> Wetting and stripping	<input type="checkbox"/> Unit/Sectional		
	<input type="checkbox"/> Glovebag method	<input type="checkbox"/> Dry		
<b>ISOLATION</b>				
Warning signs displayed outside work area	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Objects within work area covered	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Evidence of water in containment	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
<b>ASBESTOS WASTE HANDLING</b>				
Stripped asbestos adequately wet	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Stripped asbestos placed in leak tight wrapping	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Waste bags labeled with generator and warning labels	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Any visible emissions	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
<b>CLEANING</b>				
Work area clear of visible signs of asbestos material	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Plastic sheeting disposed of as asbestos waste	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Area wet wiped/HEPA vacuumed	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Final visual inspection completed	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
<b>STORAGE</b>				
Material remaining on site securely stored	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Warning signs/labels posted outside storage area	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
<b>ASBESTOS WASTE DISPOSAL</b>				
Waste disposed of at an approved landfill	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Not Observed	<input checked="" type="checkbox"/> N/A
Name and location of landfill				
<b>ACM AMOUNTS</b>				
If violation(s) noted, estimated amount of ACM involved:				
<b>ADDITIONAL COMMENTS</b>				
None				

SAMPLE INFORMATION					
Sample ID	Photo No.	Sample Location/Description	Chain of Custody Complete	Sent to Lab	Results
N/A			<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	...	
ADDITIONAL SAMPLING COMMENTS					
N/A					

INSPECTION FINDINGS	
<input checked="" type="checkbox"/> No violations were observed or determined at the time of the inspection. <input type="checkbox"/> The following violations were determined at the time of the inspection:	
RECOMMENDED ACTION	Issue inspection summary letter.
EXIT INTERVIEW	I explained my findings, recommendations, and conclusions with Jeff Geller prior to exiting the site.

ATTACHMENTS	
<input type="checkbox"/> None <input checked="" type="checkbox"/> Notification(s) <input type="checkbox"/> List of licensed personnel <input type="checkbox"/> Other:	




# NOTIFICATION OF DEMOLITION AND RENOVATION OPERATIONS

State Form 44593 (R3 / 9-18)

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

<b>I. TYPE OF NOTIFICATION</b> (check one):		<input checked="" type="checkbox"/> Original	<input type="checkbox"/> Revised	<input type="checkbox"/> Canceled	<input type="checkbox"/> Courtesy
<b>II. FACILITY INFORMATION</b>					
Owner / Operator: American Electric Power					
Address: 110 East Wayne Street		City: Fort Wayne		State: IN	ZIP: 46802
Contact: Nicole Buridana		Telephone: 614-477-1532		E-mail: ncburidana@aep.com	
Asbestos Removal Contractor: Star Environmental, Inc.			Demolition Contractor: Denney Excavating		
Address: 2215 Alvord Street			Address: 2050 South Harding Street		
City: Indianapolis	State: IN	ZIP: 46205	City: Indianapolis	State: IN	ZIP: 46221
Contact: Chris Zumbaugh	Telephone: 317-294-2235		Contact: Bill McNaughton	Telephone: 317-797-8009	
E-mail: czumbaugh@starenv.net			E-mail: bmcnaughton@denneyex.com		
IN License Number: 190106071	Expiration: 07/12/2024				
Licensed Asbestos Inspector: Kevin Borsch			Project Designer: NA		
Address: 839 Mill Lake Road, Suite 400			Address:		
City: Fort Wayne	State: IN	ZIP: 46845	City:	State:	ZIP:
Contact: Kevin Borsch	Telephone: 260-483-9795		Contact:	Telephone:	
E-mail: kevin@acmenv.com			E-mail:		
IN License Number: 190120122	Expiration: 8/03/2024		IN License Number:	Expiration:	
<b>III. TYPE OF OPERATION</b>					
<input type="checkbox"/> Demolition	<input checked="" type="checkbox"/> Renovation	<input type="checkbox"/> Ordered Demolition	<input type="checkbox"/> Emergency Renovation	<input type="checkbox"/> Intentional Burning	
<b>IV. IS ASBESTOS PRESENT?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No					
<b>V. PROCEDURES / ANALYTICAL METHODS USED TO DETECT THE PRESENCE AND AMOUNT OF ASBESTOS MATERIALS</b>					
PLM analysis of bulk samples.					
<b>VI. APPROXIMATE AMOUNT OF ASBESTOS TO BE REMOVED AND/OR NOT TO BE REMOVED</b>					
	Regulated ACM to be removed	Nonfriable Asbestos Material to be removed		Nonfriable Asbestos Material NOT to be removed	
		Category I	Category II	Category I	Category II
Pipes (Ln. Ft.)					
Surface Area (Sq. Ft.)	2,370 Sq. Ft.	1,225 Sq. Ft.	2 Sq. Ft.		
Total Volume (Cu. Ft.)					
Total amount on or off all facility components where length or area could not be measured previously					
<b>VII. SCHEDULED DATE OF STRIPPING / REMOVAL</b>		Start (mm/dd/yy): 6/25/2024	End (mm/dd/yy): 8/31/2024		
<b>VIII. SCHEDULED DATES OF RENOVATION / DEMOLITION</b>					
Renovation	Start (mm/dd/yy):	End (mm/dd/yy):			
Demolition	Start (mm/dd/yy): 6/27/2024	End (mm/dd/yy): 8/31/2024			
<b>IX. FACILITY DESCRIPTION</b>					
Building Name: Residential Structure, Log Cabin, Outbuildings #1, #2, #4, & #5					
Street Address: 3717 Ardmore Avenue					
City: Fort Wayne			State: IN	County: Allen	
Location of removal within building (including floor and room numbers):		see attached summaries			
Building Size (Sq. Ft.): see attached summaries		Number of Floors:	Age / Year Built: 1930-1950		
Present Use: Vacant			Prior Use: Residential		



<b>X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, METHODS/TECHNIQUES TO BE USED, AFFECTED FACILITY COMPONENTS AND TYPE OF MATERIAL REMOVED</b>					
Project involves removal of asbestos containing plaster, window glazing, floor tile, floor tile mastic, and sink coating to facilitate demolition.					
<b>XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE SITE; INCLUDING ASBESTOS STRIPPING, REMOVAL AND WASTE HANDLING PROCEDURES TO PREVENT NONFRIABLE ASBESTOS MATERIAL FROM BECOMING FRIABLE IN THE COURSE OF THE PROJECT</b>					
Critical barriers will be utilized. Materials will be removed wet, and placed in sealed, leak proof containers for disposal at an EPA approved landfill.					
<b>XII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER</b>					
Work will cease. Re-notification will be made if necessary. Accredited personnel will remove the acm using appropriate methods.					
<b>XIII. ASBESTOS WASTE TRANSPORTER</b>			<b>XIV. ASBESTOS WASTE DISPOSAL SITE</b>		
Name: National Serv-All (Republic) Hauling Division			Name: Wabash Valley Landfill		
Address: 6231 MacBeth Road			Address: 316 Spring Valley Road		
City: Fort Wayne	State: IN	ZIP: 46809	City: Wabash	State: IN	ZIP: 46992
Contact: James Music	Telephone: 260-377-9280		Contact: Jay Weiseman		
E-mail: smusic@republicservices.com			E-mail: jweiseman@republicservices.com		
<b>XV. ORDER DEMOLITIONS</b>					
Agency Name: NA			Date Ordered Demolition to Begin (mm/dd/yy): NA		
Contact:	Title:	Telephone:	E-mail:		
Regulatory Authority:			Date of Order (mm/dd/yy):		
<b>XVI. EMERGENCY RENOVATIONS</b>					
Date (mm/dd/yy) and Time of Emergency: NA					
Description of sudden, unexpected event:					
Explanation of how the event caused unsafe conditions or would cause equipment damage:					
<b>XVII. CERTIFICATION STATEMENT AND SIGNATURE BY OWNER/OPERATOR</b>					
I HEREBY CERTIFY THAT THE INFORMATION IN THIS NOTIFICATION IS CORRECT AND THAT I WILL ONLY USE INDIANA LICENSED WORKERS AND PROJECT SUPERVISORS, TO IMPLEMENT THIS ASBESTOS PROJECT, WHICH HAVE BEEN TRAINED IN 326 IAC 14-10; 40 CFR PART 61, SUBPART M; AND, IF APPLICABLE, INDIANAPOLIS AIR POLLUTION CONTROL BOARD REGULATION 14. THE TRAINED INDIVIDUAL(S) ALONG WITH EVIDENCE THAT THE REQUIRED TRAINING WAS ACCOMPLISHED SHALL BE AVAILABLE AT THE JOB SITE DURING ACTUAL WORKING HOURS.					
			Date (mm/dd/yy): 6/11/2024	E-mail: czumbaugh@starenv.net	
Owner / operator (Signature)					
Chris T. Zumbaugh			Title: Vice President		
Owner / operator (Printed)					

VI. APPROXIMATE AMOUNT OF ASBESTOS TO BE REMOVED AND/OR NOT TO BE REMOVED					
	Regulated ACM to be removed	Nonfriable Asbestos Material to be removed		Nonfriable Asbestos Material NOT to be removed	
		Category I	Category II	Category I	Category II
Pipes (Ln. Ft.)					
Surface Area (Sq. Ft.)		1,215 Sq. Ft.	2 Sq. Ft.		
Total Volume (Cu. Ft.)					
Total amount on or off all facility components where length or area could not be measured previously					
VII. SCHEDULED DATE OF STRIPPING / REMOVAL		Start (mm/dd/yy): 6/25/2024	End (mm/dd/yy): 8/31/2024		
VIII. SCHEDULED DATES OF RENOVATION / DEMOLITION					
Renovation	Start (mm/dd/yy):	End (mm/dd/yy):			
Demolition	Start (mm/dd/yy): 6/27/2024	End (mm/dd/yy): 8/31/2024			
IX. FACILITY DESCRIPTION					
Building Name: Residential Structure					
Street Address: 3717 Ardmore Avenue					
City: Fort Wayne			State: IN	County: Allen	
Location of removal within building (including floor and room numbers):		Throughout			
Building Size (Sq. Ft.): 1,500 Sq. Ft.		Number of Floors: 1+B	Age / Year Built: 1950's		
Present Use: Vacant			Prior Use: Residence		

VI. APPROXIMATE AMOUNT OF ASBESTOS TO BE REMOVED AND/OR NOT TO BE REMOVED					
	Regulated ACM to be removed	Nonfriable Asbestos Material to be removed		Nonfriable Asbestos Material NOT to be removed	
		Category I	Category II	Category I	Category II
Pipes (Ln. Ft.)					
Surface Area (Sq. Ft.)	2,370 Sq. Ft.				
Total Volume (Cu. Ft.)					
Total amount on or off all facility components where length or area could not be measured previously					
VII. SCHEDULED DATE OF STRIPPING / REMOVAL		Start (mm/dd/yy): 6/25/24	End (mm/dd/yy): 8/31/2024		
VIII. SCHEDULED DATES OF RENOVATION / DEMOLITION					
Renovation	Start (mm/dd/yy):	End (mm/dd/yy):			
Demolition	Start (mm/dd/yy): 6/27/2024	End (mm/dd/yy): 8/31/2024			
IX. FACILITY DESCRIPTION					
Building Name: Log Cabin					
Street Address: 3717 Ardmore Avenue					
City: Fort Wayne			State: IN	County: Allen	
Location of removal within building (including floor and room numbers):		Entire structure to be removed as ACM.			
Building Size (Sq. Ft.): 1,800 Sq. Ft.		Number of Floors: 2+B	Age / Year Built: 1930's		
Present Use: Vacant			Prior Use: Log Cabin		



VI. APPROXIMATE AMOUNT OF ASBESTOS TO BE REMOVED AND/OR NOT TO BE REMOVED					
	Regulated ACM to be removed	Nonfriable Asbestos Material to be removed		Nonfriable Asbestos Material NOT to be removed	
		Category I	Category II	Category I	Category II
Pipes (Ln. Ft.)					
Surface Area (Sq. Ft.)		10 Sq. Ft.			
Total Volume (Cu. Ft.)					
Total amount on or off all facility components where length or area could not be measured previously					
VII. SCHEDULED DATE OF STRIPPING / REMOVAL		Start (mm/dd/yy): 6/25/2024		End (mm/dd/yy): 8/31/2024	
VIII. SCHEDULED DATES OF RENOVATION / DEMOLITION					
Renovation	Start (mm/dd/yy):	End (mm/dd/yy):			
Demolition	Start (mm/dd/yy): 6/27/2024	End (mm/dd/yy): 8/31/2024			
IX. FACILITY DESCRIPTION					
Building Name: Outbuilding #1					
Street Address: 3717 Ardmore Avenue					
City: Fort Wayne			State: IN		County: Allen
Location of removal within building (including floor and room numbers):		Windows			
Building Size (Sq. Ft.): 600 Sq. Ft.		Number of Floors: 1		Age / Year Built: 1950's	
Present Use: Vacant			Prior Use: Garage		

Page 1 of 2

VI. APPROXIMATE AMOUNT OF ASBESTOS TO BE REMOVED AND/OR NOT TO BE REMOVED					
	Regulated ACM to be removed	Nonfriable Asbestos Material to be removed		Nonfriable Asbestos Material NOT to be removed	
		Category I	Category II	Category I	Category II
Pipes (Ln. Ft.)					
Surface Area (Sq. Ft.)	None	None	None		
Total Volume (Cu. Ft.)					
Total amount on or off all facility components where length or area could not be measured previously					
VII. SCHEDULED DATE OF STRIPPING / REMOVAL		Start (mm/dd/yy): NA		End (mm/dd/yy):	
VIII. SCHEDULED DATES OF RENOVATION / DEMOLITION					
Renovation	Start (mm/dd/yy):	End (mm/dd/yy):			
Demolition	Start (mm/dd/yy): 6/27/2024	End (mm/dd/yy): 8/31/2024			
IX. FACILITY DESCRIPTION					
Building Name: Outbuilding #2					
Street Address: 3717 Ardmore Avenue					
City: Fort Wayne			State: IN		County: Allen
Location of removal within building (including floor and room numbers):		NA			
Building Size (Sq. Ft.): 600 Sq. Ft.		Number of Floors: 1		Age / Year Built: 1950's	
Present Use: Vacant			Prior Use: Garage		

Page 1 of 2



VI. APPROXIMATE AMOUNT OF ASBESTOS TO BE REMOVED AND/OR NOT TO BE REMOVED					
	Regulated ACM to be removed	Nonfriable Asbestos Material to be removed		Nonfriable Asbestos Material NOT to be removed	
		Category I	Category II	Category I	Category II
Pipes (Ln. Ft.)					
Surface Area (Sq. Ft.)	None	None	None		
Total Volume (Cu. Ft.)					
Total amount on or off all facility components where length or area could not be measured previously					
VII. SCHEDULED DATE OF STRIPPING / REMOVAL		Start (mm/dd/yy): NA		End (mm/dd/yy):	
VIII. SCHEDULED DATES OF RENOVATION / DEMOLITION					
Renovation	Start (mm/dd/yy):	End (mm/dd/yy):			
Demolition	Start (mm/dd/yy): 6/27/2024	End (mm/dd/yy): 8/31/2024			
IX. FACILITY DESCRIPTION					
Building Name: Outbuilding #4					
Street Address: 3717 Ardmore Avenue					
City: Fort Wayne			State: IN		County: Allen
Location of removal within building (including floor and room numbers):		NA			
Building Size (Sq. Ft.): 1,400 Sq. Ft.		Number of Floors: 2		Age / Year Built: 1950's	
Present Use: Vacant			Prior Use: Garage		

VI. APPROXIMATE AMOUNT OF ASBESTOS TO BE REMOVED AND/OR NOT TO BE REMOVED					
	Regulated ACM to be removed	Nonfriable Asbestos Material to be removed		Nonfriable Asbestos Material NOT to be removed	
		Category I	Category II	Category I	Category II
Pipes (Ln. Ft.)					
Surface Area (Sq. Ft.)	None	None	None		
Total Volume (Cu. Ft.)					
Total amount on or off all facility components where length or area could not be measured previously					
VII. SCHEDULED DATE OF STRIPPING / REMOVAL		Start (mm/dd/yy): NA		End (mm/dd/yy):	
VIII. SCHEDULED DATES OF RENOVATION / DEMOLITION					
Renovation	Start (mm/dd/yy):	End (mm/dd/yy):			
Demolition	Start (mm/dd/yy): 6/27/2024	End (mm/dd/yy): 8/31/2024			
IX. FACILITY DESCRIPTION					
Building Name: Outbuilding #5					
Street Address: 3717 Ardmore Avenue					
City: Fort Wayne			State: IN		County: Allen
Location of removal within building (including floor and room numbers):		NA			
Building Size (Sq. Ft.): Collapsed		Number of Floors: 0		Age / Year Built: 1950's	
Present Use: Vacant			Prior Use: Garage		