



Indiana Department of Environmental Management Emergency Response Incident Report

Description

Incident # 111529

Incident Description: Transformer oil spill
Incident Type: Emergency Response-Reportable Spill
Occurred Date/Time: 03/15/2024 5:50 am
Regulatory Program: Emergency Response
Sub-Program: Other
Follow-Up Priority: 3-Low
Follow-Up Status: Closed
Incident Priority: 3-Low
Incident Status: Closed
Closure Method: Emergency Response Complete

Weather Condition: Rain

Lead Investigator: Caldwell, Dwayne

Resolution Desc: Correspondence

	Parameter	CAS #	Quantity	Units
Substances/Impacts:	Mineral Oil	8012951	100	gallons

Media Impacted: Surface Soil

Location

Location Description: 1430 National Road
Columbus
Bartholomew County

Region Code: Indianapolis Office

County: Bartholomew

Latitude DD: 39.2126

Longitude DD: -85.8801

Method: Interpolation-Map

System: Lat.\Long - Decimal Degrees

Datum: NAD83

Collected By: IDEM Staff



Indiana Department of Environmental Management

Emergency Response Incident Report

Source Entity

Source Type: Agency Interest

Source Entity Name: Duke Energy

Address 1: 2727 Central Ave

Municipality: Columbus

County: Bartholomew

State: IN

Zip Code: 47201

Telecom: Business phone number 1 3173613416

Reporter

Received By: Caldwell, Dwayne

Received Date/Time: 03/15/2024 6:01:25 am

Receipt Method: Emergency Response Hotline

Reporter Type: Self Reported/Resp Party

Name: Chad Miller

Organization: Duke Energy

State: IN

Telecom: Cellular phone number 1 (317) 412-5943

Actions

Task	Staff Assigned	Start Date	Due Date	Completed Date	Hours Spent
Conduct Follow-up Comments: Emailed incident number and request for cleanup report to Mr. Miller.	Caldwell, Dwayne			03/15/2024	
Lead ER Staff Comments: Transformer mineral oil spilled, approximately 100 gallons (all non-PCB). Oil contained to grass and booms placed in concrete ditch that contained water, but doesn't the reporter doesn't believe any oil reached the water. Cleanup crew on scene placing oil dry and will excavate the soil area impacted (JDH Contracting). Believed to be caused by thunderstorms overnight.	Caldwell, Dwayne			03/15/2024	
Conduct Follow-up Comments: emailed RP for cleanup report.	Caldwell, Dwayne			06/28/2024	



Indiana Department of Environmental Management Emergency Response Incident Report

Actions						
Task	Staff Assigned	Start Date	Due Date	Completed Date	Hours Spent	
Complete Emergency Response	Caldwell, Dwayne			07/01/2024		
Comments: Received the final report						