

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

Public Water System Sanitary Survey / Field Inspection Report

Public Water System Sanitary Survey  Field Inspection Report

PWS Name Boss Baptist Church PWSID Number 2450068 Date 6-28-24

Yes  No

\* Are there any possible system problems not addressed by this survey that deserve attention of system staff?

42. Comments and Recommendations

No issues at time of Sanitary Survey.

They removed the particulate filter and installed reverse osmosis system. I will enter this in to the records!

\* I went over the SSP with the O.P.

Survey Performed By

Person Interviewed and Signature

Recheck Date

*[Signature]*

*[Signature]*

6-28-29

Go over Site Sampling Plan.

Due 7-7-24  
 ON for 3:00 PM Friday  
 6-28-24

**System Basic Information Summary**  
**IN2450068 ROSS BAPTIST CHURCH**


Activity	Activity Date	Source Type	System Type	Population	Total Population	Seasonal Dates	Service Area
A	4/14/2009	GW	NC	R 2	110	1 1 to 12 31	CHURCH
<b>Operator Class</b>	<b>Service Connections</b>	<b>Field Inspector</b>		T 108		<b>Contact Type Key</b>	OTHER TRANSIENT AREA
	3	Daniel Keane					

AC - Mailing Contact    EC - Emergency Contact    OW - Owner  
 FC - Financial Contact    OP - Operator    SA - Reminders  
 SC - SCADA Contact

**Contact Information**

Type	Contact Name	Street	City	State	Zip	Phone	Ext	Fax
AC	Mr. MOORE, ANDREW rossbaptist@sbcglobal.net	4790 Noble Street	GARY	IN	46408	219-980-1533		
EC	Ms. EATON, KATHRYN kecakelady@sbcglobal.net	4639 Roosevelt Place	GARY	IN	46408	219-677-1986		
FC	Ms. ETHERIDGE, TERESA	2326 West 46th Avenue	GARY	IN	46408	219-980-1533 219-801-2818		
OP	Mr. ETHERIDGE, GLEN (BUTCH)	2326 West 46th Avenue	GARY	IN	46408	219-805-0315		
PL	PHYSICAL ADDRESS, IN2450068	4790 Noble Street	GARY	IN	46408	219-980-1533		
SA	Ms. EATON, KATHRYN kecakelady@sbcglobal.net	4639 Roosevelt Place	GARY	IN	46408	219-677-1986		

Ext    Fax  
 } sk



Need to add reverse Osmosis.

# Unresolved Site Visit Deficiencies By PWSID

IN2450068 ROSS BAPTIST CHURCH

Visit Date	Visit Reason	Deficiency Date	Severity	Deficiency Type	Deficiency Description	Comments
11/9/2020	Level 2 Assessment	11/9/2020	MIN	Cross connection(s) in the treatment process	Cross connection in the treatment process	Airgap needs to be adjusted to meet the requirement.

*Corrected*