

From: [TERNIEDEN, LUCIO](#)
To: [anita ramer](#); [Diana Hernandez](#); [Caleb Miller](#); [Bethel Missionary Church](#)
Cc: [Sims, April](#); [Wright, Megan](#)
Subject: RE: IN2200503 Bethel Missionary Ch. Inspection Summary 6.14.2024
Date: Wednesday, June 19, 2024 2:01:00 PM
Attachments: [image001.png](#)
[image002.png](#)
[image003.png](#)
[image004.png](#)
[image005.png](#)
[image006.png](#)

Yes, this will suffice as a response. Do you have a time frame?

Lucio M. Ternieden, Chief
Field Inspection Section-Drinking Water Branch
Office of Water Quality-IDEM
100 North Senate Avenue-MC: 66-34
Indianapolis, IN 46204
(317) 234-7461 • L.Ternied@idem.IN.gov

From: anita ramer <anitaramer@gmail.com>
Sent: Wednesday, June 19, 2024 10:30 AM
To: TERNIEDEN, LUCIO <LTERNIED@idem.IN.gov>; Diana Hernandez <dianajhernandez79@yahoo.com>; Caleb Miller <calebandrachel.service@gmail.com>; Bethel Missionary Church <joel@bethelmissionarychurch.org>
Subject: Re: IN2200503 Bethel Missionary Ch. Inspection Summary 6.14.2024

**** This is an EXTERNAL email. Exercise caution. DO NOT open attachments or click links from unknown senders or unexpected email. ****

This deficiency was noted several inspections ago. At that time an exterior smooth bore tap was provided at the axillary buildings, which we call the cabin, NW corner. It wasn't identified in further inspections. Regardless, I will obtain a licensed plumber's estimate if this requirement is possible for our well system. Please let me know if this reply satisfies your 30 day plan requirement.

Best Regards,
Jim Ramer
Trustee, Bethel Missionary Church

On Mon, Jun 17, 2024 at 9:38 AM Bethel Missionary Church Office <officebethelmissionarychurch@gmail.com> wrote:

----- Forwarded message -----

From: **TERNIEDEN, LUCIO** <LTERNIED@idem.in.gov>

Date: Fri, Jun 14, 2024 at 2:38 PM

Subject: IN2200503 Bethel Missionary Ch. Inspection Summary 6.14.2024

To: office@bethelmissionarychurch.org <office@bethelmissionarychurch.org>

Cc: Judson, Edward <ejudson@idem.in.gov>, Sims, April <ASIMS@idem.in.gov>,

Goodman, Karla <kgoodman@idem.in.gov>, Wright, Megan

<MeWright@idem.in.gov>, ENV Health <ehealth@elkhartcounty.com>

Attached is your Inspection Summary letter and Sanitary Survey report. We are now issuing the summary letters via email versus regular mail in order to get them to you more quickly.

There were Deficiencies noted at the time of the inspection (See attached sanitary survey report). Within 30 days of receipt of this letter, a written detailed explanation, documenting compliance with each of the requirements noted on the attached survey, must be submitted to this office. Noncompliance with any of the deficiencies listed in the sanitary survey report noted at the time of the next inspection may result in further action by this office. Please direct any response to this letter to me at the email or fax provided below.

If you have any questions regarding the inspection please contact your inspector whose contact information is listed at the end of the inspection summary letter.



Lucio M. Ternieden, Chief
Field Inspection Section-Drinking Water Branch
Office of Water Quality-IDEM
100 North Senate Avenue-MC: 66-34
Indianapolis, IN 46204
(317) 234-7461 • LTernied@idem.IN.gov

Indiana Department of Environmental Management



Scan the QR code to leave your feedback.

We appreciate your input!

