



INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

We Protect Hoosiers and Our Environment.

100 N. Senate Avenue • Indianapolis, IN 46204
(800) 451-6027 • (317) 232-8603 • www.idem.IN.gov

Eric J. Holcomb
Governor

Brian C. Rockensuess
Commissioner

June 25, 2024

VIA E-MAIL

Mr. Colton Moulder
Colton T. Moulder
11411 W 300 N
Kempton, IN 46049
cmoulder91@yahoo.com

Re: **Inspection Summary Letter**
Colton T. Moulder
FID# 6877
Kempton, Tipton County

Dear Mr. Moulder:

On June 24, 2024, a representative of the Indiana Department of Environmental Management, Office of Land Quality, conducted a follow-up inspection of the Colton T. Moulder farm, located at 654 N 975 W, Kempton, Tipton County. This inspection was conducted pursuant to IC 13-14-2-2. For your information, and in accordance with IC 13-14-5, a summary of the inspection is provided below:

Type of Inspection:	CFO Follow-up
Results of Inspection:	No violation(s). See attached inspection report (re-sample perimeter tile at 1E).

Please direct any questions regarding this inspection to Kim Whittington-Vester at (317) 409-4729 or by email at kwhittin@idem.in.gov.

Sincerely,

Charles P. Grady, Section Chief
Confined Feeding Operation Compliance
Office of Land Quality

Enclosure

cc: Tipton County Health Department



CFO
INSPECTION REPORT
 INDIANA DEPARTMENT OF
 ENVIRONMENTAL MANAGEMENT

Inspector's Name:	Kim Whittington-Vester	
Others Present	Colton Moulder	Owner/Operator
Date:	6/24/2024	
Time In:	11:25 AM	
Time Out:	11:35 AM	

General Information

Inspection Type

Inspection Type: CFO Follow-Up

Facility Information

Facility Name: Facility Name: Colton T. Moulder

Facility Location: Street Address: 654 N 975 W
 City: Kempton
 State: IN
 Zip Code: 46049
 County: Tipton

Facility Mailing Information: Mailing Address: 11411 W 300 N
 Mailing City: Kempton
 Mailing State: IN
 Mailing Zip Code: 46049

Facility Contact Information: Contact Person: Colton Moulder
 Contacts Phone Number: 765-860-7468 (cell)
 Contact Fax Number:
 Contact E-mail Address: cmoulder91@yahoo.com

Owner Contact Information: Owner Name: Same as Facility Contact
 Owner Phone Number:
 Owner Fax Number:
 Owner E-mail Address:

Facility ID

Log Number: 6877

Animal Types

Animals Present: Finishers
 Nursery Pigs

Manure Management Systems

Type of Manure Management System: Below Ground Liquid Storage Tank

Approved Structures

Number of Permitted Structures: 1 barn

Number of Observed Structures: 1 barn

Outstanding Issues

Last Inspection Date: 6/10/2024

Previous Violation(s): Yes No

Perimeter drain tile riser located at 1E tested >6 ppm for ammonia nitrogen.

Checklist

Discharge and Spill Requirements

- Unpermitted Discharge
- Spill Not Reported
- Spills Not Managed

Approval and Performance Standards

- No Valid Approval
- Approval Condition
- Access Denied

Operational Standards

- Maintenance and Operation
- Improper Freeboard

Manure Application Activities

- Staging
- Run-Off

<input type="checkbox"/> Markers Not Maintained <input type="checkbox"/> Unapproved Manure Storage <input type="checkbox"/> Self Monitoring <input type="checkbox"/> Earthen Berm Not Maintained <input type="checkbox"/> Removal of Accumulated Solids <input type="checkbox"/> Vegetation Management System <input type="checkbox"/> Feedlot Run-Off <input type="checkbox"/> Transport & Handling <input type="checkbox"/> Mortality Management	<input type="checkbox"/> Ponding <input type="checkbox"/> Spray Irrigation Operation <input type="checkbox"/> Transport and Handling <input type="checkbox"/> Emergency Application, Snow and Frozen Ground <input type="checkbox"/> Manure Applied from Roadway <input type="checkbox"/> Manure Applied to Erodible Soils <input type="checkbox"/> Manure Applied to Saturated Soils
--	---

Operating Record <input type="checkbox"/> Requirements <input type="checkbox"/> Farmstead Plan <input type="checkbox"/> Manure Management Plan <input type="checkbox"/> Ground Water Monitoring <input type="checkbox"/> Storm Water Pollution Prevention Plan Certification <input type="checkbox"/> Certification by a Registered Professional Engineer <input type="checkbox"/> Construction Requirements <input type="checkbox"/> Self-Monitoring Records <input type="checkbox"/> Emergency Response Plan <input type="checkbox"/> Land Use Agreements <input type="checkbox"/> Justification of Nitrogen Losses <input type="checkbox"/> Land Application Records for 5 Years <input type="checkbox"/> Emergency Land Application of Manure <input type="checkbox"/> Spill Documentation <input type="checkbox"/> Spray Irrigation Plan <input type="checkbox"/> Land Application Monitoring Activities <input type="checkbox"/> Marketing and Distribution Records for 5 Years <input type="checkbox"/> Maintenance Activities on Liquid Manure Storage Facilities <input type="checkbox"/> Setback Waivers <input type="checkbox"/> Approvals	Land Application Records <input type="checkbox"/> Required Acreage for Manure Application <input type="checkbox"/> Manure and Soil Testing <input type="checkbox"/> Apply at Agronomic Rate <input type="checkbox"/> Land Application Records <input type="checkbox"/> Marketing & Distribution <input type="checkbox"/> Information Sheets
--	--

Storm Water Management <input type="checkbox"/> Applicability <input type="checkbox"/> Storm Water Management	Exiting Program <input type="checkbox"/> Decommissioning Storage Facility <input type="checkbox"/> Exiting the Program Requirements <input type="checkbox"/> Closing the Operation
--	--

General Comments

On June 24, 2024, a follow-up inspection was conducted to re-sample the perimeter drain tile riser located at 1E for ammonia nitrogen. During the routine compliance inspection conducted on 6/10/2024, the sample collected from this perimeter drain tile riser tested >6ppm for ammonia nitrogen.

The sample collected today was non-detect. See attached photo.

No further action is necessary.

NOTE: Prior to this follow-up inspection, a routine compliance inspection was conducted at FID# 3401. However, Mr. Moulder waived biosecurity to allow for this follow-up inspection/re-sampling to occur on the same day.

Description of Violations and Further Actions

The findings noted in this report do not include a compliance evaluation for the submittal of required construction notifications, construction affidavits, facility change notifications, as-built plans, waste storage structure closures, and special compliance monitoring reports or data.

Inspection Documentation

Photograph's Taken	<input checked="" type="radio"/> Yes <input type="radio"/> No
--------------------	---

Photo Description	Location
-------------------	----------

See attached	
--------------	--

Map(s)	<input type="radio"/> Yes <input checked="" type="radio"/> No
--------	---

GPS Location Collected	<input type="radio"/> Yes <input checked="" type="radio"/> No
------------------------	---

Field Screening Conducted	<input type="radio"/> Yes <input checked="" type="radio"/> No
---------------------------	---

Lab Sample	<input type="radio"/> Yes <input checked="" type="radio"/> No
------------	---

Inspection Results/Actions	
Bio-Security	Bio-Security Policy time frames between facilities waived by operator.
Finalize Inspection	
Written Summary of Inspection	No violation(s)
Inspector Information	Inspector: Kim Whittington-Vester
	Phone Number: (317) 409-4729
	Email Address: kwhittin@idem.in.gov



Facility Name

FID# 6877 – Colton T. Moulder

Photographer

Kim Whittington-Vester

Date

6-24-2024

Others Present

Colton T. Moulder, Owner/Operator

Description

This photo shows the ammonia nitrogen test result of non-detect from the perimeter tile riser located at permitted structure 1E.

From: [colton moulder](#)
To: [Martin, Bradley A](#)
Subject: Re: Colton T Moulder - Confined Feeding Inspection Report
Date: Wednesday, June 26, 2024 4:02:27 PM

**** This is an EXTERNAL email. Exercise caution. DO NOT open attachments or click links from unknown senders or unexpected email. ****

Received

On Jun 25, 2024, at 6:33 AM, Martin, Bradley A <BAMartin@idem.in.gov> wrote:

Attached is the Confined Feeding Inspection Report for Colton T Moulder. Please respond to this email to confirm your receipt of this document.

<image001.png> Brad Martin
Administrative Assistant | Compliance Branch
Office of Land Quality
Indiana Department of Environmental Management
<image003.png> <!--[if !vml]--> <!--[endif]-->
(317) 234 6923 | Bamartin@idem.IN.gov
<image004.png>
|
<image005.png>
|
<image006.png>
|
<image007.png>

<80 - CF - Colton T Moulder - 6877 - 6-24-24.pdf>