



Indiana Department of Environmental Management

Emergency Response Incident Report

Description

Incident # 112716

Incident Description: Small Diesel Spill

Incident Type: Emergency Response-Non-reportable Spill

Occurred Date/Time: 06/02/2024 9:32 pm

Regulatory Program: Emergency Response

Follow-Up Status: Assigned to Staff

Incident Status: Closed

Closure Method: Emergency Response Complete

Weather Condition: Clear

Lead Investigator: Sawin, Jared

Resolution Desc: Small diesel spill @ a filling station. Spill was cleaned up by ISR. OSC Sawin will get a report from Keith Belcher. OSC Sawin will also provide Adam Reid with IDEM RM Entry Number.

Location

Location Description: 14000 West 28th street
Gaston

Delaware County

County: Delaware

Latitude: 85 Degrees 33 Minutes 8.3 Seconds

Longitude: 40 Degrees 16 Minutes 36.7 Seconds

Latitude DD: 40.276861

Longitude DD: -85.552306

Method: Interpolation-Map

System: Lat.\Long - Decimal Degrees

Datum: NAD83

Collected By: IDEM Staff

Source Entity

Source Type: Agency Interest



Indiana Department of Environmental Management Emergency Response Incident Report

Reporter

Received By: Sawin, Jared

Received Date/Time: 06/02/2024 5:20:11 pm

Reporter Type: Private Citizen

State: IN

Actions

Task	Staff Assigned	Start Date	Due Date	Completed Date	Hours Spent
Lead ER Staff	Sawin, Jared	6/2/24 9:32	06/02/2024	06/02/2024	
Conduct Follow-up	Sawin, Jared	6/2/24 21:32	06/02/2024	06/02/2024	
Comments: OSC Sawin followed up with Adam Reid, initial reporter. Adam states that ISR responded to this spill & cleaned it up. OSC Sawin provided the database entry number for Mr. Reid & ISR Keith Belcher, who will return a report once prepared.					
Conduct Follow-up	Sawin, Jared	6/24/24 12:43	06/24/2024	06/24/2024	
Comments: Requested report update from Adam Reid via email.					
Complete Emergency Response	Sawin, Jared	6/26/24 14:36	06/26/2024	06/26/2024	
Comments: Closed, logged, uploaded for VFC.					