



# Indiana Department of Environmental Management Emergency Response Incident Report

## Description

Incident # 107177

**Incident Description:** Diesel Spill I-70 Ext 11A Terra Haute Vigo County

**Incident Type:** Emergency Response-Non-reportable Spill

**Occurred Date/Time:** 05/22/2023 2:39 pm

**Regulatory Program:** Emergency Response

**Incident Priority:** 3-Low

**Incident Status:** Closed

**Closure Method:** Emergency Response Complete

**Lead Investigator:** Mcbeth, Kevin

**Resolution Desc:** ADDRESSED VIA CORRESPONDENCE.

03/25/2024- Shawn Husband advised dig is scheduled for tonight. INDOT Dig Permit E24COB0050. PAH confirmatory sample to be conducted.

04/25/2024-Spill Cleanup report, analytical results, and disposal manifests received. No further action needed from IDEM ER at this time.

	<u>Parameter</u>	<u>CAS #</u>	<u>Quantity</u>	<u>Units</u>
<b>Substances/Impacts:</b>	Diesel	68334305		

**Media Impacted:** Surface Soil

## Location

**Location Description:** I-70 exit 11 A Eastbound  
Terra Haute  
Vigo County

**Region Code:** Indianapolis Office

**County:** Vigo

**Latitude DD:** 39.4305

**Longitude DD:** -87.3394

**Method:** Interpolation-Map

**System:** Lat.\Long - Decimal Degrees

**Datum:** NAD83

**Collected By:** IDEM Staff



# Indiana Department of Environmental Management

## Emergency Response Incident Report

### Source Entity

**Source Type:** Non-Agency Interest  
**Source Entity Name:** Select 1 Transport INC  
**Address 1:** 1749 Northwood  
**Municipality:** Troy  
**State:** MI  
**Zip Code:** 48084  
**Telecom:** Business phone number 1 877-810-9700

### Reporter

**Received By:** Mcbeth, Kevin

**Received Date/Time:** 05/22/2023 3:00:01 pm

**Receipt Method:** Emergency Response Hotline

**Reporter Type:** Organization

**Name:** Matt Mcullough  
**Organization:** Riley Volunteer Fire Department  
**Address 1:** 7659 E 1st Ave  
**Municipality:** Riley  
**State:** IN  
**Zip Code:** 47871  
**Comments:** Diesel spill to roadway and shoulder.  
**Telecom:** Business phone number 1 812-894-3610

### Actions

Task	Staff Assigned	Start Date	Due Date	Completed Date	Hours Spent
Lead ER Staff	Mcbeth, Kevin			05/22/2023	
Comments: Received notification of incident.					
Conduct Follow-up	Mcbeth, Kevin			03/25/2024	
Comments: 3/25/2024- E-Environmental has scheduled a dig, followed up with soil samples. Final Report will be completed shortly after excavation work was done.					



# Indiana Department of Environmental Management Emergency Response Incident Report

## Actions

Task	Staff Assigned	Start Date	Due Date	Completed Date	Hours Spent
Complete Emergency Response	Mcbeth, Kevin			04/25/2024	

Comments: Received final cleanup report, analytical results, and disposal documentation. No further action needed from IDEM ER at this time.