

NOTIFICATION OF DEMOLITION AND RENOVATION OPERATIONS State Form 44593 (R4 / 10-18) INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT Received State of Indiana 1 5 20

							Rece	ived _a	260
NOTE:	FICATIO	N OF DEMO	I ITION AI	ND RENO	VATION OF	FRATIC		1	, 28502
State Fo	rm 44593 (F	R4 / 10-18) SENT OF ENVIR	OBBAERITAL N	IANIAGEMENT	ration of	P-13/2-117	Min	15 2023	J 40
INDIANA	1 DEFARTIV	ENTOF ENVIR	OMNEN INCH	MINAGENIEN	l		1011	ironmental	un. Mann
I. TYPE OF NOTIFICA	ATION (che	ck one):	🗹 Origin	s)	Revised		JUN Degradia	e of All O'	☐ Courtesy
II. FACILITY INFORM			VA, Interviews	100	1.00	Mile Trigger		A Property	
Owner / Operator: Juan	and Maria	G. Garcia							
Address: 24121 Lakes				City: Crete				State: IL	ZIP; 60417
Contact:			Telephone: E				E-mail:		
Asbestos Removal Contractor: Industrial Insulation Solution, Inc.			Demolition Contractor: Richardson Disposal						
Address: 443 Conkey Street			Address: 620 E 10th Place						
city: Hammond		State: IN	ZIP: 46321	City: Gary				State: IN	ZIP: 46402
Contact: Tomas Amay		Telephone: 21	9-210-2865		Richardson			Telephone:	219-944-4999
E-mail: service@iises.				E-mail: rich	ndisposal@gm	ail.com		2 - 100 (000 000 000 000 000 000 000 000 00	
IN License Number: 19/	A004301	Expiration: 09	/23/2023			1000			
Licensed Asbestos Inspector:	Lake	County Environmen	tal Services LLC	Project Des	igner:				
Addréss: 2158 45th St	reet - Suite	#155		Address:					
City: Highland		State: IN	ZIP: 46322	City:				State:	ZIP:
Contact: 219-455-1239)	Telephone: 21	9-334-9817	Contact:				Telephone:	
E-mail: Lakecountyser	vices82@g			E-mail:	, , , , , , , , , , , , , , , , , , , ,	· · · · · · · · · · · · · · · · · · ·		·	
N License Number: 19/	AD13954	Expiration: 0	5/23/2024	IN License	Number:			Expiration:	
II. TYPE OF OPERA	TION							eseu investiga	
Demalition		Renovation	, l	Ordered Den	nalition	□ Emeras	ncy Renovatio	ո Пո	tentional Burning
		TC: ID TOLIOTE	<u>, le</u>	J Drabine Bei	itosiuori j	- mision Se	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
V. IS ASBESTOS PI	RESENT?	Yes	□ No					a er naut	
		☐ Yes	□ No				OUNT OF AS		
V. PROCEDURES / /	ANALYTIC	☐ Yes	□ No USED TO D	ETECT THE	PRESENCE				
V. PROCEDURES / / A site ins	ANALYTIC spection wa	Yes AL METHODS as conducted a	USED TO D nd tested by I	ETECT THE Polarized Lig	PRESENCE	AND AMO	DUNT OF AS		
V. PROCEDURES / / A site ins	ANALYTIC spection wa	AL METHODS as conducted a DF ASBESTOR Regulated ACM	USED TO D nd tested by I S TO BE REI	DETECT THE Polarized Lig	PRESENCE ht (.(AND AMO	DUNT OF AS しじいい DVED	BESTOS N	MATERIALS
V. PROCEDURES / / A site ins	ANALYTIC spection wa	Yes AL METHODS as conducted a	USED TO DE North to be North	PETECT THE Polarized Lig MOVED AND	PRESENCE ht () HON NOT TO his Material to be	AND AMO A1 K/ BE REMO	DUNT OF AS UUU V OVED Nonfrigble A	BESTOS N	
V. PROCEDURES / / A site ins VI. APPROXIMATE /	ANALYTIC spection wa	AL METHODS as conducted a DF ASBESTOR Regulated ACM	USED TO DE North to be North	DETECT THE Polarized Lig	PRESENCE ht (.(AND AMO A1 K/ BE REMO	DUNT OF AS しじいい DVED	BESTOS N	MATERIALS erial NOT to be removed
V. PROCEDURES / / A site ins VI. APPROXIMATE / Pipes (Ln. Ft.)	ANALYTIC spection wa	AL METHODS as conducted a DF ASBESTOR Regulated ACM	USED TO DE North to be North	PETECT THE Polarized Lig MOVED AND	PRESENCE ht () HON NOT TO his Material to be	AND AMO A1 K/ BE REMO	DUNT OF AS UUU V OVED Nonfrigble A	BESTOS N	MATERIALS erial NOT to be removed
V. PROCEDURES / / A site ins VI. APPROXIMATE / Pipes (Ln. Ft.) Surface Area (Sq. Ft.)	ANALYTIC spection wa	AL METHODS as conducted a DF ASBESTOR Regulated ACM	USED TO DE North to be North	DETECT THE Polarized Lig MOVED AND	PRESENCE tht () DOOR NOT TO as Material to be	AND AMO A1 K/ BE REMO	DUNT OF AS UUU V OVED Nonfrigble A	BESTOS N	MATERIALS erial NOT to be removed
V. PROCEDURES / / A site ins VI. APPROXIMATE / Pipes (Ln. Ft.) Surface Area (Sq. Ft.) Total Volume (Cu. Ft.) Total amount on or off a components where length	ANALYTIC spection was AMOUNT (AL METHODS as conducted a DF ASBESTOR Regulated ACM	USED TO DE North to be North	DETECT THE Polarized Lig MOVED AND	PRESENCE tht () DOOR NOT TO as Material to be	AND AMO A1 K/ BE REMO	DUNT OF AS UUU V OVED Nonfrigble A	BESTOS N	MATERIALS erial NOT to be removed
Pipes (Ln. Ft.) Surface Area (Sg. Ft.) Total Volume (Cu. Ft.) Total amount on or off a components where lenguarea could not be meas	ANALYTIC spection was AMOUNT (AL METHODS as conducted a DF ASBESTOR Regulated ACM	USED TO DE North to be North	DETECT THE Polarized Lig MOVED AND	PRESENCE tht () DOOR NOT TO as Material to be	AND AMO A1 K/ BE REMO	DUNT OF AS UUU V OVED Nonfrigble A	BESTOS N	MATERIALS erial NOT to be removed
V. PROCEDURES / / A site ins VI. APPROXIMATE / Pipes (Ln. Ft.) Surface Area (Sq. Ft.) Total Volume (Cu. Ft.) Total amount on or off a components where lenguage area could not be meas previously	ANALYTIC spection was AMOUNT (AL METHODS as conducted a DF ASBESTO: Regulated ACM removed	USED TO DE Nont to be Nont	PETECT THE Polarized Lig MOVED AND Triable Asbesto Category I	PRESENCE ht	AND AMO A1 K/ BE REMO removed bry II	Nonfriable A	BESTOS N	MATERIALS erial NOT to be removed
V. PROCEDURES / / A site ins VI. APPROXIMATE / Pipes (Ln. Ft.) Surface Area (Sq. Ft.) Total Volume (Cu. Ft.) Total amount on or off a components where lenguage area could not be meas previously VII. SCHEDULED D/	ANALYTIC spection was AMOUNT (all facility gith or ured	AL METHODS as conducted a OF ASBESTO: Regulated ACM removed	No SUSED TO DE North Community of the North C	DETECT THE Polarized Lig MOVED AND Prinable Asbesto Category I	PRESENCE ht	AND AMO A1 K/ BE REMO	Nonfriable A	BESTOS N	MATERIALS erial NOT to be removed
V. PROCEDURES / / A site ins VI. APPROXIMATE / VI. APPROXIMATE / Pipes (Ln. Ft.) Surface Area (Sq. Ft.) Total Volume (Cu. Ft.) Total amount on or off a components where lenguarea could not be meas previously VII. SCHEDULED D/ VIII. SCHEDULED D/	ANALYTIC spection was AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AL METHODS as conducted a DF ASBESTO: Regulated ACM removed Repulated ACM removed	No SUSED TO DE Nond tested by STO BE REF	DETECT THE Polarized Lig MOVED AND friable Asbesto Category I	PRESENCE ht	AND AMO A1 K/ BE REMO removed bry II	Nonfriable A	BESTOS N	MATERIALS erial NOT to be removed
A site ins A site ins A site ins II. APPROXIMATE I Pipes (Ln. Ft.) Surface Area (Sg. Ft.) Total Volume (Cu. Ft.) Total volume (Cu. Ft.) Total amount on or off a components where lenguage accould not be measoreviously VII. SCHEDULED DI Renovation	ANALYTIC spection was AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AL METHODS as conducted a DF ASBESTO: Regulated ACM removed FRIPPING / RE RENOVATION	No SUSED TO DE North to be North CO	DETECT THE Polarized Lig MOVED AND friable Asbesto Category I tart (mm/dd/yy) ON m/dd/yy):	PRESENCE ht OFOR NOT TO as Material to be Categ	AND AMO A1 K/ BE REMO removed bry II	Nonfriable A	BESTOS N	MATERIALS erial NOT to be removed
A site ins A site ins VI. APPROXIMATE A Pipes (Ln. Ft.) Surface Area (Sq. Ft.) Total Volume (Cu. Ft.) Total amount on or off a components where lenguage area could not be measure could not be measure could not be measure could not be measure could not be measure. VIII. SCHEDULED DA Renovation Demolition	AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AL METHODS as conducted a DF ASBESTO: Regulated ACM removed Repulated ACM removed	No SUSED TO DE North to be North CO	DETECT THE Polarized Lig MOVED AND friable Asbesto Category I	PRESENCE ht OFOR NOT TO as Material to be Categ	AND AMO A1 K/ BE REMO removed bry II	Nonfriable A	BESTOS N	MATERIALS erial NOT to be removed
A site ins A site ins VI. APPROXIMATE A Pipes (Ln. Ft.) Surface Area (Sq. Ft.) Total Volume (Cu. Ft.) Total amount on or off a components where lenguage acould not be meas previously VII. SCHEDULED DA Renovation Demoition IX. FACILITY DESC	AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AMOUNT (AL METHODS as conducted a DF ASBESTO: Regulated ACM removed FRIPPING / RE RENOVATION	No SUSED TO DE North to be North CO	DETECT THE Polarized Lig MOVED AND friable Asbesto Category I tart (mm/dd/yy) ON m/dd/yy):	PRESENCE ht OFOR NOT TO as Material to be Categ	AND AMO A1 K/ BE REMO removed bry II	Nonfriable A	BESTOS N	MATERIALS erial NOT to be removed
A site ins VI. APPROXIMATE A Pipes (Ln. Ft.) Surface Area (Sq. Ft.) Total Volume (Cu. Ft.) Total amount on or off a components where lenguage could not be meas previously VII. SCHEDULED DA Renovation Demolition IX. FACILITY DESCI	ANALYTIC spection was AMOUNT (AMOU	AL METHODS as conducted a OF ASBESTO: Regulated ACM removed FRIPPING / RE RENOVATION (20/y/): (20/y/): 06/19/23	No SUSED TO DE North to be North CO	DETECT THE Polarized Lig MOVED AND friable Asbesto Category I tart (mm/dd/yy) ON m/dd/yy):	PRESENCE ht OFOR NOT TO as Material to be Categ	AND AMO A1 K/ BE REMO removed bry II	Nonfriable A	BESTOS N	MATERIALS erial NOT to be removed
V. PROCEDURES / / A site ins VI. APPROXIMATE / VI. APPROXIMATE / Pipes (Ln. Ft.) Surface Area (Sq. Ft.) Total Volume (Cu. Ft.) Total Volume (cu. Ft.) Total amount on or off a components where leng area could not be meas previously VII. SCHEDULED D/ Renovation Demolition IX. FACILITY DESCI Building Name: None Street Address: 530 C	ANALYTIC spection was AMOUNT (AMOU	AL METHODS as conducted a OF ASBESTO: Regulated ACM removed FRIPPING / RE RENOVATION (20/y/): (20/y/): 06/19/23	No SUSED TO DE North to be North CO	DETECT THE Polarized Lig MOVED AND friable Asbesto Category I tart (mm/dd/yy) ON m/dd/yy):	PRESENCE tht () WOR NOT TO s Material to be Categ	AND AMO AT KA	Nonfriable A Catego	BESTOS N	erial NOT to be removed Category II
V. PROCEDURES / / A site ins VI. APPROXIMATE / VI. APPROXIMATE / Pipes (Ln. Ft.) Surface Area (Sq. Ft.) Total Volume (Cu. Ft.) Total amount on or off a components where leng area could not be meas previously VII. SCHEDULED D/ Renovation Demolition IX. FACILITY DESCI Building Name: None Street Address: 530 C City: Hammond Location of removal with	ANALYTIC spection was AMOUNT (AMOU	AL METHODS as conducted a OF ASBESTO: Regulated ACM removed FRIPPING / RE RENOVATION (dayy): 06/19/23	No SUSED TO DE REI to be Nonf	DETECT THE Polarized Lig MOVED AND friable Asbesto Category I tart (mm/dd/yy) ON m/dd/yy):	PRESENCE ht OFOR NOT TO as Material to be Categ	AND AMO AT KA	Nonfriable A Catego	BESTOS N	erial NOT to be removed Category II
V. PROCEDURES / / A site ins VI. APPROXIMATE / VI. APPROXIMATE / Pipes (Ln. Ft.) Surface Area (Sq. Ft.) Total Volume (Cu. Ft.) Total amount on or off a components where lengarea could not be meas previously VII. SCHEDULED D/ Renovation Demolition IX. FACILITY DESC Building Name: None Street Address: 530 C City: Hammond	ANALYTIC spection was AMOUNT (AMOU	AL METHODS as conducted a OF ASBESTO: Regulated ACM removed FRIPPING / RE RENOVATION (dayy): 06/19/23	MOVAL S I DEMOLITI End (m	DETECT THE Polarized Lig MOVED AND friable Asbesto Category I tart (mm/dd/yy) ON m/dd/yy):	PRESENCE tht () DIOR NOT TO the Material to be Category (2023) State: I	AND AMO AT KA	OUNT OF AS UCLUIV OVED Nonfriable A Catego	BESTOS N	erial NOT to be removed Category II
A site ins Burlar Cut, Ft.) Surface Area (Sq. Ft.) Fotal Volume (Cu. Ft.) Renovation Demolifion Demolifion IX. FACILITY DESC Building Name: None Street Address: 530 C City: Hammond Location of removal with (including floor and reco	ANALYTIC spection was AMOUNT (AMOU	AL METHODS as conducted a OF ASBESTO: Regulated ACM removed FRIPPING / RE RENOVATION (dayy): 06/19/23	MOVAL S I DEMOLITI End (m	DETECT THE Polarized Lig MOVED AND Prinable Asbesto Category I Start (mm/dd/yy) ON m/dd/yy): 9/19	PRESENCE tht () DIOR NOT TO the Material to be Category (2023) State: I	AND AMO AT KA	OUNT OF AS UCLUIV OVED Nonfriable A Catego	BESTOS N	erial NOT to be removed Category II

Page 1 of 2

CS+50613 LOC 2 Seg 1

LINSCOTT

FACILITY COMPONENTS AND TYPE OF MATERIAL REMOVED						
DEMOLITION IS A RAISED STRUCTURE. REMOVE ALL C & D AND DISPOSE AT ALLIED WASTE, BRICK/IRON TO BE RECYCLED, CAP ALL SEWERS, BACKFILL WITH B-BARROW MATERIALS & BRING TO ORIGINAL GRADE.						
XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE SITE; INCLUDING ASBESTOS STRIPPING, REMOVAL AND WASTE HANDLING PROCEDURES TO PREVENT NONFRIABLE ASBESTOS MATERIAL FROM BECOMING FRIABLE IN THE COURSE OF THE PROJECT						
USE WATER TO CONTROL DUST AT SITE DURING DEMOLITION						
XII. DESCRIPTION OF PROCEDURES TO NONFRIABLE ASBESTOS MATERIAL E	O BE FOLLO SECOMES C	OWED IN THE RUMBLED, P	E EVENT UNEXPECTED ASBES PULVERIZED, OR REDUCED TO	TOS IS FOUND POWDER	OR PREVIOUSLY	
STOP JOB, CALL ASBESTOS REMOVAL CONTRACTOR, CITY AND IDEM.						
XIII. ASBESTOS WASTE TRANSPORTE		XIV. ASBESTOS WASTE DISP	OSAL SITE			
Name: RICHARDSON DISPOSAL		Name: REPUBLIC SERVICES -	NEWTON COU	NTY LANDFILL		
Address: 620 E 10TH PLACE			Address: 2266 E 500 SOUTH			
City: GARY St	tate: IN	ZIP: 46402	City: BROOK	State: IN	ZIP: 47922	
	elephone: 219)-944-4999	Contact: 219-394-7222			
E-mail; RICHDISPOSAL@GMAIL.COM			E-mail: BRIDGE@REPUBLICSE	RVICES.COM		
XV. ORDERD DEMOLITIONS						
Agency Name: Board of Public Works and S	Safety City of	Hammond	Date Ordered Demolition to Begin (mm/dd/yy): 06/19/2023			
				Telephone: 219-853-6382 E-mail: lewterw@gohammond.com		
Regulatory Authority: Board of Public Works and Safety City of Hammond Date of Order (mm/dd/yy): 10/27/22						
XVI. EMERGENCY RENOVATIONS						
Date (mm/dd/yy) and Time of Emergency:						
Description of sudden, unexpected event:						
Explanation of how the event caused unsafe conditions or would cause equipment damage:						
XVII. CERTIFICATION STATEMENT AND SIGNATURE BY OWNER / OPERATOR						
I HEREBY CERTIFY THAT THE INFORMATION IN THIS NOTIFICATION IS CORRECT AND THAT I WILL ONLY USE INDIANA LICENSED WORKERS AND PROJECT SUPERVISORS, TO IMPLEMENT THIS ASBESTOS PROJECT, WHICH HAVE BEEN TRAINED IN 326IAC 14-10; 40 CFR PART 61, SUBPART M:						
LAND IF APPLICABLE LINDIANAPOLIS AIR POLL LITION CONTROL BOARD REGULATION 14. THE TRAINED INDIVIDUAL(S) ALONG WITH EVIDENCE						
THAT THE REQUIRED TRAINING WAS ACCOMPLISHED SHALL BE AVAILABLE AT THE JOB SITE DURING ACTUAL WORKING HOURS.						
Date (mm/dd/yy): 06/14/2023 E-mail: RICHDISPOSAL@GMAIL.CO					OSAL@GMAIL.COM	
Owner operator (Sidhature)						
Alfred Richardson Title: Demolition Contractor						
Owner / operator (Printed)						

The Harbor Group, Inc.

Environmental Services 10314 Applewood Court Munster, Indiana 46321 219-670-2912

December 20th, 2022

Hammond Department of Environmental Management 5925 Calumet Avenue
Hammond, Indiana 46320

Re: 530 Conkey Street Hammond, IN (commercial building)

Attention: Ron Novak

On December 15th, 2022 an inspector from Harbor Group, Inc., visited the above referenced location to inspect the building for Asbestos Containing Materials (ACM), prior to demolition, in accordance with Indiana Department of Environmental Management (IDEM) 326 IAC Article 14 Rule 10, and EPA National Emission Standard for Hazardous Air Pollutants (NESHAP) 40 CFR 61.145.

The building structure is unsafe and cannot be safely inspected. A licensed inspector has to be on site during demolition.

Respectfully,

Antonios Uiatras

Antonios Yiatras Inspector # 19A012409) Expiration 08/19/2023

2022-544175 11/01/2022 11:05 AM TOTAL FEES: 25.00 BY: SP PG #: 4 STATE OF INDIANA LAKE COUNTY FILED FOR RECORD GINA PIMENTEL RECORDER

STATE OF INDIANA)	BEFORE THE BOARD OF PUBLIC WORKS
) ss	AND SAFETY
COUNTY OF LAKE)	CITY OF HAMMOND, INDIANA

IN RE THE PROPERTY LOCATED AT: 530 Conkey Street, Hammond, IN 46324

LEGAL DESCRIPTION: LOT 1 IN BLOCK 7 IN FRANKLIN ADDITION, IN THE CITY OF HAMMOND, AS PER PLAT THEREOF, RECORDED IN PLAT BOOK 4, PAGE 16, IN THE OFFICE OF THE RECORDER OF LAKE COUNTY, INDIANA.

Key No.: 45-06-01-410-001,000-023

Owner: Juan Garcia and Maria G. Garcia

FINDINGS AND ORDER

COMES NOW the Hammond Board of Public Works and Safety, the statutory designated Hearing Authority, acting under the authority of the Unsafe Building Act, Indiana Code 36-7-9-1 et seq., and in response to the Notice to Repair or Demolish issued by the Hammond Inspections Department, by its Building Commissioner, on October 3, 2022, now finds as follows:

- The matter appears before the Board of Public Works and Safety, brought by the Hammond Inspections Department, as Enforcement Authority (I.C. 36-7-9-2) by its Building Commissioner.
- 2. The City of Hammond, through its Enforcement Authority, has identified the above listed property as being a building or structure that is unsafe to person or property; a fire or health hazard; a public nuisance and due to condition or vacancy in violation of City Ordinance concerning Building Condition or Maintenance (I.C. 36-7-9-4).3. Pursuant to these findings and acting to eliminate blight and protect public health and safety, the Enforcement Authority issued notice of the condition of the above listed property and

- required that the above listed property be repaired or demolished, pursuant to I.C. 36-7-9-5.
- 4. This Notice to Repair or Demolish complied with I.C. 36-7-9-5 and contained the required information including in part, the name of the person to whom the ordered was issued, a legal description and common address of the unsafe premises, the action requested on the unsafe property, the time frame permitted for compliance and notice of the time, date and place of a scheduled hearing before the Hammond Board of Public Works and Safety.
- 5. Service was made upon all parties possessing a known or recorded fee interest, life estate interest, substantial property interest, or equitable interest in the above listed property, as determined from information maintained by the Lake County Recorder.
- 6. Service on the above listed property was made upon, in the following manner:

Juan Garcia and Maria G. Garcia, Certified Mail, Regular Mail, Publication;

Lake County Treasurer, Certified Mail;

Lake County Commissioners, Certified Mail;

Any and All Unknown Tenants Certified Mail, Regular Mail and Publication, Posting Notice on the premises.

This above manner of service complies with the statutory requirements, and the Hearing Authority determines that a reasonable effort has been made to obtain service.

7. A hearing on the Notice and Order to Repair or Demolish was held before the Hammond Board of Public Works, pursuant to I.C. 36-7-9-7 on Thursday, October 27, 2022 at 9:00 a.m., and was conducted on that date by the hearing

- authority at a public meeting.
- 8. No person, to whom the Notice and Order to Repair or Demolish was issued, appeared at the hearing, nor any party having a substantial property interest in the unsafe premises appeared, in person or by counsel, nor was there requested a continuance or rescheduling of the hearing by any party.
- 9. The property listed above was not substantially repaired nor demolished by the property owner prior to the scheduled hearing and the Notice and Order to Repair or Demolish issued by the Hammond Inspections Department proposes demolition of the unsafe property above, and that recommendation is reasonably related to the condition of the property, the failure of the owners of the property to remedy the condition and given the nature and use of nearby properties (36-7-9-5).
- 10. Demolition of the unsafe property is necessary and reasonable in relation to the present condition of the property, which requires services of the government in excess of ordinary property, and which creates a negative effect on property values, as well as affects the quality of life, and use, of the surrounding area in the City of Hammond.

NOW THEREFORE it is the finding and decision of the Hammond Board of Public Works and Safety to AFFIRM the Notice and Order to Repair and Demolish issued by the Enforcement Authority on the above named unsafe building. This affirmation shall be an ORDER to demolish the structure which shall be recorded in the office of the Recorder of Lake County, Indiana, with demolition of the property to subsequently follow. The costs of this demolition shall be assessed against the property and shall constitute a lien on the property.

SO ORDERED this 27th day of October, 2022.

		Hammond Board of Public Works and Safety			
•	Ву:	President, Kevin L. Margraf			
		Vice President, Jeffery Long			
		Ela Nuestras			
		Member, Eva Huerta			
State of Indiana)				
)SS				
County of Lake)				
Before me the undersigned, a Notary Public for the State of Indiana personally appeared Kevin L. Margraf, Jeffery Long and Eva Huerta and being duly sworn by me upon their oath says that the facts alleged in the foregoing instrument are true. Signed and sealed this 27th day of October, 2022.					

IN WITNESS WHEREOF, I have hereunto subscribed my name and affixed my official seal.

My Commission Expires: January 23, 2025

County of Residence: Lake

Lake County

My Commission Expires

January 23, 2025

Notary Public

Notary Public

Amage 23, 2025

I affirm, under the penalties for perjury, that I have taken reasonable care to redact each and every Social Security Number in this document, unless required by law.

Kevin C. Smith

This instrument prepared by: Kevin C. Smith (#18169-45), SMITH SERSIC, LLC, 9301 Calumet Avenue, Suite 1F, Munster, IN 46321, Telephone Number 219-933-7600.