

UNDERGROUND STORAGE TANK INSPECTION REPORT

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT


UST FAC ID: 12535

Inspector's Name:	Matt Rozycki
Date:	June 20, 2024
Time In:	10:20
Time Out:	10:40
Inspection Type:	Initial

FACILITY NAME / LOCATION										
FACILITY NAME FACILITY ADDRESS (number and street)										
	ladison Street Departm	1215 N Waln		Izin oon		Inchite the second				
ADDRESS (line 2	()	Madison		STATE IN	ZIP CODE 47	- 7250	COUNTY	erson		
			TOWNER	11 4	17	200	Oone	010011		
UST OWNER UST Owner Name (If in Individual Capacity) BUSINESS ID (From the Secretary of State)										
City of M	ladison									
PREFIX	FIRST NAME	MI	LAST NAME					SUFFIX		
TE! EB! 101/E 1//	Tony	January 1999	Sorrels							
TELEPHONE NU	TELEPHONE NUMBER EMAIL ADDRESS Streetsec@madison-in.gov									
UST OPERATOR										
UST Operator Name (If in Individual Capacity) BUSINESS ID (From the Secretary of State)										
City of M	ladison Street Departm	nent								
PREFIX	FIRST NAME	MI	LAST NAME					SUFFIX		
	Tony		Sorrels							
TELEPHONE NU	MBER	EMAIL ADDRESS	nadison-in dov							
streetsec@madison-in.gov PROPERTY OWNER										
UST Property Ov	vner Name (If in Individual Capacity)	Phop	ENTYOWNER		E	BUSINESS I	D (From the Sec	retary of State)		
City of M										
PREFIX	FIRST NAME	MI	LAST NAME					SUFFIX		
	Tony		Sorrels							
TELEPHONE NU	MBER	EMAIL ADDRESS	nadison-in.gov							
COMPLIANCE ELEMENTS All USTs properly registered and up-to-date notification form on file YES X NO UNK										
								LIONK		
Updated notification form with the proper overfill prevention method O/O is in compliance with reporting & record keeping requirements YES X NO							UNK			
O/O is in compliance with reporting & record keeping requirements YES X NO UNDESTRUCTION VES X NO VES X NO								1 JOHN		
						1	UNK			
0/0 13 111 00	impliance with release reporting	ig of investigation					/ /	1 101111		
O/O is in co	mpliance with all LIST closure	requirements			YES	X NO	N/A	UNK		
O/O is in compliance with all UST closure requirements Closure documentation for the tank removed in 1992 has not been provide							110/74	1 10.11.		
					YES	NO	N/A	UNK		
The first an interior responsionity requirements							1 1 2 1 1 1 1			
40 CFR 280	D, Subpart A installation requir	ements (partially e	xcluded) met	ΤX	YES	NC	N/A	UNK		
10 of the 200, Compare to the international of the								' '		
40 CFR 280), Subpart B installation and u	pgrade requiremer	nts met	ΤX	YES	NO		UNK		
	, ,	1		1,,,						
40 CFR 280), Subpart C spill/overfill contro	ol requirements me	 et	IX	YES	NO	N/A	UNK		
	· · ·	•		1		<u>-</u>	-!!	' '		
40 CFR 280), Subpart C compatibility requ	irements met		- X	YES	NO	N/A	UNK		
					!!	<u> </u>		•		
40 CFR 280, Subpart C O&M and testing requirements met										
Spill bucket test, overfill functionality test, monthly / annual walkthroughs not provided										
40 CFR 280, Subpart D release detection requirements met YES X NO UNK										
ATG/probe functionality test, leak detector test										
40 CFR 280, Subpart J operator training requirements met										
Operator A B & C certificates were not provided										



Imagery ©2024 Airbus, Maxar Technologies, Map data ©2024 100 ft



Imagery ©2024 Airbus. Maxar Technologies. Map data ©2024 50 ft













