SPILL REPORT							
SPILL NO:							
BASIC SPILL INFORMATION							
Date					Spill		
Discovered: 6/	/12/2024				End:	6/17/	2024
Address:			6462 Ar	6462 Ameritech Dr.			
City/Township:		South Be	nd State:		State:	IN	
County/Parish:			St Joe				
Product Spilled: Deis	sel Fuel, Coc	olant, Engine Oil	Amount Spilled:	Unkno	own	Amount Recovered:	100%
Is equipment labelled NON-PCB? (Yes/No)			N/A				
Is product NON-PCB? (Yes/No):			N/A				
Reportable Quantity:			Yes				
Describe Cause of Spill:			Truck Fire				
AFFECTED AREAS							
Area Affected:		Commercial					
Surfaces Affected:		Asphalt	S	Soil		Concrete	
CLEAN UP ACTIONS							
Visible Traces Present? (Yes/No)			Yes				
Area of Spill (Sq. ft.):		2630	Depth of So	Depth of Soil Removed (in.):		6-Apr	
Explanation of Cleanu	up Actions:	fuel on the road. Once the crew arrived on site, the crew assested the site and came up with a process to get the impacted areas cleaned up. First the crew used a 3000 gal vac trcuck to vac up appox. 150 gals of liquid in the road. After that the crew spread Oil Dry to absorb the liquid in on the concrete and asphalt. The next day the crew came back and swept up all the Oil Dry. We spread more Oil Dry in the areas that needed more. The crew used brooms to scrub in the Oil Dry. Than swept up. The crew used Hydro Vac to vac out the drywells using soapy water to clean them. Once the asphalt, concree, and drywells were cleaned up, the crew used the Hyro Vac to excavte all contaminated soil. There was					
		COLLECTED D	DEBRIS INFO	RMATION			
How was the debris con		Stock pile					
Total number of containers used:							
Description of Debris:		Deisel / Coolant / Oil					
Analytical Results:	:			Disposal Facility:		Elkhart Co. Landfill	
Site Supervisor Sign Off:			Manager S	Manager Sign Off: Nick Nowicki		owicki	







