



# BYPASS / OVERFLOW INCIDENT REPORT

State Form 48373 (R9 / 7-22)  
Indiana Department of Environmental Management  
Office of Water Quality

Follow-up to Bypass report  
previously sent on: \_\_\_\_\_

**INSTRUCTIONS:** Complete all parts of this form and e-mail signed copies to [wwreports@idem.IN.gov](mailto:wwreports@idem.IN.gov). Submittal of this report will satisfy the Office of Water Quality (OWQ) telephone and written bypass/overflow reporting requirements of your NPDES permit. Please use and the second page of this form as necessary to identify separate locations caused by the same event. If you have any questions while filling out this form, please call (317) 232-7150.

To report a spill or if the release is resulting in a fish kill or other severe environmental damage, immediately report the release to the Emergency Response Section spill response line at: (317) 233-7745 or toll free within Indiana at (888) 233-7745.

GENERAL INFORMATION					
(1) Facility Name (Organization) Town of Veedersburg		(2) Mailing Address (reporting organization) 100 S. Main Street, Veedersburg, IN 47987		(3) County Fountain	(4) NPDES Permit IN0024716
RELEASE INFORMATION (Location 1)					
(5) Outfall Number	(6) Date (mm/dd/yy) and Time Release Began	(7) Date (mm/dd/yy) and Time Release Stopped	(8) Location of Release (streets address or Manhole, Lift Station, Force Main etc.)	(9) Latitude (Deg Min Sec)	(9) Longitude (Deg Min Sec)
	06-30-24 4:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	07-01-24 10:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	Manhole #52	40.1086095	-87.2669255
(10) Amount of Flow Released (Always provide a volume.) Check one: <input checked="" type="checkbox"/> Estimated <input type="checkbox"/> Actual			(11) WWTP Flow During Release	(12) WWTP Peak Design Flow Rate	
2000 Gallons			0.250 MGD	1.8 MGD	
(13) Overflow Type (Select one.) <input checked="" type="checkbox"/> Sanitary Sewer Overflow <input type="checkbox"/> Treatment Bypass (at wastewater plant) <input type="checkbox"/> Prohibited Combined Sewer Overflow <input type="checkbox"/> Dry Weather Combined Sewer Overflow <input type="checkbox"/> Combined Sewer System Release			(14) Describe any damage to aquatic life or receiving stream: None		
(15) Reason for Bypass / Overflow (Select one or more.) <input type="checkbox"/> Construction Related <input type="checkbox"/> Power Failure <input type="checkbox"/> Equipment Failure <input type="checkbox"/> Unknown <input type="checkbox"/> Exceeded Max Capacity <input type="checkbox"/> Precipitation Inches					
(16) System Component(s) (Select one or more.) <input checked="" type="checkbox"/> Manhole <input type="checkbox"/> House Lateral <input type="checkbox"/> Pipe Failure <input type="checkbox"/> Pump Station Failure <input type="checkbox"/> Treatment Bypassed <input type="checkbox"/> Other <input type="checkbox"/> Influent Structure <input type="checkbox"/> Air Relief Valve <input type="checkbox"/> Sewer Clean Out  Describe Other: (in the box below)		(17) Additional Description of the Bypass / Overflow Event: Resident called in 07-01-24. Noticed seepage coming out of manhole. Stated he noticed it at 4:00 pm the night before. Contained to a 10' radius around manhole. Sewer main line plugged. Jetted to unclog. Wipes were found in the line.		(18) Description of the Area Impacted (Check all that apply.) <input checked="" type="checkbox"/> Affected Private Property <input type="checkbox"/> Basement Backup <input type="checkbox"/> Occurred at Treatment Plant <input type="checkbox"/> Reached Public Land <input type="checkbox"/> Reached Receiving Water  Name of Receiving Water Impacted: None	
(19) Additional organizations notified by facility, if necessary (Select one or more.) <input type="checkbox"/> IDEM Emergency Response <input type="checkbox"/> Health Department <input type="checkbox"/> DNR Fish and Wildlife <input type="checkbox"/> Local Emergency Management <input type="checkbox"/> Other:					
(20) Actions Taken to Prevent, Minimize, or Mitigate Damage including Clean-up and Treatment of Affected Area (Select one or more of the following, then add a written description.) <input checked="" type="checkbox"/> Removed Blockage <input type="checkbox"/> Repaired Pipe <input type="checkbox"/> Repaired Pump Station <input type="checkbox"/> Other <input checked="" type="checkbox"/> Lime <input type="checkbox"/> Clean-Up Debris  Jetted line to remove clog. A lot of wipes were found in the line.					
(21) Resolution: Actions Taken or Planned to Prevent Recurrence					

(22)

## CERTIFICATION AND SIGNATURE

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (The area below is for a handwritten signature or an electronic substitute. Scan the completed form to PDF and e-mail to [wwReports@idem.IN.gov](mailto:wwReports@idem.IN.gov))

SIGNATURE: <u>Connie S. Sichta</u>		DATE (month, day, year): <u>07-01-24</u>	
Individual Making Report (printed) Connie S. Sichta	Telephone Number 765-299-5136	Contact E-mail v-burgwwtp@att.net	Date (month, day, year) / Time IDEM Notified 07-01-24 1:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM