



**CONFINED FEEDING OPERATION
Construction Inspection Report**
INDIANA DEPARTMENT OF
ENVIRONMENTAL MANAGEMENT

Inspector's Name:	Mike Sonnefeld
Others Present	
Date:	Tuesday, July 2, 2024
Time In:	10:00 AM
Time Out:	11:30 AM
Inspection Type	Construction

General Information

Facility Information

Facility Name	River Valley
Facility Location	6555 N Dubois Road NE Dubois, IN 47527 Dubois County
Facility Mailing Information	PO Box 157 Dubois, IN 47527
Facility Contact During Inspection	Mark Eisenhut 812 678 3131 marke@wabashvalleyproduce.com
Owners Contact During Inspection	Same as Facility Contact
Construction Contact	Knepp Construction

Facility ID

NPDES Permit Number	
CFO Approval	188

Farm Information

Animals Present	Yes
Bio-Security Procedures Followed	Yes
Animals Type	Layers

Approved Structures

Date Permit Approved	Monday, May 20, 2024
Date Permit Expires	Sunday, May 20, 2029
Construction Notification Date	Saturday, May 18, 2024
Number of Permitted Structures	8
Number of Structures Completed	6
Number of Structures Under Construction	2

Special Permit Conditions

Permit Conditions	<input checked="" type="radio"/> Yes <input type="radio"/> No
Special Permit Requirement(s)	Contain wash/disinfectant waters. Stockpiling manure. Manure stacking setbacks. See special approval conditions in the 5/20/2024 approval.

Approved Construction Plans	
Approved Plans Being Used by the Contractor	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown
Comments	
Deviations From Approved Plans	<input type="radio"/> Yes <input type="radio"/> No <input checked="" type="radio"/> Unknown
Comments	

Stage of Construction	
Stage of Construction	
Comments	<p>P1 Concrete footings/foundations placed. Concrete perimeter wall placed. Concrete slab not placed.</p> <p>P2 Completing placement of the concrete footings/foundations. Reinforcing steel set in concrete.</p>

Manure Management Systems	
Type of Manure Management System	Dry Manure Storage Shed
Construction Status	

Drainage/Water Runoff	
Field drainage tiles properly blocked, removed, and re-directed.	<input type="radio"/> Yes <input type="radio"/> No <input checked="" type="radio"/> Not Applicable <input type="radio"/> To Be Constructed at a Later Date <input type="radio"/> Unknown
Runoff from barn floors and leachate storage directed away from surface drainage-ways.	<input type="radio"/> Yes <input type="radio"/> No <input checked="" type="radio"/> Not applicable
Roof drainage directed away from structures.	<input type="radio"/> Yes <input type="radio"/> No <input checked="" type="radio"/> Not Applicable

Checklist (Checked box indicates a compliance concern)	
Approval and Performance Standards <input type="checkbox"/> No Valid Approval <input type="checkbox"/> Access Denied <input type="checkbox"/> Notice and Changes <input type="checkbox"/> Approval Conditions <input type="checkbox"/> Individual Permit Conditions	Discharge and Spill Requirements <input type="checkbox"/> Unpermitted Discharge/Spill

General Comments
Submit the Completed Construction Affidavit(s) as required by general approval condition 10 in the 5/20/2024 approval.

Description of Violation(s) and Further Actions

Inspection Results/Action	
Deficiency/Violations	
No Violation(s) Discovered	
Additional Comments/Other	

Inspection Documentation	
Photographs	<input checked="" type="radio"/> Yes <input type="radio"/> No
Map	<input type="radio"/> Yes <input checked="" type="radio"/> No
Pollution Prevention Opportunities	
P2	
GPS Location Collected	<input type="radio"/> Yes <input checked="" type="radio"/> No

Finalize Inspection		
Written Summary of Inspection		
Inspector Information	Printed/Typed Name	Mike Sonnefeld
	Phone Number:	(317) 727-6904
	Email Address:	msonnefe@idem.in.gov
	Signature:	
Facility Representative Signature	Printed/Typed Name:	
	Signature:	Signature obtained on the Notice of Inspection

Photo Table



Number	1
Description	Standing at the north east corner of P2, manure storage, looking south west at footings/foundations and wall reinforcing steel.
Photographer	Mike Sonnefeld
Facility Name	River Valley
Photo Date	July 2, 2024



Number	2
Description	Standing at the north west corner of P2, manure storage, looking south at footings/foundations and wall reinforcing steel.
Photographer	Mike Sonnefeld
Facility Name	River Valley
Photo Date	July 2, 2024



Number	3
Description	Standing at the south east corner of P2, manure storage, looking west at just placed footings/foundations concrete and wall reinforcing steel.
Photographer	Mike Sonnefeld
Facility Name	River Valley
Photo Date	July 2, 2024



Number	4
Description	Standing at the south east corner of P2, manure storage, looking north at footings/foundations and wall reinforcing steel.
Photographer	Mike Sonnefeld
Facility Name	River Valley
Photo Date	July 2, 2024



Number	5
Description	P2 wall footing with reinforcing steel.
Photographer	Mike Sonnefeld
Facility Name	River Valley
Photo Date	July 2, 2024



Number	6
Description	East end of P1 layer barn looking west at wall and aggregate base for concrete slab.
Photographer	Mike Sonnefeld
Facility Name	River Valley
Photo Date	July 2, 2024