

317.916.8000 • www.augustmack.com 1302 North Meridian Street, Suite 300 • Indianapolis, Indiana 46202

June 7, 2024

Mr. Syed Jaffery Project Manager Office of Land Quality State Cleanup Section 100 N. Senate Avenue, IGCN, Room 1101 Indianapolis, IN 46204

**Re:** Response to IDEM Comments

**Former Classic Cleaners** 

8641 Bash Street

Indianapolis, Marion County State Cleanup Site #0000571

August Mack Job Number JW2594.750

Dear Mr. Jaffery:

August Mack Environmental, Inc. (August Mack) has prepared this submittal in response to the Indiana Department of Environmental Management (IDEM) comment letter, *IDEM Vapor Intrusion*, dated February 15, 2024, pertaining to the above-referenced Site. This submittal provides relevant background information and specific responses to IDEM comments.

### Responses to IDEM's February 2024 Comments

IDEM's comments are provided below, in italics, followed by August Mack's responses.

### IDEM Comment #1:

On August 8, 2022, IDEM issued a comments letter (VFC #83353911), regarding potential vapor intrusion (VI). In response to IDEM's letter, SESCO conducted paired indoor air (IA) and subslab soil gas (SGss) sampling in October 2022, and subsequently submitted the VI Report. During this sampling event, three paired IA/SGss, and one outdoor ambient air (AA) sample were collected. In addition, two sewer cleanout samples were also collected.

### **August Mack Response:**

August Mack acknowledges this comment.

#### IDEM Comment #2:

The IA and AA samples were collected into 6-liter batch certified Summa canisters over

approximately 8 hours while SGss samples were collected into 1-liter Summa canisters over an approximately 5-10-minute period. Start and end sampling times along with the initial, final, and laboratory vacuum measurements of the Summa canisters were recorded. The IA, SGss, and AA samples were analyzed for volatile organic compounds (VOCs) by EPA Method TO-15 while sewer cleanout samples were analyzed for VOCs by EPA Method TO-17. The reporting limits were supportive of R2 published levels (PLs). IDEM has determined that the methods used for sampling and analysis were acceptable.

### **August Mack Response:**

August Mack acknowledges this comment.

### IDEM Comment #3:

Tetrachloroethylene (PCE) and trichloroethylene (TCE) were detected in a SGss sample, SS-2, at concentrations of 246 micrograms per cubic meter ( $\mu$ g/m3) and 48.9  $\mu$ g/m3, respectively. However, these concentrations did not exceed PCE's and TCE's respective residential sub-slab published levels (RSSPLs). All other VOCs were reported as non-detect in IA, SGss, and AA samples. While no PL exceedances occurred in either the SGss or IA samples, TCE exceeded the commercial sewer conduit PL of 300  $\mu$ g/m3 at a sewer cleanout sample, Sewer Cleanout-2, with a concentration of 664  $\mu$ g/m3. For this reason and considering exterior soil-gas (SGe) exceedances of commercial soil-gas published level (CSGPL) at samples SG-1 and SG-2 during 2021 sampling, a vapor remedy is warranted.

### **August Mack Response:**

August Mack acknowledges this comment.

#### IDEM Comment #4:

Field duplicate samples were collected from IA-1 and SS-1. Field duplicate sample results compared well. Analytical reports were submitted with Level IV quality assurance and quality control (QA/QC) documentation. IDEM has determined that Level IV QA/QC documentation was not necessary; per Section 2.2.9 (Table 2-B) of the R2, laboratory reports should be submitted with QA/QC documentation that meets the R2 Level II elements.

### **August Mack Response:**

August Mack acknowledges this comment.

### **IDEM Comment #5**:

In February 2023, August Mack oversaw pilot testing for designing and installing a sub-slab depressurization system (SSDS) to mitigate VI exposure pathway. Subsequently, an operation, maintenance, and monitoring plan (OM&M Plan) for this SSDS was developed and submitted to IDEM along with the Summary Report. As reported, the pilot test included the installation of two extraction points (EP-01 and EP-02) and 20 test points (TP-01 through TP-20) to measure vacuum response. During the pilot test, a vacuum at a measured flow rate was applied to the extraction points while the test points were measured for negative pressure. In March 2023, based on the pilot test results, August Mack oversaw the installation of an SSDS in the former Classic

Cleaners tenant space consisting of four extraction points manifolded to one mitigation fan.

### **August Mack Response:**

August Mack acknowledges this comment.

### IDEM Comment #6:

On March 13, 2023, August Mack informed IDEM that the SSDS installation was completed on March 10, 2023, and expressed their intention to perform the system confirmatory VI sampling within one week to satisfy the requirements of the 'winter worst-case' sampling scenario.

### **August Mack Response:**

August Mack acknowledges this comment.

### *IDEM Comment #7:*

On March 15, 2023, IDEM provided the following response: "In accordance with Section 4.2.3.1 of IDEM's non-rule policy document, Risk-Based Closure Guide (R2), dated July 8, 2022, an equilibration period, which is 30 days as a standard, is necessary before confirmatory indoor air sampling and performance metrics are collected. Therefore, we require that August Mack must wait 30 days from the SSDS installation completion date, which you mentioned was last Friday March 10, 2023, before conducting confirmatory indoor air sampling and collecting performance metrics. This will allow the sub-slab area to reach steady-state conditions." IDEM further stated: "For your question on the 'Winter Worst-Case' sampling scenario, August Mack can provide lines of evidence as to why April should be considered a winter worst case event, such as a 10- degree temperature differential. Please refer to R2 Section 2.2.6.6 for further details and description."

### **August Mack Response:**

August Mack acknowledges this comment. As outlined in IDEM comment #14 below, August Mack returned to the Site in July 2023 to conduct a sampling which served as the 30 days post SSDS installation event. In addition to the July 2023 sampling event, August Mack returned to the Site in April 2024 to complete a winter worst case sampling event. The April 2024 winter vapor intrusion sampling report is included as **Attachment B**.

### IDEM Comment #8:

The Summary Report indicates that as part of the system verification, August Mack conducted a VI sampling event on March 21, 2023, which was less than two weeks from the installation of the SSDS. According to Section 4.2.3.1 of the R2 an equilibration period (30 days is standard) is necessary before confirmatory IA sampling and performance metrics are collected.

### **August Mack Response:**

August Mack acknowledges this comment. As outlined in IDEM comment #14 below, August Mack returned to the Site in July 2023 to conduct a sampling event which serves as the 30-day post SSDS installation sampling event sampling event.

### IDEM Comment #9:

During the March 2023 sampling event, three IA samples (IA-1 thru IA-3) and one AA sample were collected. These samples were collected into 6-liter batch certified Summa canisters over approximately 8 hours. Start and end sampling times along with the initial, final, and laboratory vacuum measurements of the Summa canisters were recorded. These samples were analyzed for VOCs by EPA Method TO-15. IDEM has determined that the methods used for sampling and analysis were acceptable. The reporting limits were supportive of R2 PLs.

### **August Mack Response:**

August Mack acknowledges this comment.

### IDEM Comment #10:

During this sampling event, the VOCs were reported as non-detect in all IA and AA samples, indicating that no IAPL exceedances occurred during the March 2023 IA 'winter worst case scenario' sampling event.

### **August Mack Response:**

August Mack acknowledges this comment.

### IDEM Comment #11:

A field duplicate sample was collected from IA-3. Field duplicate sample results compared well. The laboratory report was submitted with QA/QC documentation which met the R2 Level II elements.

### **August Mack Response:**

August Mack acknowledges this comment.

### IDEM Comment #12:

IDEM has determined that generally the OM&M Plan conforms to IDEM's Technical Guidance Document Vapor Mitigation Systems, dated October 2021; however, it does not provide a long-term IA monitoring schedule. The soil gas data indicates the potential need for a long-term remedy to mitigate the on-site vapor risk. Therefore, the OM&M plan must identify a long-term monitoring schedule, such as Schedule 1 or 2, if the system will act as a long-term remedy to vapor risk on-site. If long term remedy is not the system's intended purpose, then August Mack must provide a further clarification as to how the potential vapor risk will be addressed.

### **August Mack Response:**

August Mack acknowledges this comment. The updated OM&M plan is included as **Attachment A**.

### IDEM Comment #13:

The VI Report indicates that the highest SGe concentrations are outside of the building's footprint and not under the sub-slab; therefore, it is unclear whether the SSDS influences the vapor source. Consequently, an explanatory description is required.

### **August Mack Response:**

The SSDS was designed to mitigate any potential vapors that may be present under the structure's slab from entering the habitable space of the on-Site structure; the SSDS was not designed to influence the vapor source. Additionally, analytical data collected during IA sampling events conducted following SSDS installation confirms the efficacy of the SSDS regarding mitigation of the VI exposure pathway.

#### IDEM Comment #14:

In July 2023, August Mack conducted another round of IA sampling. Since this sampling event was performed more than 30 days after the SSDS installation, it satisfies the requirements of R2 Section 4.2.3.1.

### **August Mack Response:**

August Mack acknowledges this comment.

### IDEM Comment #15:

The Summary Report indicates that the pressure field extension results showed several points with vacuums below the minimum vacuum limit of 0.004 inches-water. However, no release related chemicals (RRCs) were detected in IA, and all surface cracks, drains, and other potential vapor entryways were plugged or sealed. IDEM has determined that as long as the IA levels remain below PLs, and all necessary OM&M repairs and maintenance are performed appropriately, the current operation of the SSDS may continue. However, if IA levels exceed the PLs then modifications to the SSDS will be necessary.

### **August Mack Response:**

August Mack acknowledges this comment.

Please do not hesitate to contact us at 317-916-8000 should you have any questions or comments.

Sincerely,

Jeremiah Miller Project Manager Zach Ramey, LPG Practice Leader

### ATTACHMENT A

### Updated August Mack OM&M Plan



317.916.8000 • www.augustmack.com 1302 North Meridian Street, Suite 300 • Indianapolis, Indiana 46202

June 5, 2024

Mr. Michael McFarland c/o Mr. Nick Gahl Cardinal Industrial San Diego 2131 Palomar Airport Road, Suite 360 Carlsbad, CA 92011

RE: Sub-Slab Depressurization System

**Operation Maintenance and Monitoring Plan** 

**Former Classic Cleaners** 

8641 Bash Street

Indianapolis, Indiana 46256

State Cleanup Site Number 0000571 August Mack Project No: JW2594.750

Dear Mr. McFarland:

August Mack Environmental, Inc. (August Mack) is pleased to submit the attached Sub-Slab Depressurization System (SSDS) Operation Maintenance and Monitoring Plan (OMM Plan) for the SSDS installed at the Former Classic Cleaners Building located at 8641 Bash Street in Indianapolis, Indiana. This plan has been prepared in accordance with August Mack proposal dated January 20, 2023, and follows the general requirements of the Indiana Department of Environmental Management's (IDEM's) Technical Guidance Document entitled *Vapor Mitigation Systems* revised in October 2021, and the Draft Interim Guidance Document entitled *Vapor Remedy Selection and Implementation* revised in July 2019.

Please contact us if you have any questions concerning the contents of this plan.

Sincerely,

Jeremiah Miller

Project Manager

Christopher S. Abel, CHMM

Senior Environmental Chemist

Zach Ramey, LPG Practice Leader

### Operation, Maintenance and Monitoring Plan for Sub-Slab Depressurization System Former Classic Cleaners 8641 Bash Street Indianapolis, Indiana

### **Prepared For:**

Cardinal Industrial San Diego 2131 Palomar Airport Road, Suite 360 Carlsbad, CA 92011

Prepared By:

August Mack Environmental, Inc. 1302 North Meridian Street, Suite 300 Indianapolis, Indiana 46202

### INTRODUCTION

August Mack Environmental, Inc. (August Mack), on behalf of Cardinal Industrial San Diego (CISD), has prepared this Operation, Maintenance, and Monitoring Plan (OMM Plan) describing the operation, maintenance, and monitoring procedures for the Sub-Slab Depressurization System (SSDS) installed at Former Classic Cleaners Building. The Former Classic Cleaners Building is located at 8641 Bash Street in Indianapolis, Indiana (Site). This OMM Plan follows the general requirements of both the Indiana Department of Environmental Management's (IDEM's) Technical Guidance Document entitled *Vapor Mitigation Systems* revised October 2021, and IDEM's Draft Interim Guidance Document entitled *Vapor Remedy Selection and Implementation* revised in July 2019.

The OMM Plan includes the following sections:

- Background Information;
- System Design and Installation Details;
- Indoor Air Monitoring Plan;
- System Monitoring Details;
- System Maintenance Details; and,
- System Termination Details

### **BACKGROUND INFORMATION**

The Site is located at 8641 Bash Street, in the northeast portion of Indianapolis in an area of commercial and industrial development. The Site consists of one parcel, encompassing 1.80-acres and is developed with a single-story, approximately 41,140-square-foot, multi-tenant commercial building in the northeast portion of the property extending off-Site to the northeast.

The building was reportedly constructed in 1985. Classic Cleaners operated the drycleaning operation at the Site from 1988 to mid-November 2015. Classic Cleaners reportedly began occupying approximately 4,250 square feet of the south side of the Site building (current tenant spaces 8621 and 8629) in 1988. From 1988 through 2006, Classic Cleaners incrementally expanded its operations to include tenant spaces 8621 through 8633, 8621 through 8645, and 8621 through 8649.

Historical investigations beginning in 2016 revealed concentrations of the volatile organic compounds (VOCs) at the Site. Tetrachloroethene (PCE) and trichloroethene (TCE) were identified in the soil but was below the IDEM 2023 Risk-based Closure Guide (R2) Short Term excavation Human Health Published Levels (PLs). PCE and TCE were identified in groundwater above the IDEM 2023 R2 Long Term Residential PLs.

Historical vapor investigations of the exterior soil gas (SGe) and Site building sub-slab soil gas (SGss) samples identified concentrations above the IDEM 2023 R2 Residential Sub-slab Published Levels and Commercial Sub-slab Published Levels. However, while there has been applicable PL exceedances in the SGss for the Site building there have not been PCE or TCE exceedances in indoor air (IA) samples above applicable PLs. The historical IA, outdoor air (OA), and SGss results collected by SESCO are provided in **Attachment A.** 

Based on the historical investigations performed at the Site by SESCO Group, the former Classic Cleaners would fall into Scenario 3. As outlined in the IDEM R2, Scenario 3 indicates a significant potential for future VI based on investigative results and requires the responsible party to either implement a remedy or undertake long term confirmation sampling. In order to address this concern, a sub-slab depressurization system (SSDS) was installed at the Site.

August Mack subcontracted Vapor Intrusion Specialists, LLC (VIS) for the pilot testing and SSDS installation at the Site. VIS mobilized to the Site on February 9, 2023 to conduct pilot testing. The pilot test included the installation of two extraction points (EP-01 and EP-02) and 20 test points (TP-01 through TP-20). During the pilot test a vacuum at a measured flow rate was applied to the extraction points while the test points were measured for negative pressure. Based on the data collected during the pilot test, the SSDS was designed to adequately remediate the Site building. The data collected from this pilot test was used to design the on-Site SSDS.

August Mack returned to the Site from March 6 through March 10th, 2023, to install the SSDS. Additional details about the system design and installation are provided in the section below. CISD is committed to proper operation of the active SSDS installed at the building. This OMM Plan outlines the SSDS maintenance and monitoring to be performed by CISD.

### SYSTEM DESIGN AND INSTALLATION DETAILS

VIS remobilized to the Site from March 6 through March 10<sup>th</sup>, 2023 to install the SSDS. The system features approximately 180 linear feet of 4-inch Schedule 40 PVC pipe installed into the building slab at the four extraction points suction pits(EP-01 through

EP-04): three extraction points located adjacent to the center support pillars and one extraction point located adjacent to the western wall. All extraction point vertical pipes manifold together to a main horizontal pipe run routing from north (EP-01) to south (EP-02 & 03, EP-04 on western wall). Exhaust piping then runs vertically to the roof, to a mitigation fan (Obar® GBR 76UB) which discharges vapors above the building. The mitigation fan maintains a measurable vacuum¹ on the SSDS. One digital gauge was installed at each extraction point vertical. Design drawings for the SSDS are provided in **Attachment B**. Details for the Obar® GBR 76UB mitigation fan are provided in **Attachment C**.

### INDOOR AIR MONITORING PLAN

IA monitoring will be performed to assess the performance of the SSDS along with the system monitoring detailed later in this plan. The pre-mitigation IA concentration of contaminants of concern (COCs) (PCE and TCE) were detected above IDEM R2 Residential SGss PLs for PCE and above IDEM R2 Commercial SGss PLs for TCE during multiple previous sampling events, while the pre-mitigation IA concentrations of COCs have been below applicable R2 PLs. Based on the historical data collected at the Site and referencing the IDEM 2023 R2 section 4.2.3.2 SSDS Operation, Maintenance, and Monitoring, the Site meets the criteria under Schedule 1 for sampling frequency. Schedule 1 requires annual sampling of indoor air during winter worst-case conditions during the first, second, and fifth year, and every fifth year thereafter.

Prior to completing the next sampling event, the SSDS system should be shut down for an approximate 30-day equilibration period. During the sampling events, three (3) IA samples (plus one duplicate IA sample) will be collected and analyzed for VOCs using United States Environmental Protection Agency (U.S. EPA) Method TO-15. IA sampling procedures are provided in **Attachment D**. A pre-sampling walkthrough and building occupant interview to document building characteristics and potential indoor air contaminant sources will be completed before each IA sampling event. A copy of the building survey checklist is provided in **Attachment E**. The sample locations are based on the historical sampling IA locations used by SESCO Group in August 2019, March 2020, February 2022, and October 2022. The locations of the three IA samples (IA-1, IA-2, and IA-3) are depicted on **Figure 1**.

Upon receipt of the IA sampling results, CISD or their designated representative, will review the results and compare them to the applicable IDEM R2 PLs (or the applicable future guidance). If exceedances of the PLs are noted, the IA samples in the areas with exceedances may be repeated or necessary adjustments to the SSDS may be made to bring the system back into compliance, based upon professional judgement of the person(s) reviewing the IA results. Any adjustments to the SSDS will be conveyed to IDEM.

<sup>&</sup>lt;sup>1</sup> As measured by the digital manometers at the extraction point vertical pipes.

Note that the above listed sample locations may be changed upon written notice and approval by IDEM. This change may be based upon future restructuring of the building layout, which may affect the future sampling locations.

### SYSTEM MONITORING DETAILS

Periodic system monitoring will be conducted to ensure the SSDS system will operate as designed. All system monitoring will be conducted by CISD personnel, or designated representatives, in accordance with this plan. Monitoring will consist of both visual inspection of system equipment and measurement of system parameters combined with the indoor air sampling detailed in the previous section. System monitoring activities may be performed concurrent with or separate from indoor air sampling events.

### **Visual Inspections and System Measurements**

Visual inspections of SSDS components and system operational conditions will be conducted and documented routinely to confirm that the system continues to operate as designed. System parameter measurements will confirm the system is still removing air from beneath the slab. The visual and measurement inspections will include:

### General Information

- Contact information for the party responsible for issues found during the inspection;
- Monitoring date and time;
- Property address;
- Tenant's name;
- Owner's name and address;
- Inspector's name;
- Inspector's company;
- Weather conditions; and,
- Is the HVAC operating.

### Visual Inspection

- Is the fan intact and operational;
- Is the fan making any unusual noises or experiencing excessive vibrations;

- Is the riser piping intact;
- Any piping cracks;
- Does the system still appear to be sealed;
- o Does the slab penetration on the first floor appear to be sealed; and,
- o Inspection of premises and building conditions for changes that may affect operation of the mitigation system (e.g. foundation cracks, remodeling, or additions to the building).
- System Measurements
  - Is the fan running and is air exiting the exhaust piping on the roof;
  - Is there measurable vacuum at the U-tube manometer at the slab penetration;
  - o Is there measurable vacuum (>0.01 inches of water vacuum) at the digital manometers mounted on the vertical extraction points.
- Any Comments Regarding System Performance

Measurements of the system can be conducted more frequently based on observed operations (i.e. if operational parameters have changed from the previous monitoring event, if operational parameters are outside the anticipated range, or if inspections indicate potential damage or malfunction of equipment) and seasonal fluctuations (i.e. temperature or pressure changes that may affect system operations). If any concerns are noted (i.e. piping cracks, fan not running, no vacuum at the slab penetration, etc.) they will be brought to the attention of CISD to be addressed. **Attachment F** is a form to be used to record the system monitoring events.

### SYSTEM MAINTENANCE DETAILS

Routine maintenance of system components will be conducted. In response to routine system monitoring events, actions will be taken, as needed, to ensure proper system performance. Routine maintenance may include:

- Cleaning of dirt/debris from any system component;
- Cleaning of fan for corrosion, wear, or buildup;
- Lubrication of fan bearings; and,
- Draining of any condensate from fan housing.

Routine maintenance will be performed annually or as needed to keep the SSDS operational. Records of routine maintenance will be recorded in the maintenance log included as **Attachment G**. Any damaged or malfunctioning components will be replaced with the same component model (or an alternative equivalent). If mechanical

problems render the SSDS system inoperable, the system will be repaired as quickly as possible to restore proper function, generally within a week or less.

The following table provides a list of system troubleshooting tips to help diagnose SSDS problems:

### **System Troubleshooting**

SSDS Issue	Potential Cause				
Low blower flow, high blower	Fan or piping blockage/obstruction				
temperature, or high inlet vacuum may					
indicate a blockage or obstruction					
High than normal air flow or low vacuum	System piping leak				
readings at both U-tube manometers may					
indicate a break or leak in piping System					
Piping Leak					
Excessive fan noise, vibrations, or high	Potential fan malfunction				
temperature.					
Fan not running	Electrical circuit tripped or fan is				
	damaged				
Water in the exhaust piping or fan	Exhaust piping should be capped such that				
	rain and moisture should not fall into the				
	system piping. If excessive moisture				
	is encountered in the SSDS, piping should be				
	modified such that moisture can be drained				
	or collected for draining to				
	prevent damage to the system				
Indoor air concentration exceedances	- Investigate potential indoor air sources of				
	the contaminant				
	- Inspect SSDS components and				
	machinery to ensure the system is not				
	compromised				
	- Adjust SSDS components, such as				
	increasing blower speed or upsizing the				
	blower, to increase sub-slab vacuum and				
	air flow				

### **SYSTEM TERMINATION**

The activities outlined in this OMM Plan may be terminated when they are no longer needed (e.g. if contaminant levels are reduced to levels no longer resulting in vapor

intrusion). Various tasks must be implemented to demonstrate that VI mitigation is no longer needed:

- Prior to sampling for system termination, the SSDS must be shut down for a period of at least 30 days to allow re-development of pre-mitigation subsurface conditions.
- o Where possible, collect samples from the same locations initially used to evaluate VI conditions.
- o Conduct a round of paired samples during the summer season and compare results to the IDEM *Vapor Remedy Selection and Implementation* guide's Table 1 to determine whether it is appropriate to terminate system operation.
- The results of the sampling will be submitted to IDEM with a petition to terminate the SSDS operation.

### **FIGURES**

**Figure 1:** Site Plan






Indoor Air Sample

Outdoor Air Sample

### **Former Classic Cleaners**

### Site Plan

8461 Bash Street Indianapolis, Indiana 46250





PROJECT NO.: JW2594.750

SCALE: 1:750 CREATED BY: ES

Nearmap Aerial Imagery: March 2, 2023

### ATTACHMENT A

Historical IA, OA, and SGss Data – SESCO October 2022 Vapor Intrusion & Sewer Cleanout Vapor Sampling Report dated December 12, 2022

## Table 1 Indoor Air Analytical Results

Former Classic Cleaners 8641 Bash Street Indianapolis, Indiana 46256 IDEM State Cleanup Site #0000571 SESCO Project #4392

						D Project #4392					
Sample Location		Date	cis-1,2-Dichloroethene (DCE)	Ethylbenzene	N-Hexane	Tetrachloroethene (PCE)	Toluene	Trichloroethene (TCE)	Vinyl Chloride	M,P - Xylene	All Other VOCs
IDE	EM R2 Commercial Indo (CIAP		NR	49	3,100	180	22,000	8.8	28	440	Varies
IDI	IDEM R2 Residential Indoor Air Published Level (RIAPL)		NR	11	730	42	5,200	2.1	1.7	100	Varies
		8/23/2019	ND	ND	572	ND	ND	ND	ND	ND	ND
		3/9/2020	ND	ND	245	ND	ND	ND	ND	ND	ND
	IA-1	2/25/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND
	174-1	2/25/2022 (DUP)	ND	ND	ND	ND	ND	ND	ND	ND	ND
		10/20/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND
		10/20/2022 (DUP)	ND	ND	ND	ND	ND	ND	ND	ND	ND
		8/23/2019	ND	ND	345	ND	ND	ND	ND	ND	ND
_	IA-2	3/9/2020	ND	ND	ND	ND	ND	ND	ND	ND	ND
Indoor Air	1/1-2	2/25/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND
oor		10/20/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND
h		8/23/2019	ND	9.73	1,270	ND	ND	ND	ND	53.8	ND
		3/9/2020	ND	ND	2,160	ND	5,000	ND	ND	ND	ND
	IA-3	3/9/2020 (DUP)	ND	ND	2,170	ND	4,940	ND	ND	ND	ND
		2/25/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND
		10/20/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND
		8/23/2019	ND	ND	ND	ND	ND	ND	ND	ND	ND
	AA-1	3/9/2020	ND	ND	ND	ND	ND	ND	ND	ND	ND
	(Ambient Air)	2/25/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND
		10/20/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND

### Notes:

All samples analyzed for VOCs via United States Environmental Protection Agency (USEPA) Test TO-15.

Red - Concentration greater than the IDEM R2 Commercial Indoor Air Published Level (CIAPL), July 8, 2022

Blue - Concentration greater than the IDEM R2 Residential Indoor Air Published Level (RIAPL), July 8, 2022

Bold - COC concentration above the Laboratory Detection Limit, but below the IDEM R2 RIAPLs

μg/m<sup>3</sup> - Micrograms per cubic meter

NR - Not Regulated.

DUP - Duplicate Sample

cVOCs - chlorinated volatile organic compounds.

ND - Not dectected above laboratory reporting limits.

# Table 2 Sub-Slab Vapor Analytical Results

Former Classic Cleaners 8641 Bash Street Indianapolis, Indiana 46256 IDEM Cleanup Site #0000571 SESCO Project #4392

		T				SESCO Floject					
Sample	Location	Date	cis-1,2-Dichloroethene (DCE)	Ethylbenzene	N-Hexane	Tetrachloroethene (PCE)	Toluene	Trichloroethene (TCE)	Vinyl Chloride	M,P - Xylene	All Other VOCs
IDEM R2 Commercial Substate Published Level (CSSPL)		el (CSSPL)	NR	2,000	100,000	6,000	700,000	300	900	10,000	Varies
	IDEM R2 Residential Subslab Published Level (RSSPL)		NR	400	20,000	1,000	200,000	70	60	3,000	Varies
		8/23/2019	ND	ND	ND	1,350	ND	240	ND	ND	ND
	SS-1	8/23/2019 (DUP)	ND	ND	ND	1,330	ND	258	ND	ND	ND
		3/9/2020	ND	ND	ND	273	ND	ND	ND	ND	ND
		2/25/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND
		2/25/2022 (DUP)	ND	ND	ND	ND	ND	ND	ND	ND	ND
		10/20/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND
q		10/20/2022 (DUP)	ND	ND	ND	ND	ND	ND	ND	ND	ND
Sub Slab		8/23/2019	374	ND	ND	4,530	ND	751	ND	ND	ND
qn	SS-2	3/9/2020	ND	ND	ND	3,710	ND	464	ND	ND	ND
S	33-2	2/25/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND
		10/20/2022	ND	ND	ND	246	ND	48.9	ND	ND	ND
		8/23/2019	ND	ND	ND	ND	ND	ND	ND	ND	ND
		3/9/2020	ND	ND	ND	340	ND	ND	ND	ND	ND
	SS-3	3/9/2020 (DUP)	ND	ND	ND	ND	ND	ND	ND	ND	ND
		2/25/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND
		10/20/2022	ND	ND	ND	ND	ND	ND	ND	ND	ND

### Notes:

All samples analyzed for VOCs via United States Environmental Protection Agency (USEPA) Test TO-15

Red - Concentration greater than the IDEM R2 Commercial Subslab Published Level (CSSPL), July 8, 2022

Blue - Concentration greater than the IDEM R2 Residential Subslab Published Level (RSSPL), July 8, 2022

**Bold** - COC concentration above the Laboratory Detection Limit, but below the IDEM R2 RSSPLs

 $\mu g/m^3$  - Micrograms per cubic meter

NR - Not Regulated.


DUP - Duplicate Sample

cVOCs - chlorinated volatile organic compounds.

ND - Not dectected above laboratory reporting limits.

### ATTACHMENT B

**System Drawings** 



### ATTACHMENT C

### **Fan Details**



### **OBAR INSTRUMENTS**



### WHOLESALE SUPPLIES BLOG

### **CONTACT US**

### **OBAR GBR 76UD**

Home / VOC FANS / Obar GBR 76UD



\$1,639.00

**GBR INSTALLATION AND WARRANTY** 

**GBR MASTER CUT SHEET** 

GBR76UD 120v Graph

GBR76UD 240v Graph

AS OF 10/9/20 WE HAVE UPDATED
OUR BLOWERS TO INCLUDE OFFBOARD POTENTIOMETERS (INCLUDED
W/ PURCHASE) AND UPGRADED THE
ELECTRONICS PACKAGE. MORE INFO
TO FOLLOW SOON.



Add to cart

Category: VOC FANS SKU: GBR76UD



#### **OBAR INSTRUMENTS**

**■** \$0.00 ○ C

WHOLESALE SUPPLIES

BLOG

### **CONTACT US**

Description Additional information Reviews (0)

### **Description**

- \* GBR76 UD 40" WC @ 0 Max flow 195 CFM.
- \* Variable speed control to customize performance.
- \* Condensate bypass built in.
- \* 12 month warranty 40,000 hr sealed bearings.

#### **DESIGN**

- \* Our modular design means the blower and manifold assembly can be removed and replaced as a unit. This makes
- repairs cost effective and easy and allows contractors to upgrade systems simply by swapping assemblies.
- \* The GBR series is based on a bypass blower designed to handle combustible materials.
- \* The housing is not required to be air tight so you can add gauges and alarms without compromising the system.
- \* Built in condensate bypass.
- \* Variable speed controller included.
- \* Quick disconnect electrical harness.
- \* All UL listed components including UL listed enclosure for outside use.
- \* Wall fastening lugs included.
- \* GBR series roof and wall mounts available to quickly configure the blowers for your installation while providing a

custom built look.

\* Compact design 16"x 14"x 8" weighing only 18 lbs.



### **OBAR INSTRUMENTS**



### WHOLESALE SUPPLIES

### **CONTACT US**





GBR M Gauge \$45.00

Add to cart



BLOG

GBR25-R Differential Pressure Gauge and Alarm

Add to cart

\$125.00



GBR Roof Mount \$185.00

Add to cart



Pipe Piers Foam Mounts \$40.00

Add to cart



Obar GBR 45 XL Radon Fan \$118.00

Add to cart



Fantech Rn1 Radon Fan \$110.00

Add to cart

### Search

Type and hit enter ...

Q

### **Categories**

Radon (1)

Vapor Intrusion

(1)



Monday - Friday

8am - 4pm

### **OBAR INSTRUMENTS**

**≡** \$0.00 ○ ○

WHOLESALE SUPPLIES BLOG

### **CONTACT US**

Contact Us	Services	INFORMATION	CONNECT
Phone numbers:	Vapor	About Obar	Facebook
1-(800) 949-6227	Intrusion Mitigation	Contact Us	Instagram
E-mail:	Radon Mitigation	Privacy	Linkedin
wholesale@obarsystems.	coWater Mitigation	Return Policy	
info@obarsystems.com	Diagnostics and		
Business hours:	System Design		



Web Development by SmartSites

### ATTACHMENT D

# Indoor Air Sampling Procedures

### INDOOR AIR SAMPLING PROCEDURES

To collect the Indoor Air samples, utilize a 6-liter laboratory-supplied canisters equipped with regulators. The canisters should be placed at human breathing height (3 to 5-feet above the floor).

After placement, open each canister valve, and collect the samples over either an 8-hour or 24-hour timeframe, depending on the use (residential or commercial) of the sampling area. Start time of each sample, initial vacuum, and canister and regulator serial numbers should be logged on a field log sheets.

After the sampling period, record the final vacuum of each canister and the sample collection times on the field log sheet. See the attached field log sheet. Close the canister valves and properly label the canisters with pertinent sampling information. Ship the samples the laboratory (i.e. EnvisionAir in Indianapolis, Indiana) for analysis with proper chain-of-custody documentation. Samples will be analyzed for VOCs using US EPA Method TO-15.





Project Name:	Former Classic Clear	ners - VI Tes	ting	Field Team:				
Project Number:				Company:				
Sampling Address (es):	8641 Bash Street, I	Indianapolis	, IN	Laboratory:				
Weather:		Temp:		Canister Clean C	ertification:	Batch	100%	

		Pre-Sam	pling Infor	Post-Sampling Information						
Sample I.D.	Sample Location	Canister Size	Canister #	Flow Regulator Serial #	Sample Start  Date /Time	Initial Vacuum ("Hg)	Sample Stop  Date/Time	Final Vacuum ("Hg)	NOTES	
	Were "Instructions for Occupants"	provided to	tenant? \( \sum \) Ye	es 🗌 No 🖺	□ NA		Windows open during sampling period? ☐ Yes ☐ No ☐ NA			
	NOTES:  Active construction in sampling period?  \( \subseteq \text{Yes} \subseteq \text{No} \)  Precipitation during sampling period?  \( \subseteq \text{Yes} \subseteq \text{No} \)									
								ctions for Occup	ant" followed?	

#### Notes & Abbreviations

Canister Sizes: 400 mL / 1.0L Canister / 6.0L Canister

The VI Sampling Data form should be completed at the beginning and end of the sampling time frame.

Any periodic checks of canister vacuums should be noted in personnel's field books.

"Hg = vacuum in inches of mercury; NA = Not applicable

Any deviations from expected conditions should be noted in the "Additional Questions: Notes" section.

### ATTACHMENT E

Pre-Sampling Building Survey



# **Vapor Intrusion**

Project Name:						
Former Classic Cleaners						
Project Number:	Survey Date:					

August Mack	Building Survey							Common Data
ENVIRDNMENTAL			_	nformation)		Project N	umber:	Survey Date:
Sampling 8641 Bash Stree	t, Indianapol	is, IN			Person Comp	leting Survey:		
Address:	•				Compan	y/Association		
Sampling Site Status Up	odate: (or v	within 6mths -	provide d	etail on timing in	notes)			
Occupants have changed		New Textiles/	/Furniture			Garage:	Not appl	icable
Renovations		Pesticide/Inse		cation	None	Cars Parked	l inside	
Fresh paint or stain		,					ed equip. stor	ed inside
·						·		eu mside
Structure Fire	:-					Fuel can(s)	present nemicals, solv	rants procent
Significant Cracks/ Penetrati		nent floor/walls		Air Purifiers in use:				& Wind Direction:
		_				ŀ	Ambient Air	7
Wood Stove	Coal Stove			None	Filtered Electrosta	.tic	0.11	: (ex. NNW, S, SW)
Electric Space Heater					luc	Outdo	oor Air Sample Yes Collected? No	
Fuel Space Heater	Other:				Other:		04.5	140
Fireplace	tio			Mechanical Fans			OA San	nple placed upwind?
Occupant-Specific Infor				1		Solvents	Llead?	
Sensitive Populations		Demographics	Smoking:	Daily Freq.:	Location	(details ir		Clothes Dry Cleaned?
Daycare/School	None	Number of Occupants	Cigarettes	<1/2 Pack	Inside	Work		Weekly
Hospital		Adult	Cigars	1 Pack	Outside	Home		Monthly
Nursing Home		Child	Pipe	2 Packs		None		<6 times per year
		Senior	None	N/A	N/A			None
<b>During Sampling Event</b>	:							
Construction Activities within 2	250 ft?		Occupants s	smoking near samples?	Yes	No	Precip	itation (during event):
Yes (describe in "Notes")		Wine	dows closed d	luring sampling event?	— Yes	<sup>-</sup> No	Heavy R	ain Snow / Ice
☐ No		"	Instructions fo	r Occupant" provided?	Yes	No	 Light Rai	n None
Notes and General Obse	ervations:							
Office Use Only:								
Precipitation : Per "Wea	ther Undergro	und" online precipita	ition database:		inches of pr	ecipitation was r	ecorded at:	



### **Vapor Intrusion Building Survey: Chemical Inventory**

		Project	Name:
	Fo	rmer Clas	sic Cleaners
	Project Nu	mber:	Survey Date:
mp	leting Survey:		

Sampling 8641 I	8641 Bash Stree	et, Indianapolis, IN	Person Compl	leting Survey:		
Address:			Company	y/Association		
(* 1 T 1	A ' D 1	10 6				

Identify all potential indoor sources found in the building (including attached garages) the location of the source (floor & room), and whether the item was removed from the building 24-48 hours prior to the indoor air sampling event.

 $\bullet \ In \ the \ "Removed" \ column, enter \ "Yes", \ "No" \ or \ "NA" \ if \ the \ souce \ material \ was \ removed \ 24-48 \ hrs \ prior \ to \ the \ sampling \ event.$ 

TYPICAL LOCATIONS	POTENTIAL BACKGROUND CONTAMINATION SOURCE	LOCATION OF SOURCE (FLOOR / ROOM)	REMOVED (Yes/No/NA)
Garage	Paints, Paint Thinners, Paint Strippers		
	Gas Powered Equipment		
Garage	Fuel Cans		
	Insecticides, Pesticides, Herbicides		
	Cleaning Supplies		
	Air Fresheners		
	Oven Cleaners		
Kitchen/	Carpet / Upholstry Cleaner		
	Polishes / Waxes		
	Other Household Cleaning Products:		
	Appliance Cleaners		
Living	Furniture / Floor Polishes		
Area	Hobby Supplies (Solvents, Paints, Lacquers,		
	Glues, Photographic Darkroom Chemicals)		
	Scented Trees, wreaths, potpourri, etc.		
	New Furniture / Upholstery		
	New Carpeting / Flooring		
	New Drapes / Curtains		
	Air Fresheners		
	Perfume / Colognes		
Bathrooms	Hairspray		
	Nail Polish / Polish Remover		
	Bathroom Cleaners		
Closets	Moth Balls		
Bottom	Fuel Tank (Inside Building)		
Floor	Wood Stove or Fireplace		
	Other Potential Sources:		
Inside			
Structure			
Ī			
Notes:			

Notes:			

### ATTACHMENT F

# System Monitoring Forms

### System Monitoring Form Former Classic Cleaners

General Information						
Contact Information of Responsible Party <u>Cardinal Industrial San Diego</u>			Tenant (Monitoring) Location	Tenant (Monitoring) Location		
Address 8641 Bash Street, Indianapolis, IN			Inspector Name/Company	Inspector Name/Company		
DateTime						
Visual Inspection ( detail any no answ	vers (except	where indicated) in th	ne comments section at the bottom of the form)			
Is the fan intact and operational?	Yes	No	Does the system still appear to be sealed?	Yes	No	
Is the fan making unusal noise or vibrations?	Yes	No	Does the slab penetration on the first floor appear to be sealed?	Yes	No	
Is the riser piping intack?  Any piping cracks?	Yes Yes	No No	Inspect premises for any changes in conditions (e.g. foundation cracks, remodeling, or building additions? (If yes detail at the bottom of the form)	Yes	No	
System Measurements (detail any no	answers in t	he comments section	at the bottom of the form)			
Is the fan running and is air exisitng t	Yes	No				
Is there measurable vacuum (>0.01 in first floor?	Yes	No				
Is there measurable vacuum (>0.01 inches of water vacuum) at the U-tube manometer mounted on the roof beneath the fan?						
Is the vacuum reading higher at the roof manometer that at the first floor manometer?						
Comments (detail any actions to be ta	ken)					

### Fan Operation Check Form

### **Former Classic Cleaners**

Fan Operating (Y/N)	Date	Inspected By:
Operating (1/14)	Dute	mspected by.

### ATTACHMENT G

### System Maintenance Form

### System Maintenance Form SSDS System Former Classic Cleaners

Maintenance Date	Maintenance	Performe	ed By:	 
Routine Maintetance Items:				
Clean dirt/debris from system components	Complete?	Yes	No	
Cleaning of fan for corrosion, wear or buildup	Complete?	Yes	No	
Lubrication of fan bearings	Complete?	Yes	No	
Drainage of condensate from fan housing	Complete?	Yes	No	
Detail other maintenance items completed				
Follow-up or other action needed? Yes No  Describe:	By Who? _			
Date Cor	mpleted:			

### ATTACHMENT B

August Macks Winter VI Sampling Summary Report April 2024



317.916.8000 • www.augustmack.com 1302 North Meridian Street, Suite 300 • Indianapolis, Indiana 46202

June 5, 2024

Mr. Syed Jaffery Indiana Department of Environmental Management State Cleanup Section 100 N. Senate Avenue, IGCN 1101 Indianapolis, Indiana 46204

> RE: Winter Vapor Intrusion (VI) Sampling Report Former Classic Cleaners 8641 Bash Street Indianapolis, Indiana 46256 State Cleanup Site Number 0000571 August Mack Project Number JW2594.750

Dear Mr. Jaffery:

August Mack Environmental, Inc. (August Mack), on behalf of Cardinal Industrial San Diego (CISD), is submitting this Summary Report describing the winter indoor air (IA) sampling activities conducted at the property located at 8641 Bash Street, in Indianapolis, Indiana (Site). This report includes pertinent Site background information, a description of recent field activities, sampling procedures, laboratory analytical results, and conclusions.

### **BACKGROUND**

The Site is located at 8641 Bash Street, in the northeast portion of Indianapolis, Indiana in an area of commercial and light industrial development. The Site consists of one parcel, encompassing 1.80-acres and is developed with a single-story, approximately 41,140-square-foot, multi-tenant commercial building in the northeast portion of the property extending off-Site to the northeast.

According to previous reports completed by SESCO Group, the Site building was constructed in 1985. Classic Cleaners operated a dry-cleaning operation at the Site from 1988 to mid-November 2015. Classic Cleaners reportedly began occupying approximately 4,250 square feet of the south side of the Site building (current tenant spaces 8621 and 8629) in 1988. From 1988 through 2006, Classic Cleaners incrementally expanded its operations to include tenant spaces 8621 through 8633, 8621 through 8645, and 8621 through 8649.

Historical investigations beginning in 2016 revealed concentrations of volatile organic compounds (VOCs) at the Site. Tetrachloroethene (PCE) and trichloroethene (TCE) were identified in the soil at concentrations below the Indiana Department of Environmental Management (IDEM) 2023 Risk-based Closure Guide (R2) Long Term Commercial/Industrial Soil Human Health Published Levels (PLs). PCE and TCE were identified in groundwater above the IDEM 2023 R2 Long Term Residential PLs.

Historical vapor intrusion investigations of the exterior soil gas (SGe) and Site building sub-slab soil gas (SGss) samples identified concentrations of PCE and TCE above the IDEM 2023 R2 Residential Sub-slab PLs and Commercial Sub-slab PLs. However, while there has been applicable PL exceedances in the SGss for the Site building there have not been PCE or TCE exceedances in IA samples above applicable PLs.

Based on the historical investigations performed at the Site by SESCO Group, the former Classic Cleaners would fall into Scenario 3. As outlined in the IDEM R2, Scenario 3 indicates a significant potential for future vapor intrusion (VI) based on investigative results and requires the responsible party to either implement a remedy or undertake long term confirmation sampling. In order to mitigate the potential for VI within the Site building, a sub-slab depressurization system (SSDS) was installed at the Site in March 2023 by Vapor Intrusion Specialists, LLC (VIS).

Prior to installing the SSDS, a pilot test was conducted at the Site on February 9, 2023 by VIS. The pilot test included the installation of two extraction points and 20 test points. Based on the pilot test results, August Mack and VIS remobilized to the Site from March 6 through March 10th, 2023, to install the SSDS. The system features approximately 180 linear feet of 4-inch Schedule 40 PVC pipe installed into the building slab at the four extraction points suction pits. All extraction point vertical pipes manifold together to a main horizontal pipe running from north to south. Exhaust piping then runs vertically to the roof, to a mitigation fan which discharges vapors above the building. The mitigation fan maintains a measurable vacuum on the SSDS.

In addition to the SSDS pilot testing and system installation, August Mack also completed the winter VI sampling event for the Site building located at 8641 Bash Street, Indianapolis, Indiana. The IA sampling was performed while the on-Site SSDS was in operation. The analytical results for the IA and outdoor air (OA) samples reported VOC concentrations below IDEM R2 2023 Residential and Commercial Long Term Indoor Air (LTIA) PLs and below the laboratory reporting limits (LRLs). More details regarding pilot testing, SSDS instillation, and winter VI sampling is summarized in August Mack's Summary Report submitted to IDEM on May 2, 2023, IDEM virtual file cabinet (VFC) #83476619.

After further communication with the IDEM Project Manager, and in accordance with Section 4.2.3.1 the IDEM 2023 Rosk Based Closure Guide (R2), an equilibration period of

30 days from SSDS installation completion date is necessary prior to collecting confirmatory IA samples; as such, Augst Mack remobilized to the Site in April 2024 to conduct IA sampling activities in winter worst-case conditions to confirm system efficacy. Details regarding the April 2024 VI sampling activities are provided in the following sections.

### **VAPOR INTRUSION SAMPLING ACTIVITIES**

August Mack mobilized to the Site on April 12<sup>th</sup> 2024, to conduct IA sampling at the Site building. The IA sampling event was performed to evaluate system performance and confirm efficacy of the mitigation system installed on March 10, 2023. Prior to sample collection, an exterior temperature of 47 degrees Fahrenheit and an interior temperature of 67 degrees Fahrenheit was recorded by Augst Mack personnel and was maintained throughout the sampling event. As stated in the IDEM R2, winter worst case conditions are considered met when the indoor temperature is typically at least ten degrees higher than the outdoor temperature. Based on the recorded exterior and interior temperatures collected prior to sampling, the VI sampling event was performed during winter worst case conditions, as prescribed by IDEM. Additionally, IDEM concurrence on the April 12, 2024 sampling event meeting the winter worst case conditions was confirmed via email on April 11, 2024 prior to completing the winter worst case sampling event on April 13<sup>th</sup>, 2024.

### **Pre-Sampling Walkthrough Activities**

Prior to conducting IA sampling activities, August Mack personnel conducted a presampling walkthrough of the Site building to document building characteristics and potential indoor contaminant sources. An Indoor Air Building Survey Checklist was completed for the building with assistance from the building owners/occupants. Results of the walkthrough inspection revealed no apparent potential background sources of contamination. A copy of the Indoor Air Building Survey Checklist is provided in **Attachment A**.

### **Indoor Air Sampling**

August Mack performed IA sampling within the Site building. The SSDS exhaust was capped and the system was shutdown for at least 30-days prior to completing the IA sampling event. Three (3) IA samples were collected from within the Site building, one in tenant space 8645 and two in tenant space 8621. The IA sampling locations are depicted on **Figure 1**.

The three (3) IA samples and appropriate quality control/quality assurance (QA/QC) sample were collected from the Site building over an eight (8)-hour period. One duplicate sample (DUP-1-20240412) was collected from location IA-3. All samples were collected in six (6)-liter stainless steel canisters equipped with a laboratory-supplied regulator. Samples were delivered to EnvisionAir and analyzed for VOCs via U.S. EPA

Method TO-15. Field procedures utilized to collect samples are included in **Attachment B**.

### **Outdoor Ambient Air Sampling**

August Mack collected one OA sample during the April 2024 sampling event from the upwind exterior location to the west of the Site building over a period of 8 hours. The OA sample was started approximately 30-minutes prior to the IA samples and collected over 8 hours.

Sampling data sheets documenting start and end times, start and end vacuums, specific sample locations, temperatures, and other pertinent information are included in **Attachment A**. All air samples were delivered to EnvisionAir and analyzed for VOCs via U.S. EPA Method TO-15. The field procedures used to collect samples are included in **Attachment B**.

### VAPOR INTRUSION ANALYTICAL RESULTS

The VI analytical results were reported in micrograms per cubic meter ( $\mu$ g/m3) and compared to the IDEM R2 2023 Residential and Commercial LTIA Human Health PLs. A copy of the laboratory analytical report is provided as **Attachment C**.

### **Indoor Air Sample Results**

The analytical results for the IA samples were compared to the IDEM R2 Residential and Commercial LTIA PLs. Laboratory analytical results reported VOC concentrations below the LRLs. The IA analytical results are summarized in **Table 1**.

### **Outdoor Ambient Air Results**

The analytical results for the OA sample were compared to the IDEM R2 Residential and Commercial LTIA PLs. Laboratory analytical results reported VOC concentrations below the LRLs. The OA analytical results are summarized in **Table 1**.

### **CONCLUSIONS**

August Mack has completed the winter VI sampling event for the Site building located at 8641 Bash Street, Indianapolis, Indiana. Based on the time of year and exterior temperatures, the VI sampling event was conducted during winter worst case conditions as prescribed by IDEM. The IA sampling was performed following an equilibration period of at least 30 days from SSDS shutdown and capping of the roof exhaust. The analytical results for the IA and OA samples reported VOC concentrations below the LRLs. Based on the data collected during the April 2024 sampling event, the VI exposure pathway within the on-Site building is currently incomplete.

Sincerely,

Jeremiah Miller Project Manager Zach Ramey, LPG Practice Leader

Christopher S. Abel, CHMM Senior Environmental Chemist

Attachments

### **FIGURES**

**Figure 1**: Site Plan






Indoor Air Sample

Outdoor Air Sample

# **Former Classic Cleaners**

# Site Plan

8461 Bash Street Indianapolis, Indiana 46250





PROJECT NO.: JW2594.750

SCALE: 1:750 CREATED BY: ES

Nearmap Aerial Imagery: March 2, 2023

# **TABLES**

 Table 1: Summary of Air Analytical Results

# SUMMARY OF AIR ANALYTICAL DATA FORMER CLASSIC CLEANERS

	Δ		Volatile Organic Compounds (VOCs) via U.S. EPA Method TO-15				
	ust N		<u>k</u>	All Analyzed VOCs			
Sample Type	Sample ID	DUP ID	Date Collected				
2024 IDEM LON	G TERM RESI	DENTIAL	IAPLs (*)	Varies			
2024 IDEM LONG	G TERM COM	Varies					
			03/21/2023	BRL			
Outdoor Air Samples	OA-1		07/25/2023	BRL			
			04/12/2024	BRL			
			03/21/2023	BRL			
	IA-1		07/25/2023	BRL			
			04/12/2024	BRL			
			03/21/2023	BRL			
	IA-2		07/25/2023	BRL			
			04/12/2024	BRL			
Indoor Air Samples			03/21/2023	BRL			
		DUP	03/21/2023	BRL			
	TA 0		07/25/2023	BRL			
	IA-3	DUP	07/25/2023	BRL			
			04/12/2024	BRL			
		DUP	04/12/2024	BRL			

### Abbreviations & Notes

BRL = Below Laboratory Reporting Limits

DUP = Duplicate Sample

IDEM = Indiana Department of Environmental Management

PLs = Human Health Published Levels

R2 = Risk-Based Closure Guide

U.S. EPA = United States Environmental Protection Agency

#### The following denote the symbol and color of screening level exceedances:

\* = At or Above 2024 IDEM R2 Long Term Residential Indoor Air PLs (IAPLs)

\*\* = At or Above 2024 IDEM R2 Long Term Commercial Indoor Air PLs

IDEM PLs are based on the IDEM R2, Table 1: Human Health Published Levels with updates. Results and IDEM PLs are reported in micrograms per cubic meter ( $\mu g/m^3$ ). All samples presented were collected by August Mack Environmental.

### ATTACHMENT A

# **Building Survey and VI Data Sheets**



# Vapor Intrusion

Project Name:						
Classic (	Cleaners					
Project Number:	Survey Date:					
IW/2594 750	4/12/2024					

August Mack		Bu	ilding Si	urvey		Project 1	Number:	Survey Date:
ENVIRONMENTAL		(Day-of-	Event In	formation)			94.750	4/12/2024
Sampling 8641 Bash St. I	ndiananolis I	· •		,	Person Comp	leting Survey:	,, s	A. Crane
Address:	raiaria pono, n				Compan	y/Association		
Committee City Chatres II	mdata. (au -	within Graths	manida da	tail on timing in a		<i>y</i>		AME
Sampling Site Status U	paate: (or t		_	tall on timing in i	iotes)	l e		-11
Occupants have changed		☐ New Textiles,			_	Garage:	☐ Not appli	cable
Renovations		Pesticide/Ins	ecticide Applica	tion	☐ None	☑ Cars Parke		
✓ Fresh paint or stain						☑ Gas power	red equip. stor	ed inside
Structure Fire						✓ Fuel can(s)	present	
Significant Cracks/ Penetra	ations in baser	ment floor/walls				☑ Cleaners, o	chemicals, solv	ents present
Secondary Heat Sources in us	e:		Air Purifiers in use:			Ambient Air	& Wind Direction:	
☐ Wood Stove	Coal Sto	ve	I	✓ None	Filtered		SW	: (ex. NNW, S, SW)
☐ Electric Space Heater	✓ None Ob	served		lon	☐ Electrosta	atic	Outdo	or Air Sample Yes
☐ Fuel Space Heater	Other:			Charcoal	Other:			Collected ☐ No
☐ Fireplace				Mechanical Fans			✓ OA Sam	ple placed upwind?
Occupant-Specific Info	rmation:							
Sensitive Populations	s:	Demographics  Number of	Smoking:	Daily Freq.:	Location		ts Used? in Notes)	Clothes Dry Cleaned?
☐ Daycare/School	✓ None	Occupants	☐ Cigarettes	☐ <1/2 Pack	☐ Inside	☑ Work		☐ Weekly
☐ Hospital		Adult(18-65)	☐ Cigars	☐ 1 Pack	☐ Outside	☐ Home		☐ Monthly
☐ Nursing Home		Child	☐ Pipe	2 Packs		☐ None		<6 times per year
		Senior	✓ None	☑ N/A	☑ N/A			☑ None
<b>During Sampling Even</b>						1		
Construction Activities within	250 ft?		_	moking near samples?		☑ No	Precipi	tation (during event):
Yes (describe in "Notes")		Wii		uring sampling event?		□ No	☐ Heavy Ra	
☑ No			"Instructions for	Occupant" provided?	☐ Yes	☑ No	✓ Light Rai	n 🗌 None
Notes and General Obs	ervations:							
	Ca	ars found park	ed in the bui	lding along with n	ninor cleani	ing supplies		
Sample Location Sketch							s of interest (e.	g. fans, sumps, furnaces).
Provide one sketch for each flo	oor/area of sa	mpling (basement	, main, crawl sp	vace). Use additional si	ieets as necess	sary.		
	ì							
Office Use Only:	_							
Precipitation : Per "Wes	ather Undergro	und" online precipita	ation database:		inches of pr	recipitation was	recorded at:	



### SAMPLE TRAIN SHUT-IN TESTING

Project Name: Project Number:		ic Cleaners 72575.750					Field Team: Company:	A. Crane  August Mack Environmental, Inc.	
Sample /Por	ŧID	Parent Sample of Duplicate (NA or DUP ID)	Date Test Performed	Start Vacuum (in Hg)	Duration (target 60 sec)	End Vacuum (in Hg)	Vacuum Loss < 0.5 in Hg (Yes {PASS} or No {FAIL})	Comments	
IA-3-202404	112	IA-DUP-1-20240412	4/11/2024	-19	60 seconds	-19	PASS		
NOTES	Equipment Used:	] Hand Syringecc □ Au	rtomated Pump: N	lodel	【 Hand Pump:	Model _Maddox			

### **VAPOR INTRUSION SAMPLING DATA SHEET (TO-15)**



Project Name:	Classic Clear	ners		Field Team:	A. Crane		
Project Number:	JW2594.75	60		Company:	August Mack Environmental, Inc.		
Sampling Address (es):	8641 Bash St. Indianar	oolis, Indiana	a	Laboratory:	Envision		
Weather:	Rain	Temp:	47	Canister Clean C	Certification: Batch x 100%		

		Pre-Sam	pling Info	mation				Post-Sampling Information			
Sample I.D.	Sample Location	Canister Size	Canister #	Flow Regulator Serial #	Sample Start  Date /Time	Initial Vacuum ("Hg)	Sample Stop  Date/Time	Final Vacuum ("Hg)	NOTES		
OA-1-20240412	Collected from historical SESCO Group sample locations.	6L	16060	5303	4/12/24 08:07	-25	4/12/24 16:08	-12			
IA-1-20240412	Collected from historical SESCO Group sample locations.	6L	4650	7780	4/12/24 09:16	-19	4/12/24 16:02	-4			
IA-2-20240412	Collected from historical SESCO Group sample locations.	6L	10349	7300	4/12/24 09:17	-29	4/12/24 17:17	-7			
IA-3-20240412	Collected from historical SESCO Group sample locations.	6L	11089	5298	4/12/24 09:18	-27	4/12/24 17:18	-6			
IA-DUP-1-20240412	Collected from historical SESCO Group sample locations.	6L	16026	5722	4/12/24 09:18	-29	4/12/24 17:18	-9			
	UTM:										
	UTM:										
	Were "Instructions for Occupants"	provided to	tenant? \( \sum \cdot \text{Y}\epsilon	es 🗌 No 🕻				oling period?   Yes No NA			
Additional Questions:	NOTES:				Active construction in sampling period? ☐ Yes No ☐ NA  Precipitation during sampling period? ★Yes ☐ No						
							Were "Instru	ctions for Occup	ant" followed? ☐ Yes ☐ No 🗱 NA		

#### Notes & Abbreviations

Canister Sizes: 400 mL / 1.0L Canister / 6.0L Canister

The VI Sampling Data form should be completed at the beginning and end of the sampling time frame.

Any periodic checks of canister vacuums should be noted in personnel's field books.

"Hg = vacuum in inches of mercury; NA = Not applicable

Any deviations from expected conditions should be noted in the "Additional Questions: Notes" section.

# ATTACHMENT B

# **August Mack Field Procedures**

### INDOOR AIR SAMPLING PROCEDURES

August Mack initiated indoor air sampling by placing a six (6)-liter stainless steel Summa® canister equipped with an eight (8) hour flow controller approximately three (3) to five (5) feet above grade level. Both the canister and the regulator were laboratory-supplied, and batch certified clean. The Summa® canister flow controller was also equipped with a laboratory-supplied 0.2 micron air filter to prevent clogging of the canister opening during sample collection.

Once the sampling media was properly positioned, the serial number of the Summa® canister and the regulator was recorded on a field log sheet. The Summa® canister valve was opened and the air sample was collected. The start and end times of the sample was documented on the field log sheet along with the initial and final vacuum of the Summa® canister.

The indoor air sample was submitted to Envision Laboratories, INC. and analyzed for Volatile Organic Compounds (VOCs) using U.S. EPA Method TO-15.

### ATTACHMENT C

# **Laboratory Analytical Report**



Smpl#	Sample_ID;	м	Starting Coll Date:	Starting Coll Time:	End Coll Date:	End Coll Time:	Lests	Rec. Date	Rec. Time:	Due Date	Envision Air Proj#	Comments:	Client	Proi Name:	Rec by:	CANIST ER	FLOW CONTROL LER	INITIAL STARTING PRESSURE	FINAL FIELD PRESSURE	L Fina Field Field Vacu Vacuum um	<u>d</u>
24-1085	OA-1-20240412	A	4/12/24	8:07	4/12/24	16:08	TO-15	4/15/24	11:30	4/22/24	2024-203		AUGUST MACK ENVIRONMENTAL	JW2594	ю	16060	5303	25	12		JEREMIAH MILLER
24-1086	IA-1-20240412	A	4/12/24	9:16	4/12/24	16:02	TO-15	4/15/24	11:30	4/22/24	2024-203		AUGUST MACK ENVIRONMENTAL	JW2594	гō	4650	7780	19	4		JEREMIAH MILLER
24-1087	IA-2-20240412	A	4/12/24	9:17	4/12/24	17:17	TO-15	4/15/24	11:30	4/22/24	2024-203		AUGUST MACK ENVIRONMENTAL	JW2594	LD	10349	7300	29	7		JEREMIAH MILLER
24-1088	IA-3-20240412	A	4/12/24	9:18	4/12/24	17:18	TO-15	4/15/24	11:30	4/22/24	2024-203		AUGUST MACK ENVIRONMENTAL	JW2594	LD	11089	5298	27	5		JEREMIAH MILLER
24-1089	IA-DUP-1-20240412		4/12/24		4/12/24		TO-15	4/15/24	11:30	4/22/24	2024-203		AUGUST MACK ENVIRONMENTAL	JW2594	LO	16026	5722	29	9		JEREMIAH MILLER

Time

11:30

Date

4-15-24

# **CHAIN OF CUSTODY RECORD**

EnvisionAir | 1441Sadlier Circle West Drive | Indianapolis, IN 46239 | Phone: (317) 351-0885 | Fax: (317) 351-0882

Client: Avgust Mack Er	wironent	۸ P.O. N	umber:	H <sub>e</sub>			REQUESTE	DADAME	TEDC	ī			
Report 1302 N Meridan Address: #300 Introops	a St	Project	t Name or みらり午	Number:	B + 1	<u> </u>	REQUESTE	S /	//				
Report To: Jeremish 1	Niller	Sample	ed by: A	. Crone		0.01	//			LEN	11//	CIC	NAIR
Phone: 812-821-4	-957	QA/QC		: (circle if appl	icable) rel IV				/		AVI	SIC	MAIN
Invoice Address: Same		Report ug/m	ing Units	needed: (dire	de) PPMV	,		//	Sampling Type Soil-Gas: □ Sub-Slab: □				1
Desired TAT: (Please Circle One 1 day 2 days 3 days Std (5	bus. days)	120000000000000000000000000000000000000	e: 1LC = 1 Lite 6LC = 6 Lite TB = Tedlar TD = Thern	r Canister	e				Indoor-Air: □	Caniste	www.en	vision-air.c	com
Air Sample ID	Media Type (see code above)	Coll. Date (Grab/Comp	Coll. Time	Coll. Date	Coll. Time (Comp. End)			Canister Serial #	Flow Controller Serial #	Initial Field (in. Hg)	Final Field (in. Hg)	Lab Received (in. Hg)	EnvisionAir Sample Number
0A-1-20240412	6Lc	411774	807	4/13/24	1608	X		16060	O5303	-25	-17	-12	24-1085
IA-1-20240412	6LC	41171274	916	4177	1607	×		4650	07780	-19	-4	-4	24-1080
IA-7-90540417	6LC	4(12/24	917	412124	1717	×		10349	07300	-73	~7	-7	24-1087
IA-3-20240412	6LC	4112/24	914	机刀对	1716	×		11089	05298	-7]	-6	-6	24-1088
IA-DUP-1-20240412	6 Lc	412/24	-	419174	-	×		16026	05722	-71	~9	-9	24-1089
													1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
				NE U		12.			Yak I				1
								- 27		19-1			
				A:		1 1			h		. 8		=

Date

4/5/24

Time

1130

Received by:

Relinquished by:

austi ?



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Mr. Jeremiah Miller August Mack Environmental 1302 N. Meridian Indianapolis, IN 46202

April 23, 2024

EnvisionAir Project Number: 2024-203

Client Project Name: JW2594

Dear Mr. Miller,

Please find the attached analytical report for the samples received April 15, 2024. All test methods performed were fully compliant with local, state, and federal EPA methods unless otherwise noted. The project was analyzed as requested on the enclosed chain of custody record. Please review the comments section for additional information about your results or Quality Control data.

Feel free to contact me if you have any questions or comments regarding your analytical report or service.

Thank you for your business. EnvisionAir looks forward to working with you on your next project.

Yours Sincerely,

Meryl 4. Crum

Cheryl A. Crum

Director of Project Management EnvisionAir



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882

Fax: 317-351-0882 www.envision-air.com

Client Name: AUGUST MACK ENV

Project ID: JW2594

Client Project Manager: JEREMIAH MILLER

EnvisionAir Project Number: 2024-203

### Sample Summary

#### Canister Pressure / Vacuum

			START	START							<u>Lab</u>
			Date	Time	<b>End Date</b>	End Time	Date	Time	Initial Field	Final Field	Received
Laboratory Sample Number:	Sample Description:	Matrix:	Collected:	Collected:	Collected:	Collected:	Received:	Received	(in. Hg)	(in. Hg)	(in. Hg)
24-1085	OA-1-20240412	Α	4/12/24	8:07	4/12/24	16:08	4/15/24	11:30	-25	-12	-12
24-1086	IA-1-20240412	Α	4/12/24	9:16	4/12/24	16:02	4/15/24	11:30	-19	-4	-4
24-1087	IA-2-20240412	Α	4/12/24	9:17	4/12/24	17:17	4/15/24	11:30	-29	-7	-7
24-1088	IA-3-20240412	Α	4/12/24	9:18	4/12/24	17:18	4/15/24	11:30	-27	-6	-6
24-1089	IA-DUP-1-20240412	Α	4/12/24		4/12/24		4/15/24	11:30	-29	-9	-9



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Client Name: AUGUST MACK ENV

Project ID: JW2594

Client Project Manager: JEREMIAH MILLER

**EnvisionAir Project Number:** 2024-203

Analytical Method: TO-15 Analytical Batch: 041624AIR

Client Sample ID: OA-1-20240412 Sample Collection START Date/Time: 4/12/24 8:07

Sample Collection END Date/Time: 4/12/24 16:08
EnvisionAir Sample Number: 24-1085 Sample Received Date/Time: 4/15/24 11:30

Sample Matrix: AIR

Compounds	Sample Results ug/m³	Reporting Limit ug/m <sup>3</sup>	<u>Flag</u>
4-Ethyltoluene	< 492	492	<u></u>
4-Methyl-2-pentanone (MIBK)	< 2050	2050	
1,1,1-Trichloroethane	< 546	546	
1,1,2,2-Tetrachloroethane	< 0.34	0.34	1
1,1,2-Trichloroethane	< 0.21	0.21	1
1,1-Dichloroethane	< 4.05	4.05	
1,1-Dichloroethene	< 198	198	
1,2,4-Trichlorobenzene	< 0.74	0.74	
1,2,4-Trimethylbenzene	< 4.92	4.92	
1,2-dibromoethane (EDB)	< 0.03	0.03	1
1,2-Dichlorobenzene	< 60.1	60.1	
1,2-Dichloroethane	< 0.40	0.40	
1,2-Dichloropropane	< 0.46	0.46	
1,3,5-Trimethylbenzene	< 4.92	4.92	
1,3-Butadiene	< 0.22	0.22	
1,3-Dichlorobenzene	< 60.1	60.1	
1,4-Dichlorobenzene	< 0.60	0.60	
1,4-Dioxane	< 1.80	1.80	
2-Butanone (MEK)	< 2950	2950	
2-Hexanone	< 20.5	20.5	
Acetone	< 2380	2380	
Benzene	< 1.60	1.60	
Benzyl Chloride	< 0.41	0.41	1
Bromodichloromethane	< 0.54	0.54	1
Bromoform	< 10.3	10.3	
Bromomethane	< 3.88	3.88	
Carbon Disulfide	< 311	311	
Carbon Tetrachloride	< 0.63	0.63	
Chlorobenzene	< 23.0	23.0	
Chloroethane	< 13.2	13.2	



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Compounds	Sample Results	ug/m³	Reporting Limit ug/m³	Flag
Chloroform	< 0.83		0.83	
Chloromethane	< 20.6		20.6	
cis-1,2-Dichloroethene	< 19.8		19.8	
cis-1,3-Dichloropropene	< 4.54		4.54	
Cyclohexane	< 5510		5510	
Dibromochloromethane	< 0.85		0.85	
Dichlorodifluoromethane	< 49.5		49.5	
Ethyl Acetate	< 54.1		54.1	
Ethylbenzene	< 8.68		8.68	
Hexachloro-1,3-butadiene	< 1.07		1.07	
Isooctane	< 467		467	
m,p-Xylene	< 43.4		43.4	
Methylene Chloride	< 41.7		41.7	
Methyl-tert-butyl ether	< 36.1		36.1	
N-Heptane	< 410		410	
N-Hexane	< 176		176	
Naphthalene	< 0.524		0.524	
o-Xylene	< 43.4		43.4	
Propylene	< 172		172	
Styrene	< 426		426	
Tetrachloroethene	< 3.19		3.19	
Tetrahydrofuran	< 295		295	
Toluene	< 3770		3770	
trans-1,2-Dichloroethene	< 39.6		39.6	
trans-1,3-Dichloropropene	< 4.54		4.54	
Trichloroethene	< 1.07		1.07	
Trichlorofluoromethane	< 562		562	
Vinyl Acetate	< 176		176	
Vinyl Bromide	< 0.44		0.44	
Vinyl Chloride	< 1.28		1.28	
4-bromofluorobenzene (surrog		102%		
Analysis Date/Time:	4-17-	-24/00:11		
Analyst Initials		tjg		



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Client Name: AUGUST MACK ENV

Project ID: JW2594

Client Project Manager: JEREMIAH MILLER

**EnvisionAir Project Number:** 2024-203

Analytical Method: TO-15 Analytical Batch: 041624AIR

Client Sample ID: IA-1-20240412 Sample Collection START Date/Time: 4/12/24 9:16

Sample Collection END Date/Time: 4/12/24 16:02 EnvisionAir Sample Number: 24-1086 Sample Received Date/Time: 4/15/24 11:30

Sample Matrix: AIR

<u>Compounds</u>	Sample Results ug/m <sup>3</sup>	Reporting Limit ug/m <sup>3</sup>	Flag
4-Ethyltoluene	< 492	492	
4-Methyl-2-pentanone (MIBK)	< 2050	2050	
1,1,1-Trichloroethane	< 546	546	
1,1,2,2-Tetrachloroethane	< 0.34	0.34	1
1,1,2-Trichloroethane	< 0.21	0.21	1
1,1-Dichloroethane	< 4.05	4.05	
1,1-Dichloroethene	< 198	198	
1,2,4-Trichlorobenzene	< 0.74	0.74	
1,2,4-Trimethylbenzene	< 4.92	4.92	
1,2-dibromoethane (EDB)	< 0.03	0.03	1
1,2-Dichlorobenzene	< 60.1	60.1	
1,2-Dichloroethane	< 0.40	0.40	
1,2-Dichloropropane	< 0.46	0.46	
1,3,5-Trimethylbenzene	< 4.92	4.92	
1,3-Butadiene	< 0.22	0.22	
1,3-Dichlorobenzene	< 60.1	60.1	
1,4-Dichlorobenzene	< 0.60	0.60	
1,4-Dioxane	< 1.80	1.80	
2-Butanone (MEK)	< 2950	2950	
2-Hexanone	< 20.5	20.5	
Acetone	< 2380	2380	
Benzene	< 1.60	1.60	
Benzyl Chloride	< 0.41	0.41	1
Bromodichloromethane	< 0.54	0.54	1
Bromoform	< 10.3	10.3	
Bromomethane	< 3.88	3.88	
Carbon Disulfide	< 311	311	
Carbon Tetrachloride	< 0.63	0.63	
Chlorobenzene	< 23.0	23.0	
Chloroethane	< 13.2	13.2	



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Compounds	Sample Result	ts ug/m³	Reporting Limit ug/m³	<u>Flag</u>
Chloroform	< 0.83		0.83	
Chloromethane	< 20.6		20.6	
cis-1,2-Dichloroethene	< 19.8		19.8	
cis-1,3-Dichloropropene	< 4.54		4.54	
Cyclohexane	< 5510		5510	
Dibromochloromethane	< 0.85		0.85	
Dichlorodifluoromethane	< 49.5		49.5	
Ethyl Acetate	< 54.1		54.1	
Ethylbenzene	< 8.68		8.68	
Hexachloro-1,3-butadiene	< 1.07		1.07	
Isooctane	< 467		467	
m,p-Xylene	< 43.4		43.4	
Methylene Chloride	< 41.7		41.7	
Methyl-tert-butyl ether	< 36.1		36.1	
N-Heptane	< 410		410	
N-Hexane	< 176		176	
Naphthalene	< 0.524		0.524	
o-Xylene	< 43.4		43.4	
Propylene	< 172		172	
Styrene	< 426		426	
Tetrachloroethene	< 3.19		3.19	
Tetrahydrofuran	< 295		295	
Toluene	< 3770		3770	
trans-1,2-Dichloroethene	< 39.6		39.6	
trans-1,3-Dichloropropene	< 4.54		4.54	
Trichloroethene	< 1.07		1.07	
Trichlorofluoromethane	< 562		562	
Vinyl Acetate	< 176		176	
Vinyl Bromide	< 0.44		0.44	
Vinyl Chloride	< 1.28		1.28	
4-bromofluorobenzene (surrog	• ,	94%		
Analysis Date/Time:	4-1	17-24/00:58		
Analyst Initials		tjg		



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Client Name: AUGUST MACK ENV

Project ID: JW2594

Client Project Manager: JEREMIAH MILLER

EnvisionAir Project Number: 2024-203

Analytical Method: TO-15 Analytical Batch: 041624AIR

Client Sample ID: IA-2-20240412 Sample Collection START Date/Time: 4/12/24 9:17

Sample Collection END Date/Time: 4/12/24 17:17
EnvisionAir Sample Number: 24-1087 Sample Received Date/Time: 4/15/24 11:30

Sample Matrix: AIR

Compounds	Sample Results ug/m³	Reporting Limit ug/m <sup>3</sup>	<u>Flag</u>
4-Ethyltoluene	< 492	492	<u></u>
4-Methyl-2-pentanone (MIBK)	< 2050	2050	
1,1,1-Trichloroethane	< 546	546	
1,1,2,2-Tetrachloroethane	< 0.34	0.34	1
1,1,2-Trichloroethane	< 0.21	0.21	1
1,1-Dichloroethane	< 4.05	4.05	
1,1-Dichloroethene	< 198	198	
1,2,4-Trichlorobenzene	< 0.74	0.74	
1,2,4-Trimethylbenzene	< 4.92	4.92	
1,2-dibromoethane (EDB)	< 0.03	0.03	1
1,2-Dichlorobenzene	< 60.1	60.1	
1,2-Dichloroethane	< 0.40	0.40	
1,2-Dichloropropane	< 0.46	0.46	
1,3,5-Trimethylbenzene	< 4.92	4.92	
1,3-Butadiene	< 0.22	0.22	
1,3-Dichlorobenzene	< 60.1	60.1	
1,4-Dichlorobenzene	< 0.60	0.60	
1,4-Dioxane	< 1.80	1.80	
2-Butanone (MEK)	< 2950	2950	
2-Hexanone	< 20.5	20.5	
Acetone	< 2380	2380	
Benzene	< 1.60	1.60	
Benzyl Chloride	< 0.41	0.41	1
Bromodichloromethane	< 0.54	0.54	1
Bromoform	< 10.3	10.3	
Bromomethane	< 3.88	3.88	
Carbon Disulfide	< 311	311	
Carbon Tetrachloride	< 0.63	0.63	
Chlorobenzene	< 23.0	23.0	
Chloroethane	< 13.2	13.2	



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Compounds	Sample Result	ts ug/m³	Reporting Limit ug/m³	<u>Flag</u>
Chloroform	< 0.83		0.83	
Chloromethane	< 20.6		20.6	
cis-1,2-Dichloroethene	< 19.8		19.8	
cis-1,3-Dichloropropene	< 4.54		4.54	
Cyclohexane	< 5510		5510	
Dibromochloromethane	< 0.85		0.85	
Dichlorodifluoromethane	< 49.5		49.5	
Ethyl Acetate	< 54.1		54.1	
Ethylbenzene	< 8.68		8.68	
Hexachloro-1,3-butadiene	< 1.07		1.07	
Isooctane	< 467		467	
m,p-Xylene	< 43.4		43.4	
Methylene Chloride	< 41.7		41.7	
Methyl-tert-butyl ether	< 36.1		36.1	
N-Heptane	< 410		410	
N-Hexane	< 176		176	
Naphthalene	< 0.524		0.524	
o-Xylene	< 43.4		43.4	
Propylene	< 172		172	
Styrene	< 426		426	
Tetrachloroethene	< 3.19		3.19	
Tetrahydrofuran	< 295		295	
Toluene	< 3770		3770	
trans-1,2-Dichloroethene	< 39.6		39.6	
trans-1,3-Dichloropropene	< 4.54		4.54	
Trichloroethene	< 1.07		1.07	
Trichlorofluoromethane	< 562		562	
Vinyl Acetate	< 176		176	
Vinyl Bromide	< 0.44		0.44	
Vinyl Chloride	< 1.28		1.28	
4-bromofluorobenzene (surrog		103%		
Analysis Date/Time:	4-	17-24/02:29		
Analyst Initials		tjg		



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Client Name: AUGUST MACK ENV

Project ID: JW2594

Client Project Manager: JEREMIAH MILLER

EnvisionAir Project Number: 2024-203

Analytical Method: TO-15
Analytical Batch: 041624AIR

Client Sample ID: IA-3-20240412 Sample Collection START Date/Time: 4/12/24 9:18

Sample Collection END Date/Time: 4/12/24 17:18
EnvisionAir Sample Number: 24-1088 Sample Received Date/Time: 4/15/24 11:30

Sample Matrix: AIR

Compounds	Sample Results ug/m <sup>3</sup>	Reporting Limit ug/m <sup>3</sup>	<u>Flag</u>
4-Ethyltoluene	< 492	492	
4-Methyl-2-pentanone (MIBK)	< 2050	2050	
1,1,1-Trichloroethane	< 546	546	
1,1,2,2-Tetrachloroethane	< 0.34	0.34	1
1,1,2-Trichloroethane	< 0.21	0.21	1
1,1-Dichloroethane	< 4.05	4.05	
1,1-Dichloroethene	< 198	198	
1,2,4-Trichlorobenzene	< 0.74	0.74	
1,2,4-Trimethylbenzene	< 4.92	4.92	
1,2-dibromoethane (EDB)	< 0.03	0.03	1
1,2-Dichlorobenzene	< 60.1	60.1	
1,2-Dichloroethane	< 0.40	0.40	
1,2-Dichloropropane	< 0.46	0.46	
1,3,5-Trimethylbenzene	< 4.92	4.92	
1,3-Butadiene	< 0.22	0.22	
1,3-Dichlorobenzene	< 60.1	60.1	
1,4-Dichlorobenzene	< 0.60	0.60	
1,4-Dioxane	< 1.80	1.80	
2-Butanone (MEK)	< 2950	2950	
2-Hexanone	< 20.5	20.5	
Acetone	< 2380	2380	
Benzene	< 1.60	1.60	
Benzyl Chloride	< 0.41	0.41	1
Bromodichloromethane	< 0.54	0.54	1
Bromoform	< 10.3	10.3	
Bromomethane	< 3.88	3.88	
Carbon Disulfide	< 311	311	
Carbon Tetrachloride	< 0.63	0.63	
Chlorobenzene	< 23.0	23.0	
Chloroethane	< 13.2	13.2	



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Compounds	Sample Results ug/m	Reporting Limit ug/m <sup>3</sup> Flag
Chloroform	< 0.83	0.83
Chloromethane	< 20.6	20.6
cis-1,2-Dichloroethene	< 19.8	19.8
cis-1,3-Dichloropropene	< 4.54	4.54
Cyclohexane	< 5510	5510
Dibromochloromethane	< 0.85	0.85
Dichlorodifluoromethane	< 49.5	49.5
Ethyl Acetate	< 54.1	54.1
Ethylbenzene	< 8.68	8.68
Hexachloro-1,3-butadiene	< 1.07	1.07
Isooctane	< 467	467
m,p-Xylene	< 43.4	43.4
Methylene Chloride	< 41.7	41.7
Methyl-tert-butyl ether	< 36.1	36.1
N-Heptane	< 410	410
N-Hexane	< 176	176
Naphthalene	< 0.524	0.524
o-Xylene	< 43.4	43.4
Propylene	< 172	172
Styrene	< 426	426
Tetrachloroethene	< 3.19	3.19
Tetrahydrofuran	< 295	295
Toluene	< 3770	3770
trans-1,2-Dichloroethene	< 39.6	39.6
trans-1,3-Dichloropropene	< 4.54	4.54
Trichloroethene	< 1.07	1.07
Trichlorofluoromethane	< 562	562
Vinyl Acetate	< 176	176
Vinyl Bromide	< 0.44	0.44
Vinyl Chloride	< 1.28	1.28
4-bromofluorobenzene (surro		
Analysis Date/Time:	4-17-24/03	:23
Analyst Initials	tjg	



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Client Name: AUGUST MACK ENV

Project ID: JW2594

Client Project Manager: JEREMIAH MILLER

**EnvisionAir Project Number:** 2024-203

Analytical Method: TO-15
Analytical Batch: 041624AIR

Client Sample ID: IA-DUP-1-20240412 Sample Collection START Date/Time: 4/12/24

Sample Collection END Date/Time: 4/12/24

EnvisionAir Sample Number: 24-1089 Sample Received Date/Time: 4/15/24 11:30

Sample Matrix: AIR

<u>Compounds</u>	Sample Results ug/m <sup>3</sup>	Reporting Limit ug/m <sup>3</sup>	<u>Flag</u>
4-Ethyltoluene	< 492	492	
4-Methyl-2-pentanone (MIBK)	< 2050	2050	
1,1,1-Trichloroethane	< 546	546	
1,1,2,2-Tetrachloroethane	< 0.34	0.34	1
1,1,2-Trichloroethane	< 0.21	0.21	1
1,1-Dichloroethane	< 4.05	4.05	
1,1-Dichloroethene	< 198	198	
1,2,4-Trichlorobenzene	< 0.74	0.74	
1,2,4-Trimethylbenzene	< 4.92	4.92	
1,2-dibromoethane (EDB)	< 0.03	0.03	1
1,2-Dichlorobenzene	< 60.1	60.1	
1,2-Dichloroethane	< 0.40	0.40	
1,2-Dichloropropane	< 0.46	0.46	
1,3,5-Trimethylbenzene	< 4.92	4.92	
1,3-Butadiene	< 0.22	0.22	
1,3-Dichlorobenzene	< 60.1	60.1	
1,4-Dichlorobenzene	< 0.60	0.60	
1,4-Dioxane	< 1.80	1.80	
2-Butanone (MEK)	< 2950	2950	
2-Hexanone	< 20.5	20.5	
Acetone	< 2380	2380	
Benzene	< 1.60	1.60	
Benzyl Chloride	< 0.41	0.41	1
Bromodichloromethane	< 0.54	0.54	1
Bromoform	< 10.3	10.3	
Bromomethane	< 3.88	3.88	
Carbon Disulfide	< 311	311	
Carbon Tetrachloride	< 0.63	0.63	
Chlorobenzene	< 23.0	23.0	
Chloroethane	< 13.2	13.2	



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Compounds	Sample Results up	g/m³	Reporting Limit ug/m³	<u>Flag</u>
Chloroform	< 0.83		0.83	
Chloromethane	< 20.6		20.6	
cis-1,2-Dichloroethene	< 19.8		19.8	
cis-1,3-Dichloropropene	< 4.54		4.54	
Cyclohexane	< 5510		5510	
Dibromochloromethane	< 0.85		0.85	
Dichlorodifluoromethane	< 49.5		49.5	
Ethyl Acetate	< 54.1		54.1	
Ethylbenzene	< 8.68		8.68	
Hexachloro-1,3-butadiene	< 1.07		1.07	
Isooctane	< 467		467	
m,p-Xylene	< 43.4		43.4	
Methylene Chloride	< 41.7		41.7	
Methyl-tert-butyl ether	< 36.1		36.1	
N-Heptane	< 410		410	
N-Hexane	< 176		176	
Naphthalene	< 0.524		0.524	
o-Xylene	< 43.4		43.4	
Propylene	< 172		172	
Styrene	< 426		426	
Tetrachloroethene	< 3.19		3.19	
Tetrahydrofuran	< 295		295	
Toluene	< 3770		3770	
trans-1,2-Dichloroethene	< 39.6		39.6	
trans-1,3-Dichloropropene	< 4.54		4.54	
Trichloroethene	< 1.07		1.07	
Trichlorofluoromethane	< 562		562	
Vinyl Acetate	< 176		176	
Vinyl Bromide	< 0.44		0.44	
Vinyl Chloride	< 1.28		1.28	
4-bromofluorobenzene (surrog	,	8%		
Analysis Date/Time:		24/04:16		
Analyst Initials	ţ	ijg		



Analytical Report

#### **EnvisionAir**

1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

### **TO-15 Quality Control Data**

EnvisionAir Batch Number: 041624AIR

Enviolenza Baton Namber.	0410247 til t		
Method Blank (MB):	MB Results (ppbv)	Reporting Limit (ppbv)	<u>Flags</u>
4-Ethyltoluene	< 100	100	
4-Methyl-2-pentanone (MIBK)	< 500	500	
1,1,1-Trichloroethane	< 100	100	
1,1,2,2-Tetrachloroethane	< 0.049	0.049	1
1,1,2-Trichloroethane	< 0.038	0.038	1
1,1-Dichloroethane	< 1	1	
1,1-Dichloroethene	< 50	50	
1,2,4-Trichlorobenzene	< 0.1	0.1	
1,2,4-Trimethylbenzene	< 1	1	
1,2-dibromoethane (EDB)	< 0.0041	0.0041	1
1,2-Dichlorobenzene	< 10	10	
1,2-Dichloroethane	< 0.1	0.1	
1,2-Dichloropropane	< 0.1	0.1	
1,3,5-Trimethylbenzene	< 1	1	
1,3-Butadiene	< 0.1	0.1	
1,3-Dichlorobenzene	< 10	10	
1,4-Dichlorobenzene	< 0.1	0.1	
1,4-Dioxane	< 0.5	0.5	
2-Butanone (MEK)	< 1000	1000	
2-Hexanone	< 5	5	
Acetone	< 1000	1000	
Benzene	< 0.5	0.5	
Benzyl Chloride	< 0.08	0.08	1
Bromodichloromethane	< 0.08	0.08	1
Bromoform	< 1	1	
Bromomethane	< 1	1	
Carbon Disulfide	< 100	100	
Carbon Tetrachloride	< 0.1	0.1	
Chlorobenzene	< 5	5	
Chloroethane	< 5	5	
Chloroform	< 0.17	0.17	
Chloromethane	< 10	10	
cis-1,2-Dichloroethene	< 5	5	
cis-1,3-Dichloropropene	< 1	1	
Cyclohexane	< 1600	1600	
Dibromochloromethane	< 0.1	0.1	
Dichlorodifluoromethane	< 10	10	
Ethyl Acetate	< 15	15	
Ethylbenzene	< 2	2	
Hexachloro-1,3-butadiene	< 0.1	0.1	
Isooctane	< 100	100	
m,p-Xylene	< 10	10	
Methylene Chloride	< 12	12	
Methyl-tert-butyl ether	< 10	10	
N-Heptane	< 100	100	
N-Hexane	< 50	50	
Naphthalene	< 0.1	0.1	
o-Xylene	< 10	10	
Propylene	< 100	100	
Styrene	< 100	100	
Tetrachloroethene	< 0.47	0.47	
Tetrahydrofuran	< 100	100	



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Analytical Report

Method Blank (MB):	MB Results (ppbv)	Reporting Limit (ppbv)	<u>Flags</u>
Toluene	< 1000	1000	
trans-1,2-Dichloroethene	< 10	10	
trans-1,3-Dichloropropene	< 1	1	
Trichloroethene	< 0.2	0.2	
Trichlorofluoromethane	< 100	100	
Vinyl Acetate	< 50	50	
Vinyl Bromide	< 0.1	0.1	
Vinyl Chloride	< 0.5	0.5	
4-bromofluorobenzene (surrogate)	99%		
Analysis Date/Time:	4-16-24/15:45		
Analyst Initials	tjg		

			LCS/D		LCSD		
LCS/LCSD	LCS Results (ppbv)	LCSD Results (ppbv)	Conc(ppbv)	Rec.	Rec.	RPD	<u>Flag</u>
Propylene	9.33	9.9	10	93%	99%	5.9%	
Dichlorodifluoromethane	9.36	10.2	10	94%	102%	8.6%	
Chloromethane	10.5	9.56	10	105%	96%	9.4%	
Vinyl Chloride	10.5	9.81	10	105%	98%	6.8%	
1,3-Butadiene	9.9	9.71	10	99%	97%	1.9%	
Bromomethane	9.95	10.4	10	100%	104%	4.4%	
Chloroethane	9.22	10.1	10	92%	101%	9.1%	
Vinyl Bromide	10.6	10.9	10	106%	109%	2.8%	
Trichlorofluoromethane	10.2	10.7	10	102%	107%	4.8%	
Acetone	10.1	9.75	10	101%	98%	3.5%	
1,1-Dichloroethene	9.42	10.7	10	94%	107%	12.7%	
Methylene Chloride	10.2	10.1	10	102%	101%	1.0%	
Carbon Disulfide	9.47	10.5	10	95%	105%	10.3%	
trans-1,2-Dichloroethene	10.9	9.38	10	109%	94%	15.0%	
Methyl-tert-butyl ether	10.2	10	10	102%	100%	2.0%	
1,1-Dichloroethane	9.64	9.91	10	96%	99%	2.8%	
Vinyl Acetate	9.62	9.76	10	96%	98%	1.4%	
N-Hexane	9.33	10.1	10	93%	101%	7.9%	
2-Butanone (MEK)	10.6	10.5	10	106%	105%	0.9%	
cis-1,2-Dichloroethene	10.6	10.7	10	106%	107%	0.9%	
Ethyl Acetate	9.81	10.2	10	98%	102%	3.9%	
Chloroform	10.3	10.5	10	103%	105%	1.9%	
Tetrahydrofuran	9.79	9.96	10	98%	100%	1.7%	
1,2-Dichloroethane	9.76	9.98	10	98%	100%	2.2%	
1,1,1-Trichloroethane	9.52	10.2	10	95%	102%	6.9%	
Carbon Tetrachloride	10.2	9.55	10	102%	96%	6.6%	
Benzene	9.79	9.45	10	98%	95%	3.5%	
Cyclohexane	10.2	9.95	10	102%	100%	2.5%	
1,2-Dichloropropane	10.1	9.75	10	101%	98%	3.5%	
Trichloroethene	10.1	9.69	10	101%	97%	4.1%	
Bromodichloromethane	9.44	9.69	10	94%	97%	2.6%	
1,4-Dioxane	10.3	9.11	10	103%	91%	12.3%	
Isooctane	9.22	9.56	10	92%	96%	3.6%	
N-Heptane	9.95	10.6	10	100%	106%	6.3%	
cis-1,3-Dichloropropene	10.2	10.9	10	102%	109%	6.6%	
4-Methyl-2-pentanone (MIBK)	10.2	10.2	10	102%	102%	0.0%	
trans-1,3-Dichloropropene	9.55	9.55	10	96%	96%	0.0%	
1,1,2-Trichloroethane	9.8	8.85	10	98%	89%	10.2%	
Toluene	10.4	9.92	10	104%	99%	4.7%	
2-Hexanone	9.87	9.13	10	99%	91%	7.8%	
Dibromochloromethane	10.2	10.5	10	102%	105%	2.9%	
1,2-dibromoethane (EDB)	9.95	9.31	10	100%	93%	6.6%	
Tetrachloroethene	9.85	10.2	10	99%	102%	3.5%	
Chlorobenzene	10.8	10.8	10	108%	108%	0.0%	
Ethylbenzene	9.82	9.93	10	98%	99%	1.1%	
m,p-Xylene	20.6	21.4	20	103%	107%	3.8%	
Bromoform	9.86	10.3	10	99%	103%	4.4%	



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Analytical Report

			LCS/D	LCS	LCSD		
LCS/LCSD	LCS Results (ppbv)	LCSD Results (ppbv)	Conc(ppbv)	Rec.	Rec.	<u>RPD</u>	Flag
Styrene	10.4	10.5	10	104%	105%	1.0%	
1,1,2,2-Tetrachloroethane	10.3	10.9	10	103%	109%	5.7%	
o-Xylene	9.64	9.94	10	96%	99%	3.1%	
4-Ethyltoluene	10.8	10.4	10	108%	104%	3.8%	
1,3,5-Trimethylbenzene	10.9	10.5	10	109%	105%	3.7%	
1,2,4-Trimethylbenzene	10.7	10	10	107%	100%	6.8%	
1,3-Dichlorobenzene	9.8	9.8	10	98%	98%	0.0%	
Benzyl Chloride	10.2	9.62	10	102%	96%	5.9%	
1,4-Dichlorobenzene	10.8	10.4	10	108%	104%	3.8%	
1,2-Dichlorobenzene	10.3	9.29	10	103%	93%	10.3%	
1,2,4-Trichlorobenzene	9.9	9.01	10	99%	90%	9.4%	
Naphthalene	11	9.08	10	110%	91%	19.1%	
Hexachloro-1,3-butadiene	9.03	8.64	10	90%	86%	4.4%	
4-bromofluorobenzene (surrogate)	100%	98%					
Analysis Date/Time:	4-16-24/12:35	4-16-24/14:11					
Analyst Initials	tjg	tjg					



1441 Sadlier Circle West Drive Indianapolis, IN 46239 Ph: 317-351-0885 Fax: 317-351-0882 www.envision-air.com

Flag Number

**Comments** 

1

Reporting limit is supported by MDL. TJG

11:30

4-15-24

# **CHAIN OF CUSTODY RECORD**

EnvisionAir | 1441Sadlier Circle West Drive | Indianapolis, IN 46239 | Phone: (317) 351-0885 | Fax: (317) 351-0882

Client: Avoyst Mack Enimerated  Report 1302 N Meriden St  Address: #300 Indonerous 46202  Report To: Jeremish Miller  Phone: 912-821-4957  Invoice Address: Game		, P.O. N	P.O. Number:  Project Name or Number:  Jwas y 4  Sampled by: A. Crocc  QA/QC Required: (circle if applicable) Level III Level IV  Reporting Units needed: (circle) ug/m³ mg/m³ PPBV PPMV  Media type: 1LC = 1 Liter Canister 6LC = 6 Liter Canister 6LC = 6 Liter Canister TB = Tedlar Bag TD = Thermal Desorption Tube				BE	01150	TED DADAL	FTEDC				
		Projec					REQUESTED PARAMETERS  ENVISIONAIR  Sampling Type: Soil-Gas: Sub-Slab: Indoor-Air:  Canister Pressure / Vacuum							
		Sample							100		J.C.F	11//	CIC	NAIR
		QA/QC					/	//				AVI	SIC	MAIN
									///	Sampling Type Soil-Gas: □ Sub-Slab: □	<u>**</u>			
Desired TAT: (Please Circle One 1 day 2 days 3 days Std (	Media typ	10 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2					5/		Indoor-Air: □					
Air Sample ID	Media Type (see code above)	Coll. Date (Grab/Comp	Coll. Time	Coll. Date	Coll. Time (Comp. End)				Canister Serial #	Flow Controller Serial #	Initial Field (in. Hg)	Final Field (in. Hg)	Lab Received (in. Hg)	EnvisionAir Sample Number
0A-1-20240412	6LC	411124	807	4/13/24	1608	X			16060	05303	-25	-17	-12	24-1085
IA-1-20240412	6LC	41171274	916	4112724	1607	×	<u> </u>		4650	07780	-19	-4	-4	24-1080
IA-7-90540417	6LC	4(1)/24	917	412124	1717	×		1	10349	07300	-73	~7	-7	24-1087
IA-3-20240412	6LC	4112/24	914	州河河	1716	×		W.	11089	05298	-77	-6	-6	24-1088
IA-DUP-1-20240412	bLc	412/24	-	412124	_	×			16026	02177	-71	~9	-9	24-1089
	10.04-11													A Company
			3								- ,	43		
	13 :	30- 3												
Comments:							10.0	Ser X			H * 1/2		1	1 1 1
Relinquished by: Date					Date	Time			○ Re	Received by:			ate	Time

4/15/24

1130

austi