## **BYPASS / OVERFLOW INCIDENT REPORT**

State Form 48373 (R9 / 7-22) Indiana Department of Environmental Management Office of Water Quality

	Follow-up to Bypass report							
previously sent on:								

INSTRUCTIONS:

Complete all parts of this form and e-mail signed copies to <a href="www.eports@idem.IN.gov">www.eports@idem.IN.gov</a>. Submittal of this report will satisfy the Office of Water Quality (OWQ) telephone and written bypass/overflow reporting requirements of your NPDES permit. Please use and the second page of this form as necessary to identify separate locations caused by the same event. If you have any questions while filling out this form, please call (317) 232-7150.

To report a spill or if the release is resulting in a fish kill or other severe environmental damage, immediately report the release to the Emergency Response Section spill response line at: (317) 233-7745 or toll free within Indiana at (888) 233-7745.

Response Section spill response line at: (317) 233-7745 or toll free within Indiana at (600) 233-7745.												
GENERAL INFORMATION												
	<sub>me (Organization)</sub> omo Wastewat	ər	(2) Mailing A 1501 W. I	(2) Mailing Address <i>(reporting organization)</i> 1501 W. Markland Ave Kokomo IN 46901			(3) County Howard		(4) NPDES Permit IN0032875			
RELEASE INFORMATION (Location 1)												
(5) Outfall Number			(7) Date (mm/dd/yy) and Time Release Stopped		(8) Location of Release (streets address Manhole, Lift Station, Force Main etc.)		or (9	9) Latitude Deg Min Sec)	(9) Long (Deg Min			
CSO009	7/2/24 955	⊠ AM 7	/2/24 1253	☐ AM 図 PM			4	0 29 3.80	86 7 4	15.7		
(10) Amount of	of Flow Released	(Alwa	llways provide a volume.) (11) WWTP Flo			ow During						
Check one: ☐ Estimated ☐ Actual UNK Gallons 7.0 MGD 0.0 MGD												
(13) Overflow Type (Select one.)  ☐ Sanitary Sewer Overflow ☐ Treatment Bypass (at wastewater plant) ☐ Prohibited Combined Sewer Overflow ☐ Dry Weather Combined Sewer Overflow ☐ Combined Sewer System Release  (15) Reason for Bypass / Overflow (Select one or more.)												
☑ Construction Related ☐ Power Failure ☑ Equipment Failure ☐ Unknown ☑ Exceeded Max Capacity ☐ Precipitation   Inches												
Constitution Related   Constitution Related   Constitution   Con								rea Impar perty nt Plant i Vater er Impacte	cted			
(21) Resolution: Actions Taken or Planned to Prevent Recurrence Installed an additional bypass pump to handle the flow of the temporary bypass.  (22)  CERTIFICATION AND SIGNATURE  I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the												
possibility of fine and imprisonment for knowing violations. (The area below is for a handwritten signature or an electronic substitute. Scan the completed form to PDF and e-mail to www.Repdrts@idem.IN.gov)  SIGNATURE:  DATE (month, day, year): 7/3/2024												
SIGNATURE		V V V V	- Newstra	0	meil			, day, year): <u>_//.</u> lay, year) / Time ID				
Individual Mak Katie Trob	ing Report (printed) augh		one Number ₹ 575509	Ktroba	-mail ugh@cityofkokomo.org			ay, year, i iille it	) LIVI	☐ AM ☐ PM		