BYPASS / OVERFLOW INCIDENT REPORT

State Form 48373 (R8 / 2-19) Indiana Department of Environmental Management Office of Water Quality

☐ Follow-up to Bypass repo	ort
previously sent on:	

INSTRUCTIONS:

Complete all parts of this form and e-mail signed copies to www.eports@idem.IN.gov. Submittal of this report will satisfy the Office of Water Quality (OWQ) telephone and written bypass/overflow reporting requirements of your NPDES permit. Please use and the second page of this form as necessary to identify separate locations caused by the same event. If you have any questions while filling out this form, please call (317) 232-6770.

To report a spill or if the release is resulting in a fish kill or other severe environmental damage, immediately report the release to the Emergency Response Section spill response line at: (317) 233-7745 or toll free within Indiana at (888) 233-7745.

Response Se	ction spill response lir	ne at: (317)	233-7745 or to	II free with	in Indiana at (8	888) 233-774	5.				•
				GENERA	L INFORMATI	ON					
(1) Facility Na	(1) Facility Name (Organization)				porting organiz	zation)	(3	(3) County			S Permit
Cheeney Creek WWTP			10210 Elle	10210 Eller Road				Hamilton I			484
					RMATION (L	ocation 1)					
Number Release Began Rel) Date (mm/dd/yy) elease Stopped	-	(8) Location of Release (streets addres Manhole, Lift Station, Force Main etc.)					(9) Longit (Deg Min	
(40) 4	04/11/19 2:30		4/11/19 3:15					39 94 20.90			4 975
	of Flow Released ☑ Estimated ☐ A						(11) WWTP Flow During Release (12) WWTP Per 8.2 MGD 16.7 MGD				Flow Rate
Check one: (13) Overflow T	ype (Select one.)	ctuai			any damage to			stream		טו	
☐ Treatment☐ Prohibited☐ Dry Weath☐ Combined (15) Reason f	ewer Overflow Bypass (at wastewar Combined Sewer Over er Combined Sewer C Sewer System Relea or Bypass / Overflow	erflow Overflow se (Select one	or more.)	ne Observ	ed						
	component(s) rmore.) eral e eion Failure Bypassed ucture ralve n Out	Overflo Allison	7) Additional Description of the Bypass / Overflow Event: verflow occured while replacing an isolation valve at the lisonviller Road Lift Station					Max Capacity Precipitation Inches (18) Description of the Area Impacted (Check all that apply.) Affected Private Property Basement Backup Occurred at Treatment Plant Reached Public Land Reached Receiving Water Name of Receiving Water Impacted: Cheeney Creek			
(19) Additional organizations notified by facility, if necessary (Select one or more.) □ IDEM Emergency Response □ Health Department □ DNR Fish and Wildlife □ Local Emergency Management □ Other: (20) Actions Taken to Prevent, Minimize, or Mitigate Damage including Clean-up and Treatment of Affected Area (Select one or more of the following, then add a written description.) □ Removed Blockage □ Repaired Pipe ☑ Repaired Pump Station □ Other □ Lime □ Clean-Up Debris											
(21) Resolution	n: Actions Taken or P aned up.	lanned to P	revent Recurrer	nce							
(22)											
I certify under designed to as manage the sy belief, true, ac imprisonment mail to wwRep	penalty of law that thisure that qualified perstem, or those persocurate, and complete for knowing violations	rsonnel prop ns directly re I am award . (The area	and all attachm perly gather and esponsible for g e that there are a below is for a h	nents were d evaluate athering the significant nandwritter	the information ne information, penalties for s n signature or a	er my direction submitted. the information submitting fal	Based on mion submitted se information substitute. DATE (mo	y inquir d is, to t on, inclu Scan th oth, day	y of the perso the best of my iding the poss e completed for y, year):	n or perso knowledg sibility of fir form to PD	ns who e and ne and
			one Number 595-3281	t E-mail amr@fisher				Date (month, day, year) / Time IDEM Notified 4/12/19 2:00			