## INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY FIELD INSPECTION REPORT



12/28/2020

							/ V 12	128/2020
SOURCE INFORMATION								
SOURCE NAME	Phoenix Color							
SOURCE LOCATION	200 Hulman St Terre Haute IN 47802							
SOURCE ECCATION	Vigo County							
MAILING ADDRESS	same							
PLANT ID	167-00136							
PERMIT INFORMATION	Permit Type: Registration Permit Number: 42640 Permit Expiration Date: NA VFC Document No.(hyperlink): 82943066							
ATTAINMENT STATUS	<ul> <li>         △ Attainment for all criteria pollutants         □ Nonattainment for □SO₂ □CO □O₃ □NO₂ □Pb □PM₁₀ □PM₂.5         □</li> </ul>							
SOURCE STATUS	<ul> <li>□ PSD Major (326 IAC 2-2)</li> <li>□ Emission Offset (326 IAC 2-3)</li> <li>□ Acid Rain (326 IAC 21)</li> <li>□ Major Source of HAPs</li> <li>□ Area Source of HAPs</li> </ul>							
SOURCE DESCRIPTION	The Registrant owns and operates a stationary sheetfeed offset printing process operation. SIC code 2752							
INSPECTION INFORMATION								
INSPECTED BY	Tammy Haug							
INSPECTION DATE AND TIME	12/21/2020 TIME IN: 10:30 am TIME OUT: 11:30			1:30				
REPORTED BY	Tammy Haug REPORT DATE: 12/23/2020							
COMPLIANCE PERIOD REVIEWED	1/2019 to 12/2020							
INSPECTION NOTIFICATION	☐ Unannounced  ☐ Unannounced  ☐ Unannounced  ☐ Unannounced to determine operational status and additional PPE requirements."							
INSPECTION OBJECTIVE(S)	<ul> <li>□ Compliance Monitoring Strategy (CMS)</li> <li>□ Mega-Site: □ FCE □ PCE</li> <li>□ Other: □ Surveillance</li> </ul>							
ACES TRACKING NUMBER(S)	Inspection: 253355 Complaint:				Violat	ion/Warning:	253398	
RM TRACKING NUMBER(S)	Complaint:							
INSPECTION BACKGROUND	Registration originally issued October 8, 2003 to Moore Langen Printing. Permit issued to LSC Communications US LLC on October 28, 2016. Permit issued to Phoenix Color Inc. on November 30, 2017. Last inspection was November 6, 2014 with no findings.							

Phoenix Color (Plant ID: 167-00136) Inspection Report Page 2 of 5

SOURCE PERSONNE	L INTERVIEWED		
Name	Title	Phone Number	Email Address
Nick Kirkling	EHS / QC	812.234.1585	nkirkling@phoenixcolor.com

INSPECTION AND COMPLAINT HISTORY (PREVIOUS 5 YEARS)				
Date	Inspection/Complaint Type	Result	Comments	
None	COMMITMENT / CMS / COMPLAINT / OTHER	SELECT RESULT		

COMPLIANCE HISTORY (PREVIOUS 5 YEARS)				
Informal Enforcement Actions				
Date Issued	Action Taken	Describe Violation(s)		
N/A	SELECT ACTION TAKEN	TAKEN		
Formal Enforcement Actions				
Case Number	Enforcement Type	Civil Penalty	Describe Violation(s)	
N/A	SELECT ENFORCEMENT TYPE	\$		
Other Relevant Actions				
Action Taken	Comments			
N/A				

Phoenix Color (Plant ID: 167-00136) Inspection Report Page 3 of 5

PERMIT SECTION D.1					
Emission Units and Control Devices:					
One (1) parts washer (cold cleaner degreaser), identified as PW1, installed in 2015.					
Pollutants with Emission Limi	ts or Applic	able Standards:			
□ SO <sub>2</sub> □ NO <sub>X</sub> □ CO	⊠ VOC □	PM □ PM <sub>10</sub> □ PM <sub>2.5</sub> □ HAPS	3		
Applicable Rules:					
Cold Cleaner Degreaser	Control Equ	ipment and Operating Requireme	nts [326 IAC 8-3-2]		
Requirement:			Applicable	Violation Noted	
Emission Limitations and	Standards			$\square$ Yes $\boxtimes$ No	
Preventive Maintenance I	Plan			☐ Yes ☒ No	
Compliance Determinatio	n Requirem	nents	☐ Yes ⊠ No	☐ Yes ☒ No	
Testing Requirements			☐ Yes ⊠ No	☐ Yes ☒ No	
Compliance Monitoring R	equirement	S	☐ Yes ⊠ No	☐ Yes ⋈ No	
Recordkeeping Requirem	ents			☐ Yes ⊠ No	
Types of Records Re	viewed: inv	oice, SDS, waste disposal			
Reporting Requirements	Reporting Requirements □ Yes ☒ No □ Yes ☒ No				
	Observations and Comments:				
	ne past mor mm Hg.	ility. The parts washer was not in hth. The supplier comes every 6 w peration.			
Emission Unit or Control De	vice	Parameter	Permitted Value/Range	Observed	
N/A					
Permit Section Compliance S					
		ermined for this permit section at the	•		
Condition/Citation		nined for this permit section at the	time of the inspection:		
Condition/Citation	Comment	5			

Phoenix Color (Plant ID: 167-00136) Inspection Report Page 4 of 5

ADDITIONAL SOURCE COMPLIANCE REVIEW:				
The following reports are required and were reviewed:				
☐ Annual Compliance Certification(s) ☐ Deviation & Compliance Monitoring Report(s)				
The reports are consistent w	ith inspection observations.	⊠ Yes □ No □ N/A		
The permit accurately repres	ents emission units observed on site.	⊠ Yes □ No □ N/A		
Compliance assistance was	provided during the inspection.	⊠ Yes □ No □ N/A		
The source is required to ha	ve a Risk Management Plan [40 CFR 68].	□ Yes ⊠ No		
If yes, the source has a	olan.	□ Yes □ No ⊠ N/A		
If yes, the employees ha	ve been trained.	□ Yes □ No ⋈ N/A		
Additional Information and C	omments:			
The Annual Notification	n was not submitted by March 1, 2019.			
Additional Source Complian	ce Review Status:			
	served or determined at the time of the inspensions were determined at the time of the inspect			
Condition/Citation	·			
B.5	Failure to submit annual notification by March 1, 2019 for CY18			
INSPECTION FINDINGS				
	red or determined at the time of the inspection			
☐ The following violations were determined at the time of the inspection:				
Condition/Citation Description of Violation(s)				
D.5 Failure to submit annual notification by March 1, 2019 for CY18				
RECOMMENDED ACTION   Issue inspection summary letter.				
EXIT INTERVIEW  I explained my findings, recommendations, and conclusions with Mr. Kirkling prior exiting the facility.				
ATTACHMENTS				

Phoenix Color (Plant ID: 167-00136) Inspection Report Page 5 of 5

SUPPORTING DOCUMENTATION				
Photo No.				
Course Name:	SOURCE NAME			
Source Name:	SOURCE NAME			
Photographer:	STAFF NAME, IDEM, Office of Air Quality			
Date and Time:	DATE AND TIME			
Others Present:	NAME, COMPANY			
Description:	DETAILED DESCRIPTION OF PHOTO			