



INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

We Protect Hoosiers and Our Environment.

100 N. Senate Avenue • Indianapolis, IN 46204
(800) 451-6027 • (317) 232-8603 • www.idem.IN.gov

Eric J. Holcomb
Governor

Brian C. Rockensuess
Commissioner

June 20, 2022

VIA ELECTRONIC MAIL

Roland Otte
Riverview Energy Corporation
1614 O Union Valley Rd Ste 162
West Milford, NJ 07457
Ronald.otte@riverviewenergy.com

Re: Inspection Summary Letter
Riverview Energy Corporation
Source ID 147-00065
Dale, Spencer County

Dear Roland Otte:

On June 10, 2022, representatives of the Indiana Department of Environmental Management (IDEM), Office of Air Quality (OAQ), conducted an inspection of Riverview Energy Corporation, located at 4704 East County Road 2000 North in Dale, Indiana. This inspection was conducted pursuant to IC 13-14-2-2. For your information, and in accordance with IC 13-14-5, a summary of the inspection is provided below:

Inspection Type: Other
Inspection Results: No violations were observed

Please direct any questions to me at 812-380-2307 or by email at ncarr@idem.in.gov.

Sincerely,

Nicholas Carr, Director
Southwest Regional Office
Office of Air Quality

ACES ID: 271384

ENCLOSURE

cc: Daniel Roos and Michele Bramlett, Compliance and Enforcement Branch, Office of Air Quality
Gregory Merle, Riverview Energy Corporation, 6671 W Indiantown Rd Ste 50 #240, Jupiter, FL 33458

**INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT
OFFICE OF AIR QUALITY
FIELD INSPECTION REPORT**



SOURCE INFORMATION	
SOURCE NAME	Riverview Energy Corporation
SOURCE LOCATION	4704 East County Road 2000 North, Dale, Indiana Spencer County
MAILING ADDRESS	1614 O Union Valley Rd Ste 162, West Milford, NJ 07457
PLANT ID	147-00065
<u>PERMIT INFORMATION</u>	Permit Type: TVOP Permit Number: 39554 Permit Expiration Date: 6/11/2024 VFC Document No.(hyperlink): 82790509
ATTAINMENT STATUS	<input checked="" type="checkbox"/> Attainment for all criteria pollutants <input type="checkbox"/> Nonattainment for <input type="checkbox"/> SO ₂ <input type="checkbox"/> CO <input type="checkbox"/> O ₃ <input type="checkbox"/> NO ₂ <input type="checkbox"/> Pb <input type="checkbox"/> PM ₁₀ <input type="checkbox"/> PM _{2.5}
SOURCE STATUS	<input checked="" type="checkbox"/> PSD Major (326 IAC 2-2) <input checked="" type="checkbox"/> Major Source of HAPs <input type="checkbox"/> Emission Offset (326 IAC 2-3) <input type="checkbox"/> Area Source of HAPs <input type="checkbox"/> Acid Rain (326 IAC 21)
<u>SOURCE DESCRIPTION</u>	A stationary direct coal hydrogenation facility.

INSPECTION INFORMATION			
INSPECTED BY	Daniel Roos and Michele Bramlett		
INSPECTION DATE AND TIME	June 10, 2022	TIME IN: 9:15am and 1:15pm	TIME OUT: 9:30am and 1:30pm
REPORTED BY	Daniel Roos and Michele Bramlett	REPORT DATE: 6/14/2022	
<u>COMPLIANCE PERIOD REVIEWED</u>	6/10/2022 to 6/10/2022		
<u>INSPECTION NOTIFICATION</u>	<input checked="" type="checkbox"/> Unannounced <input type="checkbox"/> Announced:		
INSPECTION OBJECTIVE(S)	<input type="checkbox"/> Complaint <input checked="" type="checkbox"/> Surveillance <input type="checkbox"/> Other:		
ACES TRACKING NUMBER(S)	Inspection: 271384	Complaint:	Violation/Warning:
RM TRACKING NUMBER(S)	Complaint:		
<u>INSPECTION BACKGROUND</u>			

SOURCE PERSONNEL INTERVIEWED			
Name	Title	Phone Number	Email Address
Scott Maddox	Operations Manager	812-544-2156	SMADDOX@MIC-IN.NET
David Maddox	Owner	812-686-9430	DMADDOX@MIC-IN.NET

INSPECTION AND COMPLAINT HISTORY (PREVIOUS 5 YEARS)			
Date	Inspection/Complaint Type	Result	Comments

COMPLIANCE HISTORY (PREVIOUS 5 YEARS)			
Informal Enforcement Actions			
<i>Date Issued</i>	<i>Action Taken</i>	<i>Describe Violation(s)</i>	
Formal Enforcement Actions			
<i>Case Number</i>	<i>Enforcement Type</i>	<i>Civil Penalty</i>	<i>Describe Violation(s)</i>
		\$	
Other Relevant Actions			
<i>Action Taken</i>	<i>Comments</i>		


INSPECTION OBSERVATIONS AND COMMENTS
The following construction activities were observed at the time of the inspection. The nearby ground had been graded in preparation for the project and to control sediment runoff, an access road was being graded, a barrier fence had been completed around the construction site, and a concrete foundation pad for a building had been poured.

INSPECTION FINDINGS	
<input checked="" type="checkbox"/> No violations were observed or determined at the time of the inspection. <input type="checkbox"/> The following violations were determined at the time of the inspection:	
RECOMMENDED ACTION	Issue inspection summary letter.
EXIT INTERVIEW	I explained my findings, recommendations, and conclusions with Mr. Maddox prior to exiting the facility.

ATTACHMENTS
•

SUPPORTING DOCUMENTATION

Photo No. 1



Source Name:	Riverview Energy Corporation
Photographer:	Daniel Roos, IDEM, Office of Air Quality

Date and Time:	June 10, 2022, 1:20pm
Others Present:	David and Scott Maddox, MIC
Description:	Contractors' business card

Photo No. 2



Source Name:	Riverview Energy Corporation
Photographer:	Daniel Roos, IDEM, Office of Air Quality
Date and Time:	June 10, 2022, 1:20pm
Others Present:	David and Scott Maddox, MIC
Description:	Contractor's business card

Photo No. 3



Source Name:	Riverview Energy Corporation
Photographer:	Daniel Roos, IDEM, Office of Air Quality
Date and Time:	June 10, 2022, 1:20pm
Others Present:	David and Scott Maddox, MIC
Description:	Poured concrete pad

Photo No. 4



Source Name:	Riverview Energy Corporation
Photographer:	Daniel Roos, IDEM, Office of Air Quality
Date and Time:	June 10, 2022, 1:20pm
Others Present:	David and Scott Maddox, MIC

Description:	View of perimeter fencing, grading, and concrete pad
--------------	--

Photo No. 5




Source Name:	Riverview Energy Corporation
Photographer:	Daniel Roos, IDEM, Office of Air Quality
Date and Time:	June 10, 2022, 1:20pm
Others Present:	David and Scott Maddox, MIC
Description:	View of access road being graded and perimeter fencing

Photo No. 6



Source Name:	Riverview Energy Corporation
Photographer:	Daniel Roos, IDEM, Office of Air Quality
Date and Time:	June 10, 2022, 1:20pm
Others Present:	David and Scott Maddox, MIC
Description:	View of perimeter fencing, grading and concrete pad.

Photo No. 7



Source Name:	Riverview Energy Corporation
Photographer:	M. Bramlett & T. Haug, IDEM, Office of Air Quality
Date and Time:	June 10, 2022, 9:30 AM
Others Present:	N/A
Description:	Building permit posted

Photo No. 8



Source Name:	Riverview Energy Corporation
Photographer:	M.Bramlett & T. Haug, IDEM, Office of Air Quality
Date and Time:	June 10, 2022, 9:30 AM
Others Present:	N/A
Description:	Permit posted

Photo No. 9



Source Name:	Riverview Energy Corporation
Photographer:	M.Bramlett & T. Haug, IDEM, Office of Air Quality
Date and Time:	June 10, 2022, 9:30 AM
Others Present:	N/A
Description:	Form for pad

Photo No. 10



Source Name:	Riverview Energy Corporation
Photographer:	M. Bramlett & T. Haug, IDEM, Office of Air Quality
Date and Time:	June 10, 2022, 9:30 AM
Others Present:	N/A
Description:	Gravel drive